





report date: 2024-03-28

General information

Make	PEUGEOT
Model	307 SW SPORT
Colour	Grey
Year of manufacture	-
Top speed	120 mph
0 - 60 mph	11.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	240 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	46.3 mpg
Consumption extra urban	64.2 mpg
Consumption combined	56.5 mpg



CarCheck.co.uk page 1/13



Internet history

Entry 1

Date 2021-07-13

Pictures 7

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT #16		2020-12-01 10:18
MOT test r	number	350489152283
Result		✓ Passed
Next expir	y date	2021-12-27
Advice	Exhaust heat shield loose over rear box	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #15		2019-12-04 10:14
MOT test	number	892921256826
Result		✓ Passed
Advice	Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))	

MOT #14	2018-11-29 11:17
MOT test number	124044724268
Result	✓ Passed
Advice Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))	

MOT #13	2017-12-08 09:20
MOT test number	634050653046
Result	✓ Passed

CarCheck.co.uk page 3/13



KU57AGO

report date: 2024-03-28

MOT #12 2017-12-07 10:34 246941441854 **MOT** test number Result × Failed Fail Offside Front Track rod end ball joint has excessive play (2.2.B.1f) Fail Nearside Rear coil spring broken (2.4.C.1a) **Advice** Nearside Front track rod end has slight play in ball joint Fail Offside Rear coil spring broken (2.4.C.1a) **Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)

MOT #11

MOT test number

401235150207

Result

Advice Offside Rear tyre worn close to legal requirements

Advice Front brake pads worn low

MOT #10

MOT test number

Result

Advice Slight play osf track rod end

Advice Osf track rod end dust cover split but still prevents ingress of dirt

MOT #9

MOT test number

607614754352

Result

Notice Slight engine oil leak

2014-12-20 10:03

607614754352

CarCheck.co.uk page 4/13



MOT #8 2013-12-23 16:35

MOT test number 387387153326

Result
✓ Passed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #7 2013-12-21 11:02

MOT test number 295535353392

Result X Failed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Fail Offside Stop lamp not working (1.2.1b)

Fail Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Fail Offside Track rod end ball joint has excessive play (2.2.B.1f)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Fail Nearside Rear position lamp(s) not working (1.1.A.3b)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Fail Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Notice Eml light on

Fail

Nearside Track rod end ball joint has excessive play (2.2.B.1f)

Advice Front Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 5/13



KU57AGO

report date: 2024-03-28

MOT #6

MOT test number

877692752357

Result

Advice Nearside Front Ball joint has slight play (2.2.B.1f)

Advice Offside Front Ball joint has slight play (2.2.B.1f)

MOT #5 2012-12-17 10:31 **MOT** test number 759232752389 Result X Failed Fail Rear Brake pad(s) less than 1.5 mm thick (3.5.1g) Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Advice Offside Front Ball joint has slight play (2.2.B.1f) **Advice** Nearside Rear Rear position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)**Advice** Nearside Front Ball joint has slight play (2.2.B.1f)

MOT #4

MOT test number

709372561310

Result

Notice Slight play n/side steering arm

MOT test number
615892861327

Result

Fail Offside Headlamp not working on dipped beam (1.7.5a)

Notice Slight play n/side steering arm

Fail Offside Registration plate lamp not working (1.1.C.1d)

Notice N/s/r lower and o/s/r upper side lamps inop


CarCheck.co.uk page 6/13



KU57AGO

report date: 2024-03-28





CarCheck.co.uk page 7/13



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

e when mistery		
For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full respectively.		EOT

,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		

	More info >	
Plate changes		
See in this check if this PEUGEOT had different number plates.		
Number of plates		
Current registration	UK ZIS	
Plate since		
Current registration	NK SIE	
Plate since		
	More info >	

CarCheck.co.uk page 10/13



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info


More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2007-11-28
Last registration	2020-12-01
Complete history	See info



Registration #1	2007-11-28	24 mi
Registration #2	2010-11-04	60.821 mi
Registration #3	2011-12-28	71.840 mi
Registration #4	2011-12-28	71.840 mi
Registration #5	2012-12-17	79.717 mi
Registration #6	2012-12-17	79.718 mi
Registration #7	2013-12-21	85.694 mi
Registration #8	2013-12-23	85.695 mi
Registration #9	2014-12-20	93.734 mi
Registration #10		10.777 au
Registration #11		11.777 mi
_		11.777 es
Registration #11		11.777 es 11.777 es 11.777 es
Registration #11 Registration #12		71.777 es 71.777 es 71.777 es
Registration #11 Registration #12 Registration #13		77.777-66 77.777-66 77.777-66 77.777-66
Registration #11 Registration #12 Registration #13 Registration #14		11.777 es 11.777 es 11.777 es 11.777 es

More info >

CarCheck.co.uk page 12/13



Car features

S0225	Air conditioni
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1920 mm
Height	1555 mm
Length	4156 mm
Wheel base	2540 mm
Kerb weight	1350 kg
Max. allowed weight	1758 kg

Additional information

Fuel tank capacity	50 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 page	e 13/13

Number of axles 2

Engine number JB853018520