





General information

Make	HYUNDAI
Model	IX35 GDI SE
Colour	Black
Year of manufacture	2015
Top speed	111 mph
0 - 60 mph	11.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	133 BHP
Max. torque	165 Nm at 4.850 rpm
Engine capacity	1.591 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.5 mpg
Consumption extra urban	47.1 mpg
Consumption combined	41.5 mpg
CO2 emission	158 g/km
CO2 label	G







Internet history

Entry 1

Date Pictures 2021-10-27

19

Listing price

View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-12-07
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	16
Total items failed	8

MOT #12		2023-12-08 16:28
MOT test	number	238640051416
Result		🗸 Passed
Next expi	ry date	2024-12-07
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge worn inside edge (5.2.3	(e))
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))	

MOT #11 2023-12-08 16:28 MOT test number 275468571047 Result X Failed Pass with rectification Rear Registration plate lamp inoperative in the case of a single lamp or all lamps both lights (4.7.1 (b) (ii)) Advice Offside Rear Direction indicator slightly discoloured (4.4.3 (a)) Advice Nearside Rear Direction indicator slightly discoloured (4.4.3 (a)) Advice Offside Front Tyre worn close to legal limit/worn on edge worn inside edge (5.2.3 (e))

MOT #10	2022-11-24 16:29
MOT test number	112599286852
Result	✓ Passed





MOT #9	2021-11-08 14:32
MOT test number	530635556097
Result	✓ Passed
MOT #8	2021-11-05 09:18
MOT test number	967744959868
Result	🗙 Failed
Fail Nearside Windscreen washer not working (3.5 (a))	
Fail Offside Windscreen washer provides insufficient washer liquid (3.5 (a))	
MOT #7	2021-06-09 08:11
MOT test number	191518528622

MOT test number	191518528622
Result	✓ Passed
Advice Offside Rear Tyre slightly damaged/cracking or perishing badly perished 215-70)-16 (5.2.3 (d) (ii))
Advice Offside Rear Nail in tyre	

MOT #6	2021-06-09 08:11
MOT test number	359716367511
Result	× Failed
Pass with rectification	Offside Headlamp aim too high (4.1.2 (a))
Advice Offside Rear Nai	l in tyre
Pass with rectification	Nearside Headlamp aim too high (4.1.2 (a))
Advice Offside Rear Tyre slightly damaged/cracking or perishing badly perished 215-70-16 (5.2.3 (d) (ii))	





MOT #5		2020-06-16 08:49
MOT test	number	690798207668
Result		✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #4	2019-05-15 11:10
MOT test number	716012616752
Result	✓ Passed
Advice Both front tyres getting low on tread	

МОТ #3	2019-05-13 10:08
MOT test number	518810549380
Result	🗙 Failed
Fail Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
Fail Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.	1 (b) (ii))
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Fail Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a	a) (ii))
Minor Windscreen wiper blade defective both (3.4 (b) (i))	

MOT #2	2018-05-21 11:10
MOT test number	209400267897
Result	✓ Passed

MOT #1	2017-12-14 11:24
MOT test number	465951352950
Result	✓ Passed



Tax & MOT check

✓ Taxed	√ MOT
Tax due: 1 April 2025	Expires: 7 December 2024
Tax status	Valid until 1 April
Days left	337
MOT expiry date	7 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-





Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEIDO
Category	Lamp
Туре	
Damage 2	VAMPL
Date	······································
Category	AMP
Туре	

Extra HYUNDAI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Rinks sizes	





Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2015-01-30
Last registration	2023-12-08
Complete history	See info



Registration #1	2015-01-30	18 mi
Registration #2	2017-12-14	24.201 mi
Registration #3	2018-05-21	25.787 mi
Registration #4	2019-05-13	46.018 mi
Registration #5	2019-05-15	46.018 mi
Registration #6	2020-06-16	61.926 mi
Registration #7	2021-06-09	71.983 mi
Registration #8		11.777 est
Registration #8 Registration #9		11.517 est 11.517 est
		01.000 est 01.000 est 01.000 est
Registration #9		01.000 est 01.000 est 01.000 est 01.000 est
Registration #9 Registration #10		0.000 es
Registration #9 Registration #10 Registration #11		0.000 es 0.000 es 0.000 es 0.000 es 0.000 es 0.000 es





Car features

S0225	Air conditioning
\$0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	90%
Children	88%
Pedestrian	54%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight	
Width	1820 mm
Height	1665 mm
Length	4410 mm
Wheel base	2640 mm
Kerb weight	1427 kg
Max. allowed weight	1830 kg
Additional information	
Fuel tank capacity	58
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/12

Number of axles	2
Engine number	G4FDFZ963022