





report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	GOLF SE TSI
Colour	Red
Year of manufacture	2009
Top speed	120 mph
0 - 60 mph	10.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	122 BHP
Max. torque	200 Nm at 1.500 rpm
Engine capacity	1.390 сс
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	51.4 mpg
Consumption combined	42.8 mpg
CO2 emission	152 g/km
CO2 label	G



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-06-14

Pictures 46

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-12-11
MOT pass rate	93 %
MOT passed	13
Failed MOT tests	1
Total advice items	15
Total items failed	0

MOT #14	2023-12-12 15:43
MOT test number	548064233984
Result	✓ Passed
Next expiry date	2024-12-11

MOT #13	2023-08-31 11:56
MOT test number	276328614135
Result	✓ Passed

MOT #12	2023-08-21 07:47
MOT test number	855770732220
Result	X Failed

Advice Offside Front Tyre worn close to legal limit/worn on edge worn inner edge (5.2.3 (e))

MAJOR Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

DANGEROUS Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

MOT #11	2022-08-23 14:47
MOT test number	508315762487
Result	✓ Passed

CarCheck.co.uk page 3/12



FL59VCP

report date: 2024-03-29

MOT #10 2021-06-07 16:50 MOT test number 471074824720

Result ✓ Passed

MOT #9 2020-09-08 14:14

MOT test number 890986389363

Advice Front Brake disc worn, but not excessively inner faces (1.1.14 (a) (i))

Minor Nearside Rear Direction indicator with a multiple light source up to 1/2 not functioning (4.4.1 (a) (i))

MOT #8 2019-09-09 13:40

MOT test number 903803857599

Result \(\sqrt{Passed}\)

Advice Offside Front Tyre worn close to legal limit/worn on edge worn on edge (5.2.3 (e))

Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #7 2018-09-10 13:05

MOT test number 136559949371

CarCheck.co.uk page 4/12



MOT #6 2017-08-29 13:30 MOT test number 347354231723

Advice Offside Rear Nail in tyre

Advice Offside Rear Shock absorber has a light misting of oil (2.7.3)

Advice Nearside Rear Nail in tyre

Advice Nearside Rear Shock absorber has a light misting of oil (2.7.3)

MOT #5 2016-09-06 10:36

MOT test number 549596157955

Result
✓ Passed

MOT #4 2015-10-12 14:49

MOT test number 854050111555

Result
✓ Passed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #3 2014-10-17 13:11

MOT test number 115310594238

Result

Passed

MOT #2 2013-10-23 14:17

MOT test number 858306293246

Result ✓ Passed

MOT #1 2012-11-02 12:56

MOT test number 585307802385

Result
✓ Passed

CarCheck.co.uk page 5/12





Tax & MOT check





Expires: 11 December 2024

Tax status	Valid until 1 September
Days left	124
MOT expiry date	11 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 6/12




Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	

Damage 2	
Date	
Category	



Extra VOLKSWAGEN salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Downere.	

Plate changes	More info >
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	NE N
Plate since	
Current registration	NE UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 10/12



FL59VCP

report date: 2024-03-29

Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-11-14
Last registration	2023-12-12
Complete history	See info



Registration #1	2009-11-14	26 mi
Registration #2	2012-11-02	15.117 mi
Registration #3	2013-10-23	22.997 mi
Registration #4	2014-10-17	27.012 mi
Registration #5	2015-10-12	33.930 mi
Registration #6	2016-09-06	39.363 mi
Registration #7	2017-08-29	46.477 mi
Registration #8	2018-09-10	51.384 mi
Registration #9		11.777 es
Registration #10		11.177 es
Registration #11		11.177 mi
Registration #12		11.177 es
Registration #13		11.177 mi
Registration #14		11.777 es
Registration #15		11.777 es

7070.70.70

More info >

77.777 86

CarCheck.co.uk page 11/12



Car features

50225	Air conditionir
50295	
60482	
60501	
60566	
0567	
60569	

Safety ratings

NCAP rating	****
Adult	97%
Children	84%
Pedestrian	61%
Safety systems	71%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1759 mm
Height	1580 mm
Length	4206 mm
Wheel base	2578 mm
Kerb weight	1262 kg
Max. allowed weight	1970 kg

Additional information

Fuel tank capacity	55 I
Fuel delivery	Multi-Point Injection
Number of doors	5
CarChack co.uk	nago 12/12

CarCheck.co.uk page 12/12

Number of seats	5
Number of axles	2
Engine number	CAX 355769