



report date: 2024-03-29

General information

Make	VOLVO
Model	V50 D S
Colour	Grey
Year of manufacture	2010
Top speed	127 mph
0 - 60 mph	9.1 seconds
Gearbox	6 speed Semi-Automatic

Engine & fuel consumption

Power	136 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.1 mpg
CO2 emission	153 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-08-13
Pictures	1
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-05
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	18
Total items failed	7

MOT #15 2023-10-06 13:25

MOT test number 739762896164

Result ✓ Passed

Next expiry date 2024-10-05

- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Minor** Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #14 2022-09-07 09:26

MOT test number 551234459457

Result ✓ Passed

- Advice** Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #13** 2022-08-31 10:14**MOT test number** 727010891252**Result** ✗ Failed**Advice** Nearside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**MOT #12** 2021-08-20 13:37**MOT test number** 436276535366**Result** ✓ Passed**MOT #11** 2020-12-09 16:08**MOT test number** 244943383835**Result** ✓ Passed**MOT #10** 2019-07-30 14:13**MOT test number** 284127084295**Result** ✓ Passed**MOT #9** 2019-07-30 10:05**MOT test number** 838526617187**Result** ✗ Failed**Fail** Offside Rear Direction indicator adversely affected by the operation of another lamp Affects All Other Lamps (4.4.3 (b))**Minor** Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Fail** Nearside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**MOT #8** 2018-07-04 13:48**MOT test number** 799593875284**Result** ✓ Passed**MOT #7** 2018-07-04 09:14**MOT test number** 976411768713**Result** ✗ Failed**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**MOT #6** 2017-07-04 13:21**MOT test number** 720763672729**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2017-07-03 08:30**MOT test number** 219321366249**Result** ✗ Failed**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Advice** Nearside Front Tyre worn close to the legal limit Bald Inner Edge (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Advice** Offside Rear Upper Side Light Not Working**MOT #4** 2016-07-04 08:27**MOT test number** 197903240489**Result** ✓ Passed



MOT #3	2015-07-06 11:37
MOT test number	787077185130
Result	✓ Passed
MOT #2	2014-07-04 12:19
MOT test number	889965584176
Result	✓ Passed
MOT #1	2013-06-17 14:41
MOT test number	936518163170
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
5 October 2024

Tax status	Valid until 1 September
Days left	124
MOT expiry date	5 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	YY10FZE
Plate since	2019-09-29
Current registration	YY10FZE
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-07-06
Last registration	2023-10-06
Complete history	See info



Registration #1	2010-07-06	23 mi
Registration #2	2013-06-17	33.041 mi
Registration #3	2014-07-04	42.040 mi
Registration #4	2015-07-06	54.600 mi
Registration #5	2016-07-04	62.261 mi
Registration #6	2017-07-03	71.003 mi
Registration #7	2017-07-04	71.056 mi
Registration #8	2018-07-04	80.115 mi
Registration #9	2018-07-04	80.115 mi
Registration #10	2019-06-20	89.277 mi
Registration #11	2019-06-20	89.277 mi
Registration #12	2019-06-20	89.277 mi
Registration #13	2019-06-20	89.277 mi
Registration #14	2019-06-20	89.277 mi
Registration #15	2019-06-20	89.277 mi
Registration #16	2019-06-20	89.277 mi
Registration #17	2019-06-20	89.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1454 mm
Length	4476 mm
Wheel base	2640 mm
Kerb weight	1446 kg
Max. allowed weight	1940 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Engine number	727050
---------------	--------