





report date: 2024-03-28

General information

Make	FORD
Model	KA ZETEC
Colour	Silver
Year of manufacture	2010
Top speed	99 mph
0 - 60 mph	13.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	44.8 mpg
Consumption extra urban	64.2 mpg
Consumption combined	55.4 mpg
CO2 emission	119 g/km
CO2 label	С



CarCheck.co.uk page 1/13



report date: 2024-03-28

Internet history

Entry 1

Date	2021-01-30
Pictures	1
Listing price	<u>View report</u>



source: autoonline.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

	_				
11/1/	TC	n		$\overline{}$	r\/
IVIL	, ,		51	LU.	ıv
					. ,

MOT expiry date	2024-09-01
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	22
Total items failed	1

MOT #15	2023-09-02 10:27
MOT test number	459161663597
Result	✓ Passed
Next expiry date	2024-09-01

MOT #14	2023-08-26 11:24
MOT test number	529611521895
Result	X Failed
MAJOR Engine MIL inoperative or indi	cates a malfunction (8.2.1.2 (h))

MOT #13		2022-01-26 15:45
MOT test	number	209475823750
Result		✓ Passed
Advice	Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Advice	Steering rack has slight free play detected at steering wheel (2.3 (a) (i))	

MOT #12	2021-02-05 15:00
MOT test number	183366466652
Result	✓ Passed

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #11		2021-02-04 11:44
MOT test	number	234944131450
Result		× Failed
MAJOR	Offside Parking brake inoperative on one side (1.4.1 (a))	
MAJOR	Front Windscreen washer provides insufficient washer liquid (3.5 (a))	
MAJOR	Offside Stop lamp(s) not working (4.3.1 (a) (ii))	
Advice	Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))	
MAJOR	Nearside Rear Service brake excessively binding (1.2.1 (f))	
MAJOR	Nearside Front Position lamp not working (4.2.1 (a) (ii))	
MAJOR	Parking brake efficiency below requirements (1.4.2 (a) (i))	
MAJOR	Nearside Stop lamp(s) not working (4.3.1 (a) (ii))	
MAJOR	Offside Rear Shock absorbers has an excessively worn bush (5.3.2 (c))	
Advice	Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))	

MOT #10	2020-01-03 16:36
MOT test number	259008245917
Result	✓ Passed

MOT #9	2020-01-03 09:32
MOT test number	483916283769
Result	× Failed
DANGEROUS Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
Minor Brake hydraulic reservoir fluid level below minimum level (1.1.10 (d) (i))	
MAJOR Parking brake efficiency below requirements (1.4.2 (a) (i))	

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT #8	2018-12-28 12:55
MOT test number	611956641326
Result	✓ Passed
Advice Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #7		2018-01-08 14:17
MOT test	number	865451349614
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Handbrake cable casing cracking	
Advice	Exhaust has a minor leak of exhaust gases back box (7.1.2)	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #6	2017-01-21 12:16
MOT test number	549070005190
Result	✓ Passed
Advice Exhaust back box corroded on outer skin but not blowing	

MOT #5	2016-01-09 12:13
MOT test number	587085353008
Result	✓ Passed
MOT #4	2015-01-27 09:25
MOT test number	598227225028
Result	✓ Passed
MOT #3	2014-01-20 11:02
MOT test number	896870224013
Result	✓ Passed

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #2	2013-01-21 13:06
MOT test number	147511523436
Result	✓ Passed
MOT #1	2013-01-19 14:35
MOT test number	975939313065
Result	× Failed
Fail Front Brake pad(s) less than 1.5 mm thick (3.5.1g)	

CarCheck.co.uk page 6/13



report date: 2024-03-28

Tax & MOT check





Expires: 1 September 2024

Tax status	Valid until 1 September
Days left	126
MOT expiry date	1 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



YB59HZU report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

Owner history

Owner mistory	
For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	
Current registration	UK NE
Plate since	
Current registration	NK NE
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-28

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-01-29
Last registration	2023-09-02
Complete history	See info



Registration #1	2010-01-29	20 mi
Registration #2	2013-01-19	27.196 mi
Registration #3	2013-01-21	27.196 mi
Registration #4	2014-01-20	34.392 mi
Registration #5	2015-01-27	40.305 mi
Registration #6	2016-01-09	45.374 mi
Registration #7	2017-01-21	51.624 mi
Registration #8	2018-01-08	57.331 mi
Registration #9	2018-12-28	66.082 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 au
Registration #13		11.777 es
Registration #14		11.777 au
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		

 $\quad \text{More info} \quad > \quad$

CarCheck.co.uk page 12/13



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1702 mm
Height	1505 mm
Length	3620 mm
Wheel base	2300 mm
Kerb weight	940 kg
Max. allowed weight	1320 kg

Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 13/1

Number of axles 2
Engine number 5775203