



TOYOTA




report date: 2024-03-29

General information

Make	TOYOTA
Model	COROLLA VERSO D-4D T SPIRIT
Colour	Blue
Year of manufacture	2005
Top speed	112 mph
0 - 60 mph	12.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	279 Nm at 2.000 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	53.3 mpg
Consumption combined	45.6 mpg
CO2 emission	165 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-08-28
Pictures	0
Listing price	View report

source: cargurus.co.uk








MOT history

MOT expiry date	2024-08-02
MOT pass rate	73 %
MOT passed	16
Failed MOT tests	6
Total advice items	17
Total items failed	9

MOT #22	2023-08-03 14:46
MOT test number	625311844509
Result	✓ Passed
Next expiry date	2024-08-02
Minor	Offside Headlamp lens slightly defective (4.1.1 (b) (i))
Advice	Towball/hitch not fitted at time of test
Advice	Child Seat fitted not allowing full inspection of adult belt

MOT #21	2023-08-03 10:56
MOT test number	876184895738
Result	✗ Failed
Fail	Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))
Fail	Nearside Headlamp aim too high (4.1.2 (a))
Advice	Eml on
Advice	Child Seat fitted not allowing full inspection of adult belt
Fail	Electronic stability control warning lamp indicates a fault (7.12 (e))
Minor	Offside Headlamp lens slightly defective (4.1.1 (b) (i))
Advice	Emissions limit 1.2 m-1

**MOT #20** 2022-07-21 12:46**MOT test number** 401310186224**Result**  Passed**MOT #19** 2022-07-20 12:53**MOT test number** 629970254480**Result**  Failed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Service brake fluctuating, but not excessively (1.2.1 (e))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Nail in tyre**Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #18** 2021-08-03 13:05**MOT test number** 756142338980**Result**  Passed**MOT #17** 2020-07-15 14:26**MOT test number** 373492089999**Result**  Passed**MOT #16** 2019-07-03 10:52**MOT test number** 309569171377**Result**  Passed

**MOT #15** 2018-07-23 13:15**MOT test number** 324297117738**Result** ✓ Passed**MOT #14** 2017-07-19 10:57**MOT test number** 771201880631**Result** ✓ Passed**MOT #13** 2016-07-21 09:41**MOT test number** 662276947766**Result** ✓ Passed**MOT #12** 2015-07-23 12:45**MOT test number** 706194305261**Result** ✓ Passed**Advice** Offside front brake fluctuating, but not excessively (3.7.B.3)**Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)**MOT #11** 2014-07-14 09:53**MOT test number** 779195694111**Result** ✓ Passed**MOT #10** 2013-07-09 11:50**MOT test number** 528040993185**Result** ✓ Passed**MOT #9** 2013-07-09 11:50**MOT test number** 638020193112**Result** ✗ Failed**Pass with rectification** Rear fog lamp not working (1.3.2b)

**MOT #8** 2012-07-16 12:14**MOT test number** 776348792173**Result** ✓ Passed**MOT #7** 2012-07-16 10:12**MOT test number** 509158592192**Result** ✗ Failed**Fail** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)**MOT #6** 2011-07-18 11:47**MOT test number** 259779091461**Result** ✓ Passed**MOT #5** 2010-07-26 13:47**MOT test number** 883017200227**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2009-07-25 13:39**MOT test number** 683966009209**Result** ✓ Passed**MOT #3** 2009-07-25 13:39**MOT test number** 324386009496**Result** ✗ Failed**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)



MOT #2	2008-07-25 13:29
MOT test number	162767308217
Result	✓ Passed

MOT #1	2008-07-25 13:29
MOT test number	492657408269
Result	✗ Failed

Pass with rectification

 Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
2 August 2024

Tax status	Valid until 1 September
Days left	125
MOT expiry date	2 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history


Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	YL05HXX
Plate since	2024-03-29
Current registration	YL05HXX
Plate since	2024-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2005-07-29
Last registration	2023-08-03
Complete history	See info



Registration #1	2005-07-29	19 mi
Registration #2	2008-07-25	26.892 mi
Registration #3	2009-07-25	36.384 mi
Registration #4	2010-07-26	47.169 mi
Registration #5	2011-07-18	56.815 mi
Registration #6	2012-07-16	63.365 mi
Registration #7	2012-07-16	63.365 mi
Registration #8	2013-07-09	68.114 mi
Registration #9	2014-07-14	69.734 mi
Registration #10	2015-07-23	72.252 mi
Registration #11	2016-07-21	74.638 mi
Registration #12	2017-07-20	76.977 mi
Registration #13	2018-07-20	79.277 mi
Registration #14	2019-07-20	81.577 mi
Registration #15	2020-07-20	83.877 mi
Registration #16	2021-07-20	86.177 mi
Registration #17	2022-07-20	88.477 mi
Registration #18	2023-07-20	90.777 mi
Registration #19	2024-07-20	93.077 mi
Registration #20	2025-07-20	95.377 mi
Registration #21	2026-07-20	97.677 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1660 mm
Length	4360 mm
Wheel base	2750 mm
Kerb weight	1495 kg
Max. allowed weight	2140 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	1CD0440382