



report date: 2024-03-28

General information

Make	MAZDA
Model	3 SPORT
Colour	Silver
Year of manufacture	2009
Top speed	114 mph
0 - 60 mph	12.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	103 BHP
Max. torque	145 Nm at 4.000 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.0 mpg
Consumption extra urban	54.3 mpg
Consumption combined	44.8 mpg
CO2 emission	149 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-06-17
Pictures	34
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-02-25
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	50
Total items failed	11

MOT #18 2024-02-16 16:25

MOT test number 632580421616

Result ✓ Passed

Next expiry date 2025-02-25

Advice Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Minor Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

MOT #17 2023-02-14 10:30

MOT test number 887617295711

Result ✓ Passed

Advice Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Minor Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Advice Exhaust has a minor leak of exhaust gases Flexi worn (6.1.2 (a))

**MOT #16**

2023-02-14 10:30

MOT test number

73777776390

Result**✗ Failed**

Minor Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Pass with rectification Front Position lamp not working (4.2.1 (a) (ii))

Advice Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Advice Exhaust has a minor leak of exhaust gases Flexi worn (6.1.2 (a))

MOT #15

2022-02-22 13:55

MOT test number

923005980927

Result**✓ Passed****MOT #14**

2021-02-26 11:52

MOT test number

342567497409

Result**✓ Passed**

Advice Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Rear Valve stem slightly damaged (5.2.3 (j))

Advice Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #13**

2021-02-25 10:47

MOT test number

731131036623

Result**✗ Failed**

- Advice** Offside Rear Valve stem slightly damaged (5.2.3 (j))
- Fail** Central Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #12

2020-02-25 13:23

MOT test number

804397347850

Result**✓ Passed**

- Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Valve stem slightly damaged (5.2.3 (j))
- Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #11**

2020-02-24 11:39

MOT test number

466629862258

Result**✗ Failed**

- Advice** Offside Rear Valve stem slightly damaged (5.2.3 (j))
- Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #10

2019-02-20 11:14

MOT test number

820211245005

Result**✓ Passed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Valve stem slightly damaged (5.2.3 (j))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #9

2018-02-14 09:38

MOT test number

749906723412

Result**✓ Passed**

- Advice** Offside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
- Advice** Nearside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #8** 2017-02-10 12:41**MOT test number** 656576502527**Result** ✓ Passed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #7** 2017-02-10 12:41**MOT test number** 179011990364**Result** ✗ Failed**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #6** 2016-02-16 14:12**MOT test number** 844610154052**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Middle and rear sections of the exhaust heavily corroded**MOT #5** 2015-02-18 15:35**MOT test number** 387389645005**Result** ✓ Passed**Advice** Offside Rear Anti-roll bar linkage worn but not seriously weakened (2.4.G.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #4** 2015-02-18 12:42**MOT test number** 395769645095**Result** ✗ Failed**Fail** Offside rear parking brake recording little or no effort (3.7.B.6a)**Advice** Offside Rear Anti-roll bar linkage worn but not seriously weakened (2.4.G.1)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2014-02-24 09:32**MOT test number** 328115454052**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2013-02-26 13:18**MOT test number** 276597053079**Result** ✓ Passed**MOT #1** 2012-08-30 11:55**MOT test number** 989213142230**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
25 February 2025

Tax status	Valid until 1 July
Days left	63
MOT expiry date	25 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-




Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	SK59XPV
Plate since	2019-03-28
Current registration	SK59XPV
Plate since	2019-03-28

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2009-09-01
Last registration	2024-02-16
Complete history	See info



Registration #1	2009-09-01	9 mi
Registration #2	2012-08-30	30.643 mi
Registration #3	2013-02-26	34.894 mi
Registration #4	2014-02-24	44.912 mi
Registration #5	2015-02-18	56.513 mi
Registration #6	2015-02-18	56.513 mi
Registration #7	2016-02-16	66.814 mi
Registration #8	2017-02-10	76.091 mi
Registration #9	2017-02-10	76.091 mi
Registration #10	2018-02-14	82.476 mi
Registration #11	2019-02-10	92.476 mi
Registration #12	2019-02-10	92.476 mi
Registration #13	2019-02-10	92.476 mi
Registration #14	2019-02-10	92.476 mi
Registration #15	2019-02-10	92.476 mi
Registration #16	2019-02-10	92.476 mi
Registration #17	2019-02-10	92.476 mi
Registration #18	2019-02-10	92.476 mi
Registration #19	2019-02-10	92.476 mi
Registration #20	2019-02-10	92.476 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2002 mm
Height	1470 mm
Length	4490 mm
Wheel base	2640 mm
Kerb weight	1275 kg
Max. allowed weight	1770 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	Z6 819186