



General information

Make	FORD
Model	GALAXY GHIA TDCI
Colour	Grey
Year of manufacture	2007
Top speed	120 mph
0 - 60 mph	9.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	340 Nm at 1.750 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.4 mpg
Consumption extra urban	51.4 mpg
Consumption combined	43.5 mpg
CO2 emission	172 g/km
CO2 label	H






Internet history

Entry 2


Date	2021-06-22
Pictures	15
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 1

Date	2021-06-22
Pictures	15
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-06-01
MOT pass rate	65 %
MOT passed	13
Failed MOT tests	7
Total advice items	33
Total items failed	21

MOT #20	2023-06-02 15:24
MOT test number	946216568355
Result	✓ Passed
Next expiry date	2024-06-01

MOT #19	2023-06-02 15:24
MOT test number	803314741456
Result	✗ Failed
Pass with rectification	Windscreen wiper blade missing (3.4 (b) (ii))

MOT #18	2022-05-06 11:22
MOT test number	565609231641
Result	✓ Passed
Minor	Offside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
Advice	Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Minor	Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
Advice	Offside Front Steering linkage ball joint has slight play rack-end (2.1.3 (b) (i))

**MOT #17**

2022-05-04 14:31

MOT test number

124707235458

Result**✗ Failed****Fail** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Items removed from driver's view prior to test**Fail** Nearside Direction indicator not working On wing mirror (4.4.1 (a) (ii))**Advice** Rear Wiperblade Split**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))**Advice** Nearside Front Fog Light Inop**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MOT #16**

2021-04-26 08:46

MOT test number

268698818956

Result**✓ Passed****Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))



MOT #152019-10-21 14:26

MOT test number362611727142

Result✓ Passed

MinorOffside Obligatory mirror slightly damaged (3.3 (b) (i))

AdviceCentral Rear Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))

MinorNearside Obligatory mirror slightly damaged (3.3 (b) (i))

AdviceOffside Rear Nail in tyre

AdviceNearside Rear Lower Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #14** 2019-10-21 09:58**MOT test number** 615319026355**Result** ✗ Failed**Fail** Nearside Front Road wheel fixing missing (5.2.1 (a) (i))**Minor** Offside Obligatory mirror slightly damaged (3.3 (b) (i))**Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps All (4.7.1 (b) (ii))**Fail** Offside Rear Road wheel fixing missing (5.2.1 (a) (i))**Fail** Offside Rear Rear reflector defective or damaged by more than 50% of the reflecting surface (4.8.1 (a) (ii))**Advice** Offside Rear Nail in tyre**Fail** Nearside Side repeater not working on mirror (4.4.1 (a) (ii))**Advice** Nearside Rear Lower Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Minor** Nearside Obligatory mirror slightly damaged (3.3 (b) (i))**Fail** Nearside Rear Road wheel fixing missing (5.2.1 (a) (i))**Fail** Nearside Rear Rear reflector defective or damaged by more than 50% of the reflecting surface (4.8.1 (a) (ii))**Fail** Offside Front Road wheel fixing missing (5.2.1 (a) (i))**Advice** Central Rear Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))**Fail** Nearside Side repeater missing on mirror (4.4.1 (a) (ii))**MOT #13** 2018-07-07 12:49**MOT test number** 807192942848**Result** ✓ Passed**MOT #12** 2017-08-01 08:47**MOT test number** 259631745479**Result** ✓ Passed

**MOT #11** 2017-08-01 08:47**MOT test number** 282699794112**Result** ✗ Failed

Pass with rectification Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

Pass with rectification Offside Front position lamp(s) not working (1.1.A.3b)

Pass with rectification Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #10 2016-07-20 15:12**MOT test number** 418372634222**Result** ✓ Passed

Advice Air freshener removed from mirror - obscuring the view of the road

MOT #9 2016-07-20 14:20**MOT test number** 785654568729**Result** ✗ Failed

Fail Offside Front Tyre has ply or cords exposed (4.1.D.1b)

Advice Air freshener removed from mirror - obscuring the view of the road

MOT #8 2015-07-19 12:30**MOT test number** 458210905226**Result** ✓ Passed**MOT #7** 2014-06-12 10:50**MOT test number** 406023564178**Result** ✓ Passed

**MOT #6** 2013-06-24 15:02**MOT test number** 895295973195**Result** ✓ Passed**Notice** Tyre inflater kit missing from vehicle**MOT #5** 2013-06-24 09:11**MOT test number** 636055273160**Result** ✗ Failed**Advice** Offside Rear position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Tyre inflater kit missing from vehicle**MOT #4** 2012-07-07 10:26**MOT test number** 725419282123**Result** ✓ Passed**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Rear position lamp(s) damaged, but still visible from a reasonable distance (1.1.A.3d)**MOT #3** 2011-07-05 16:29**MOT test number** 435296181140**Result** ✓ Passed



MOT #2	2011-07-05 16:29
MOT test number	206156181123
Result	✗ Failed
Pass with rectification	Offside Stop lamp not working (1.2.1b)

MOT #1	2010-06-23 15:31
MOT test number	274164770189
Result	✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
1 June 2024

Tax status	Valid until 1 September
Days left	125
MOT expiry date	1 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-03-02
Last registration	2023-06-02
Complete history	See info



Registration #1	2007-03-02	9 mi
Registration #2	2010-06-23	32.191 mi
Registration #3	2011-07-05	39.139 mi
Registration #4	2012-07-07	49.126 mi
Registration #5	2013-06-24	58.328 mi
Registration #6	2013-06-24	58.328 mi
Registration #7	2014-06-12	65.014 mi
Registration #8	2015-07-19	66.412 mi
Registration #9	2016-07-20	67.738 mi
Registration #10	2016-07-20	67.738 mi
Registration #11	2017-08-01	68.934 mi
Registration #12	2018-08-01	70.130 mi
Registration #13	2019-08-01	71.326 mi
Registration #14	2020-08-01	72.522 mi
Registration #15	2021-08-01	73.718 mi
Registration #16	2022-08-01	74.914 mi
Registration #17	2023-06-02	76.110 mi
Registration #18	2023-06-02	76.110 mi
Registration #19	2023-06-02	76.110 mi
Registration #20	2023-06-02	76.110 mi
Registration #21	2023-06-02	76.110 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2154 mm
Height	1736 mm
Length	4820 mm
Wheel base	2850 mm
Kerb weight	1933 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Engine number	6G84817
---------------	---------