

Ford



General information

Make	FORD
Model	GALAXY ZETEC TDCI (125PS)
Colour	Silver
Year of manufacture	2007
Top speed	116 mph
Gearbox	6 speed Manual

Engine & fuel consumption

ower	125 BHP	0 < 101 A
lax. torque	285 Nm at 1.750 rpm	101 - 120 ^B _C
ngine capacity	1.753 cc	121 - 140 E
ylinders	4	
uel type	Diesel	166 - 185
onsumption city	35.3 mpg	186 - 225 J
onsumption extra urban	53.3 mpg	225+ L
onsumption combined	44.8 mpg	
O2 emission	166 g/km	
O2 label	Н	
uel type consumption city consumption extra urban consumption combined CO2 emission	Diesel 35.3 mpg 53.3 mpg 44.8 mpg 166 g/km	141 - 165 F G 166 - 185 H I 186 - 225 K





Internet history

Entry 1

Date Pictures 2021-10-01

14

Listing price

View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-05-31
MOT pass rate	64 %
MOT passed	14
Failed MOT tests	8
Total advice items	59
Total items failed	8

MOT #22		2023-06-01 15:47
MOT test	number	431707462190
Result		✓ Passed
Next expi	ry date	2024-05-31
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice (4.1.4 (b))	Offside Front Headlamp has a product on the light source but not serious	y reducing light output
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Suspension component pin or bush slightly worn (5.3.4 (a) (i))
Advice (b))	Nearside Headlamp has a product on the light source but not seriously re	ducing light output (4.1.4
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Suspension component pin or bush slightly worn (5.3.4 (a)	(i))
Advice	Rear heat shield insecure	





MOT #21	2023-05-24 16:25
MOT test	number 820597662489
Result	× Failed
MAJOR (ii))	Nearside Rear Position lamp with a multiple light source more than 1/2 not functioning (4.2.1 (a)
Advice (b))	Nearside Headlamp has a product on the light source but not seriously reducing light output (4.1.4
Advice	Rear heat shield insecure
MAJOR	Front Windscreen washer not working (3.5 (a))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Suspension component pin or bush slightly worn (5.3.4 (a) (i))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
MAJOR	Offside Rear Position lamp with a multiple light source more than 1/2 not functioning (4.2.1 (a) (ii))
Advice (4.1.4 (b))	Offside Front Headlamp has a product on the light source but not seriously reducing light output
DANGER	OUS Rear Stop lamp(s) all not working (4.3.1 (a) (iii))
Advice	Nearside Rear Suspension component pin or bush slightly worn (5.3.4 (a) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
MAJOR	Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

MOT #20		2022-01-17 13:10
MOT test	number	469462755129
Result		✓ Passed
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	





MOT #19		2020-12-14 15:32
MOT test	number	170327049104
Result		✓ Passed
MOT #18		2020-12-10 11:44
MOT test	number	947308334685
Result		🗙 Failed
MAJOR	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))	
MAJOR	MAJOR Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))	

MOT #17	2019-12-12 15:14
MOT test number	319741469732
Result	🗸 Passed
Advice Offside Rear Suspension arm pin or bush worn but not resulting in excessi (i))	ve movement (5.3.4 (a)
Minor Central Rear Stop lamp(s) insecure high level brake lamp unit (4.3.1 (c) (i))	
Advice Nearside Rear Suspension arm pin or bush worn but not resulting in excess (a) (i))	sive movement (5.3.4

MOT #16	2019-12-12 10:40	
MOT test	number 892840651335	
Result	× Failed	
Advice (i))	Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a)	
MAJOR	Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	
Advice (a) (i))		
MAJOR	Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	
Minor	Central Rear Stop lamp(s) insecure high level brake lamp unit (4.3.1 (c) (i))	





MOT #15	2018-12-06 10:32
MOT test number	447452412326
Result	✓ Passed
MOT #14	2018-12-05 16:52
MOT test number	576381555379
Result	🗙 Failed

MAJOR Offside Front All direction indicators not working side repeater (4.4.1 (a) (ii))

MOT #13		2018-12-05 11:18
MOT test	number	540269469706
Result		🗙 Failed
MAJOR	Nearside Rear Service brake excessively fluctuating (1.2.1 (e))	
MAJOR	Offside Front Service brake excessively fluctuating (1.2.1 (e))	
MAJOR	Offside Front All direction indicators not working side repeater (4.4.1 (a) (ii))	
MAJOR	Offside Rear Service brake excessively fluctuating (1.2.1 (e))	

MOT #12	2018-01-03 15:18
MOT test number	122150761193
Result	✓ Passed

MOT #11		2017-03-14 14:08
MOT test	number	735432611332
Result		✓ Passed
Advice	Offside Front tyre worn to wear bar limits	
Advice	Offside Front Outer Road wheel slightly damaged rim (4.2.A.1a)	
Advice	Under covers fitted	
Advice	Engine bay covers fitted	





MOT #10		2016-02-26 10:19
MOT test	number	241299809912
Result		✓ Passed
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.	1i)
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Nearside front tyre close to tread wear bar indicator	
Advice	Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.2	1i)
Advice	Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i))

MOT #9	20	15-02-26 12:22
MOT test	number	118497255062
Result		✓ Passed
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Advice	Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	

MOT #8	2014-02-27 16:54
MOT test number	876578254068
Result	✓ Passed
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	



MOT #7	2014-02-27 10:20
MOT test number	356258754036
Result	🗙 Failed
Fail Nearside Rear Direction indicators incorrect colour (1.4.A.2f)	
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Fail Offside Direction indicators incorrect colour (1.4.A.2f)	
Fail Centre Rear Exhaust has a major leak of exhaust gases (7.1.2)	
Fail Parking brake: efficiency below requirements (3.7.B.7)	

MOT #6	2013-03-28 13:56
MOT test number	139737883472
Result	✓ Passed

МОТ #5	2013-03-28 10:52	
MOT test number	428777283042	
Result	🗙 Failed	
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)		
Fail Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)		
Advice Rear Brake pad(s) wearing thin (3.5.1g)		

MOT #4	2012-03-29 11:47
MOT test number	246389882066
Result	✓ Passed

HV07UVA

report date: 2024-03-28





MOT #3	2012-03-29 11:47
MOT test number	168629082051
Result	× Failed
Pass with rectification	Offside Rear Stop lamp not working (1.2.1b)
Pass with rectification	Nearside Rear Stop lamp not working (1.2.1b)
Pass with rectification	Nearside Rear Tyre has a cut in excess of the requirements deep enough to
reach the ply or cords (4.1.	D.1a)
MOT #2	2011-03-30 08:54
MOT test number 497	
Result	✓ Passed
MOT #1	2010-03-31 10:47

MOT test number	470410090078
Result	Passed



HV07UVA report date: 2024-03-28

Tax & MOT check

X Untaxed Tax expired: 15 December 2023	↓ MOT Expires: 31 May 2024
Tax status	Expired at 15 December 2023
Days left	136 days too late
MOT expiry date	31 May 2024
Full MOT history	See MOT history
Tax calculation	
Vehicle class	49

Vehicle class	49
Band	Н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-





Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	4. DEM PE
Туре	
Damage 2	AMPL
Damage 2	E Stand
Date	S.
Category	amp
Туре	

Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2007-03-29
Last registration	2023-06-01
Complete history	<u>See info</u>



Registration #1	2007-03-29	25 mi
Registration #2	2010-03-31	14.543 mi
Registration #3	2011-03-30	19.748 mi
Registration #4	2012-03-29	22.236 mi
Registration #5	2013-03-28	26.189 mi
Registration #6	2013-03-28	26.191 mi
Registration #7	2014-02-27	29.902 mi
Registration #8	2014-02-27	29.902 mi
Registration #9	2015-02-26	35.891 mi
Registration #10	2016-02-26	41.542 mi
Registration #11	2017-03-14	46.376 mi
Registration #12	2018-01-03	51.847 mi
Registration #13		11.777 esi
Registration #14		11.227 esi
Registration #15		11.117 esi
Registration #16		11.117 esi
Registration #17		11.777 esi
Registration #18		11.227 esi
Registration #19		11.777 esi
Registration #20		11.117 esi
Registration #21		11.117 esi
Registration #22		11.117 esi

More info >





Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1884 mm
Height	1736 mm
Length	4820 mm
Wheel base	2850 mm
Kerb weight	1807 kg
Max. allowed weight	2505 kg
Additional information	
Fuel tank capacity	70
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 16/16

Number of axles	2
Engine number	6U46590