



WR570XW

report date: 2024-03-29

General information

Make	FIAT
Model	BRAVO SPORT TJET
Colour	Blue
Year of manufacture	-
Top speed	132 mph
0 - 60 mph	8.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	150 BHP
Max. torque	206 Nm at 2.250 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	48.7 mpg
Consumption combined	39.8 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-04
Pictures	5
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history****MOT #18**

2021-11-10 15:56

MOT test number

339845756310

Result

✓ Passed

Next expiry date

2022-11-09

Advice Nearside Rear Nail in tyre**Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement front wishbone rear bush (5.3.4 (a) (i))**Minor** Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))**Advice** Offside Rear body damage**Advice** Rear Coil spring corroded both (5.3.1 (b) (i))**Advice** Nearside Front Play in steering rack inner joint(s)**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement front wishbone rear bush (5.3.4 (a) (i))**Advice** Central Exhaust mounting defective middle exhaust hanger 1/2 defective (6.1.2 (a))**Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**Minor** Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))**Advice** Nearside Rear rear light damaged**Advice** Offside Front Tyre worn close to legal limit/worn on edge close to limit and worn on edges (5.2.3 (e))

**MOT #17**

2020-11-04 13:03

MOT test number

287955886590

Result

✓ Passed

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))

MOT #16

2020-11-04 11:38

MOT test number

438881398433

Result

✗ Failed

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

DANGEROUS Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MAJOR Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Rear Exhaust mounting defective (6.1.2 (a))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Pass with rectification Front Windscreen washer provides insufficient washer liquid (3.5 (a))

Pass with rectification Nearside Front Headlamp aim too low (4.1.2 (a))

**MOT #15**

2020-03-30 13:43

MOT test number

350324095566

Result

✓ Passed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Rear Coil spring corroded NS and OS (5.3.1 (b) (i))
- Advice** Rear Exhaust mounting defective Back box mount slightly damaged (6.1.2 (a))
- Advice** Front Inner Tyre worn close to legal limit/worn on edge NS and OS (5.2.3 (e))
- Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))

MOT #14

2019-04-01 10:55

MOT test number

544928914727

Result

✓ Passed

- Advice** Exhaust system corroded
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #13** 2019-03-25 12:12**MOT test number** 957617588095**Result** ✗ Failed**MAJOR** Exhaust has a major leak of exhaust gases (6.1.2 (a))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Exhaust clamp missing from centre to rear section joint**MAJOR** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Exhaust system corroded**MOT #12** 2018-03-28 16:06**MOT test number** 782615373143**Result** ✓ Passed**Advice** Exhaust system heavily corroded.**Advice** Oil leak**MOT #11** 2018-03-28 08:02**MOT test number** 444427902761**Result** ✗ Failed**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**Advice** Oil leak**Advice** Exhaust system heavily corroded.**Advice** Offside Front Tyre worn close to the legal limit very low (4.1.E.1)



MOT #10 2017-03-27 15:32

MOT test number 473783441375

Result ✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Exhaust clamp missing from centre to rear box, exhaust is still secure at time of test
- Advice** Offside Rear coil spring corroded (2.4.C.1b)
- Advice** Nearside front tyre worn thin on inside edge
- Advice** Oil leak
- Advice** Nearside Rear coil spring corroded (2.4.C.1b)
- Advice** Exhaust back box deteriorated
- Advice** Parking brake lever has little reserve travel (3.1.6b)

MOT #9 2017-03-27 14:13

MOT test number 392230199042

Result ✗ Failed

- Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Advice** Parking brake lever has little reserve travel (3.1.6b)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Exhaust clamp missing from centre to rear box, exhaust is still secure at time of test
- Advice** Offside Rear coil spring corroded (2.4.C.1b)
- Advice** Nearside front tyre worn thin on inside edge
- Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Advice** Oil leak
- Advice** Nearside Rear coil spring corroded (2.4.C.1b)
- Advice** Exhaust back box deteriorated



MOT #8	2016-03-30 14:04
MOT test number	559073116935
Result	✓ Passed
Advice	Rear Brake pad(s) wearing thin (3.5.1g)

MOT #7	2016-03-30 10:51
MOT test number	215612906387
Result	✗ Failed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Rear Brake pad(s) wearing thin (3.5.1g)
Fail	Offside Rear Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)

MOT #6	2015-01-28 10:42
MOT test number	136678625048
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Rear Brake pad(s) wearing thin (3.5.1g)
Notice	Rear exhaust poor condition

MOT #5	2014-01-17 09:43
MOT test number	106247914051
Result	✓ Passed

MOT #4	2013-01-31 08:30
MOT test number	976101633015
Result	✓ Passed
Notice	Under-trays fitted obscuring some underside components
Notice	Exhaust tailbox corroded

**MOT #3** 2012-01-18 09:12**MOT test number** 339218112064**Result** ✓ Passed**Notice** Offside front tyre worn uneven**MOT #2** 2011-02-10 11:13**MOT test number** 386751841018**Result** ✓ Passed**MOT #1** 2011-02-08 16:34**MOT test number** 698849731045**Result** ✗ Failed**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-29
Current registration	
Plate since	2019-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-12-28
Last registration	2021-11-10
Complete history	See info



Registration #1	2007-12-28	24 mi
Registration #2	2011-02-08	14.347 mi
Registration #3	2011-02-10	14.348 mi
Registration #4	2012-01-18	20.527 mi
Registration #5	2013-01-31	28.368 mi
Registration #6	2014-01-17	34.988 mi
Registration #7	2015-01-28	43.405 mi
Registration #8	2016-03-30	53.418 mi
Registration #9	2016-03-30	53.418 mi
Registration #10	2017-03-27	57.257 mi
Registration #11	2018-03-27	61.100 mi
Registration #12	2018-03-27	61.100 mi
Registration #13	2018-03-27	61.100 mi
Registration #14	2018-03-27	61.100 mi
Registration #15	2018-03-27	61.100 mi
Registration #16	2018-03-27	61.100 mi
Registration #17	2018-03-27	61.100 mi
Registration #18	2018-03-27	61.100 mi
Registration #19	2018-03-27	61.100 mi
Registration #20	2018-03-27	61.100 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1792 mm
Height	1498 mm
Length	4336 mm
Wheel base	2600 mm
Kerb weight	1275 kg
Max. allowed weight	1785 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1164652