



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	GOLF BLUEMOTION TDI
Colour	Blue
Year of manufacture	2010
Top speed	118 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	103 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	51.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	C





MOT history

MOT expiry date	2021-10-28
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	20
Total items failed	5

MOT #12	2020-10-29 15:51
MOT test number	562241451466
Result	✓ Passed
Next expiry date	2021-10-28
Advice	Both front tyres worn on edges

MOT #11	2020-10-27 17:19
MOT test number	607398909221
Result	✗ Failed
Fail	Nearside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
Advice	Both front tyres worn on edges
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #10**

2019-10-01 16:45

**MOT test number**

249372318199

**Result**

✓ Passed

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement wishbone bush (5.3.4 (a) (i))

**Advice** Rear bumper slightly damaged

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing perished (5.2.3 (d) (ii))

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement wishbone bush (5.3.4 (a) (i))

**Advice** Offside Front Seat belt buckle slightly damaged casing cracked (7.1.2 (d))

**MOT #9**

2018-10-09 15:44

**MOT test number**

764011133309

**Result**

✓ Passed

**MOT #8**

2018-04-26 11:08

**MOT test number**

974871086932

**Result**

✓ Passed

**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #7**

2018-04-17 15:44

**MOT test number**

486006440817

**Result**

✗ Failed

**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Fail** Offside Front Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)

**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #6** 2017-04-24 12:42**MOT test number** 780274461980**Result** ✓ Passed**Advice** Undertrays and engine cover fitted**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #5** 2016-04-14 13:02**MOT test number** 531058748108**Result** ✓ Passed**Advice** Top and bottom vehicle protection covers fitted not allowing full inspection**Advice** Both front lower arm rear stabiliser bushes perished and worn**MOT #4** 2015-04-27 12:43**MOT test number** 279427515422**Result** ✓ Passed**MOT #3** 2014-03-10 11:27**MOT test number** 466589764043**Result** ✓ Passed



MOT #2	2014-03-06 08:11
MOT test number	458525264016
Result	✗ Failed
Fail	Windscreen has damage to an area in excess of a 10mm circle within zone 'A' (8.3.1a)
Fail	Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Fail	Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2013-05-23 11:13
MOT test number	827013643112
Result	✓ Passed
Notice	Nearside front tyre tread 3mm



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>GY10XVF</b>
Plate since	2019-06-29
Current registration	 <b>GY10XVF</b>
Plate since	2019-06-29

More info >





Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2010-07-08
Last registration	2020-10-29
Complete history	<a href="#">See info</a>



Registration #1	2010-07-08	7 mi
Registration #2	2013-05-23	15.590 mi
Registration #3	2014-03-06	20.074 mi
Registration #4	2014-03-10	20.074 mi
Registration #5	2015-04-27	35.219 mi
Registration #6	2016-04-14	47.130 mi
Registration #7	2017-04-24	60.179 mi
Registration #8	2019-05-29	75.277 mi
Registration #9	2019-05-29	75.277 mi
Registration #10	2019-05-29	75.277 mi
Registration #11	2019-05-29	75.277 mi
Registration #12	2019-05-29	75.277 mi
Registration #13	2019-05-29	75.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1820 mm
Height	1517 mm
Length	4774 mm
Wheel base	2709 mm
Kerb weight	1531 kg
Max. allowed weight	2060 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Engine number	CAY 733290