



A06IMJV

report date: 2024-03-28

General information

Make	LAND ROVER
Model	DEFENDER TD HARD TOP
Colour	Grey
Year of manufacture	2011
Top speed	82 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	121 BHP
Max. torque	360 Nm at 2.000 rpm
Engine capacity	2.402 cc
Cylinders	4
Fuel type	Diesel
Consumption city	22.6 mpg
Consumption extra urban	32.8 mpg
Consumption combined	28.3 mpg




LABEL UNKNOWN



Internet history

Entry 2

Date	2021-12-31
Pictures	24
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 1

Date	2021-12-30
Pictures	24
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-31
MOT pass rate	59 %
MOT passed	10
Failed MOT tests	7
Total advice items	47
Total items failed	19

MOT #17	2023-11-01 11:34
MOT test number	159564118071
Result	✓ Passed
Next expiry date	2024-10-31
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #16	2023-10-19 13:59
MOT test number	208500465785
Result	✗ Failed
Advice	Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Pass with rectification	Nearside Front Headlamp aim too high (4.1.2 (a))
Advice	Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Fail	Offside Front Steering linkage ball joint worn to the extent there is a serious risk of detachment (2.1.3 (b) (ii))
Fail	Service brake efficiency below requirements (1.2.2 (a) (i))
Pass with rectification	Offside Front Headlamp aim too high (4.1.2 (a))

**MOT #15** 2022-10-25 12:10**MOT test number** 978966684472**Result** ✓ Passed**MOT #14** 2021-11-30 11:11**MOT test number** 333769454615**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #13** 2020-11-09 12:42**MOT test number** 135434134488**Result** ✓ Passed**Advice** Nearside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing Perished and worn on inner tread (5.2.3 (d) (ii))**Minor** Offside Front Steering linkage ball joint ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt Deteriorated (2.1.3 (g) (i))**MOT #12** 2020-11-05 09:46**MOT test number** 741317177905**Result** ✗ Failed**Fail** Front Windscreen wiper does not clear the windscreen effectively Both, split (3.4 (b) (ii))**Fail** Service brake efficiency below requirements (1.2.2 (a) (i))**Minor** Offside Front Steering linkage ball joint ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt Deteriorated (2.1.3 (g) (i))**Fail** Offside Rear Service brake effort inadequate at a wheel (1.2.1 (a) (i))**Advice** Nearside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing Perished and worn on inner tread (5.2.3 (d) (ii))**Fail** Nearside Rear Service brake effort inadequate at a wheel (1.2.1 (a) (i))

**MOT #11**

2019-10-25 08:24

**MOT test number**

903067894578

**Result**

✓ Passed

- Advice** Nearside Front Nail in tyre
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Underside of vehicle/wheel arches muddy/dirty
- Advice** Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))

**MOT #10**

2019-10-24 11:17

**MOT test number**

904061501718

**Result**

✗ Failed

- Advice** Underside of vehicle/wheel arches muddy/dirty
- Fail** Nearside Rear Suspension component pin or bush excessively worn Trailing arm front bush (5.3.4 (a) (i))
- Advice** Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))
- Advice** Nearside Front Nail in tyre
- Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Offside Rear Suspension component pin or bush excessively worn Trailing arm front bush (5.3.4 (a) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #9**

2018-11-14 17:05

**MOT test number**

478541711523

**Result**

✓ Passed

- Advice** Oil leak, but not excessive Engine area (8.4.1 (a) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #8**

2018-11-13 10:07

**MOT test number**

975113788188

**Result****✗ Failed****Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Oil leak, but not excessive Engine area (8.4.1 (a) (i))**Fail** Nearside Front Headlamp levelling device inoperative (4.1.5 (a))**Fail** Offside Front Headlamp aim too high (4.1.2 (a))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c))**Minor** Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))**Advice** Nearside Rear Nail in tyre**Fail** Nearside Front Headlamp aim too low (4.1.2 (a))**MOT #7**

2017-10-25 08:53

**MOT test number**

322206355305

**Result****✓ Passed****Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #6**

2017-10-25 08:53

**MOT test number**

341213343059

**Result****✗ Failed****Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #5** 2016-10-26 11:22**MOT test number** 623052620819**Result** ✓ Passed**Advice** Steering arm deformed but serviceable steering box arm to stub (2.2.C.1d)**MOT #4** 2016-10-26 08:28**MOT test number** 547150276519**Result** ✗ Failed**Fail** Offside Rear Shock absorber has an excessively worn bush (2.7.4)**Advice** Steering arm deformed but serviceable steering box arm to stub (2.2.C.1d)**MOT #3** 2015-11-02 08:19**MOT test number** 875907118978**Result** ✓ Passed**MOT #2** 2014-11-04 12:46**MOT test number** 678808604399**Result** ✓ Passed**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Shock absorber has a slightly worn bush (2.7.4)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Shock absorber has a slightly worn bush (2.7.4)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #1

2014-11-04 12:46

MOT test number

366038604341

Result

✖ Failed

- Advice

Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Pass with rectification

Nearside Headlamp aim too high (1.8)
- Pass with rectification

Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Advice

Offside Rear Brake pad(s) wearing thin (3.5.1g)
- Advice

Offside Rear Shock absorber has a slightly worn bush (2.7.4)
- Advice

Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Pass with rectification

Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Advice

Nearside Rear Brake pad(s) wearing thin (3.5.1g)
- Advice

Nearside Rear Shock absorber has a slightly worn bush (2.7.4)





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
31 October 2024

Tax status	Valid until 1 October
------------	-----------------------

Days left	155
-----------	-----

MOT expiry date	31 October 2024
-----------------	-----------------

Full MOT history	<a href="#">See MOT history</a>
------------------	---------------------------------



Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many owners did this LAND ROVER have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this LAND ROVER had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this LAND ROVER is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2011-10-31
Last registration	2023-11-01
Complete history	<a href="#">See info</a>



Registration #1	2011-10-31	14 mi
Registration #2	2014-11-04	39.667 mi
Registration #3	2015-11-02	52.380 mi
Registration #4	2016-10-26	64.275 mi
Registration #5	2016-10-26	64.275 mi
Registration #6	2017-10-25	75.491 mi
Registration #7	2017-10-25	75.491 mi
Registration #8	2018-11-13	88.546 mi
Registration #9	2018-11-14	88.546 mi
Registration #10	2019-10-24	98.441 mi
Registration #11	2019-10-24	98.441 mi
Registration #12	2019-10-24	98.441 mi
Registration #13	2019-10-24	98.441 mi
Registration #14	2019-10-24	98.441 mi
Registration #15	2019-10-24	98.441 mi
Registration #16	2019-10-24	98.441 mi
Registration #17	2019-10-24	98.441 mi
Registration #18	2019-10-24	98.441 mi
Registration #19	2019-10-24	98.441 mi

More info >



Dimensions & weight

Width	1790 mm
Height	2128 mm
Length	4040 mm
Kerb weight	1759 kg
Max. allowed weight	2505 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Number of axles	2
Engine number	110819211015244DT