



report date: 2024-03-28

## General information

Make	VOLKSWAGEN
Model	TOURAN TDI S 5STR
Colour	Silver
Year of manufacture	2005
Top speed	110 mph
0 - 60 mph	13.5 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	103 BHP
Max. torque	250 Nm at 1.900 rpm
Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	47.1 mpg
CO2 emission	162 g/km
CO2 label	G





## MOT history

MOT expiry date	2021-12-17
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	38
Total items failed	8

MOT #18 2020-12-18 17:16

MOT test number 342790855328

Result ✓ Passed

Next expiry date 2021-12-17

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Suspension component rusty
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #17**

2019-12-11 14:33

**MOT test number**

487767063008

**Result**

✓ Passed

**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Central Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Offside Front mirror glass missing**MOT #16**

2019-12-11 14:33

**MOT test number**

839985079754

**Result**

✗ Failed

**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Pass with rectification** Offside Rear Position lamp not working (4.2.1 (a) (ii))**Advice** Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Offside Front mirror glass missing**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively both (3.4 (b) (ii))**Advice** Central Rear Child Seat fitted not allowing full inspection of adult belt**Pass with rectification** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #15** 2018-12-15 13:30**MOT test number** 733189543979**Result** ✓ Passed**Minor** Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated Both (5.3.4 (b) (i))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Nearside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))**MOT #14** 2018-12-10 14:52**MOT test number** 826274128824**Result** ✗ Failed**Advice** Nearside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))**Fail** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Minor** Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated Both (5.3.4 (b) (i))**Fail** Nearside Front Suspension arm pin or bush likely to become detached (5.3.4 (a) (ii))**MOT #13** 2017-12-09 10:44**MOT test number** 699383272036**Result** ✓ Passed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)

**MOT #12** 2016-12-13 12:07**MOT test number** 445832164814**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #11** 2015-11-21 13:59**MOT test number** 902453642506**Result** ✓ Passed**MOT #10** 2014-11-22 13:55**MOT test number** 459416624483**Result** ✓ Passed

- Advice** Offside Front Lower Suspension arm synthetic bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Notice** Engine covers fitted obscuring some components in the engine bay
- Advice** Nearside Front Lower Suspension arm synthetic bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Notice** Under-trays fitted obscuring some underside components

**MOT #9** 2013-11-14 15:32**MOT test number** 559508613301**Result** ✓ Passed

- Advice** Nearside Side repeater deteriorated, but still visible from a reasonable distance (1.4.A.2e)

**MOT #8** 2013-11-14 15:32**MOT test number** 829048913372**Result** ✗ Failed**Advice** Nearside Side repeater deteriorated, but still visible from a reasonable distance (1.4.A.2e)**Pass with rectification** Nearside Rear Tyre(s) incorrect because different size tyres are fitted on the same axle. (4.1.A.1a)**MOT #7** 2012-11-13 11:42**MOT test number** 149928212389**Result** ✓ Passed**MOT #6** 2012-11-13 11:42**MOT test number** 675768312300**Result** ✗ Failed**Pass with rectification** Offside Rear Direction indicator incorrect colour (1.4.A.2f)**MOT #5** 2011-10-06 12:58**MOT test number** 877279271295**Result** ✓ Passed**MOT #4** 2011-10-05 14:01**MOT test number** 779188971207**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #3** 2010-09-29 16:48**MOT test number** 280522570243**Result** ✓ Passed



MOT #2	2009-10-02 12:15
MOT test number	174095079279
Result	✓ Passed

  

MOT #1	2008-09-30 11:37
MOT test number	354434178492
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:  
27 January 2021

X

MOT

Expired:  
17 December 2021

Tax status	Expired at 27 January 2021
Days left	1187 days too late
MOT expiry date	17 December 2021
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-





Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	7
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2005-10-02
Last registration	2020-12-18
Complete history	<a href="#">See info</a>



Registration #1	2005-10-02	28 mi
Registration #2	2008-09-30	27.178 mi
Registration #3	2009-10-02	33.520 mi
Registration #4	2010-09-29	39.973 mi
Registration #5	2011-10-05	46.903 mi
Registration #6	2011-10-06	46.904 mi
Registration #7	2012-11-13	53.762 mi
Registration #8	2013-11-14	66.859 mi
Registration #9	2014-11-22	83.846 mi
Registration #10	2015-10-20	95.377 mi
Registration #11	2016-10-20	105.377 mi
Registration #12	2017-10-20	115.377 mi
Registration #13	2018-10-20	125.377 mi
Registration #14	2019-10-20	135.377 mi
Registration #15	2020-10-20	145.377 mi
Registration #16	2021-10-20	155.377 mi
Registration #17	2022-10-20	165.377 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2066 mm
Height	1635 mm
Length	4391 mm
Wheel base	2677 mm
Kerb weight	1498 kg
Max. allowed weight	2210 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	7
Engine number	BKC 732958