






### General information

| Make                | CITROEN           |
|---------------------|-------------------|
| Model               | DS3 DSTYLE TECHNO |
| Colour              | Purple            |
| Year of manufacture | 2014              |
| Top speed           | 130 mph           |
| 0 - 60 mph          | 7.3 seconds       |
| Gearbox             | 6 speed Manual    |

## Engine & fuel consumption

| Power                   | 156 BHP             |
|-------------------------|---------------------|
| Max. torque             | 240 Nm at 1.750 rpm |
| Engine capacity         | 1.598 cc            |
| Cylinders               | 4                   |
| Fuel type               | Petrol              |
| Consumption city        | 34.5 mpg            |
| Consumption extra urban | 60.1 mpg            |
| Consumption combined    | 47.1 mpg            |
| CO2 emission            | 135 g/km            |
| CO2 label               | E                   |







# Internet history

| Entry 2       |             |
|---------------|-------------|
| Date          | 2021-11-05  |
| Pictures      | 12          |
| Listing price | View report |



source: cargurus.co.uk

### Entry 1

Date

Pictures

Listing price

2021-09-24

12

View report



source: cargurus.co.uk









# MOT history

| MOT expiry date    | 2024-10-19 |
|--------------------|------------|
| MOT pass rate      | 62 %       |
| MOT passed         | 8          |
| Failed MOT tests   | 5          |
| Total advice items | 3          |
| Total items failed | 9          |

| MOT #13  | 2023-10-13 15:52 |
|--|------------------|
| MOT test number  | 649607488967     |
| Result   | ✓ Passed         |
| Next expiry date 2024-10-1   |                  |
| Minor Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) |                  |

| MOT #12  | 2023-10-13 13:49     |
|--|----------------------|
| MOT test number  | 431474446577         |
| Result   | 🗙 Failed             |
| <b>Fail</b> Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))             |                      |
| Minor Registration plate lamp inoperative in the case of multiple lamps or light sou | rces (4.7.1 (b) (i)) |

| MOT #11         | 2022-10-20 07:17 |
|-----------------|------------------|
| MOT test number | 562146403034     |
|                 |                  |
| Result          | ✓ Passed         |
|                 |                  |
| MOT #10         | 2022-10-18 13-41 |

| MOT #10   | 2022-10-18 13:41                        |
|---|---|
| MOT test number   | 599828164855                            |
| Result  | × Failed                                |
| Fail Exhaust system insecure back   | ox band and mounting broken (6.1.2 (a)) |
| <b>Fail</b> Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii)) |   |





| MOT #9   | 2021-10-02 06:40          |
|--|---------------------------|
| MOT test number  | 467364436906              |
| Result   | ✓ Passed                  |
|  |                           |
| MOT #8   | 2021-10-01 12:51          |
| MOT test number  | 661386982940              |
| Result   | 🗙 Failed                  |
| <b>Fail</b> Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))                          |                           |
| Fail         Front Brake disc significantly and obviously worn (1.1.14 (a) (i))                        |                           |
| FailOffside Drive shaft joint constant velocity boot split or insecure, no longer prev(6.1.7 (g) (ii)) | vents the ingress of dirt |

| MOT #7          | 2020-10-28 12:07 |
|-----------------|------------------|
| MOT test number | 706905263565     |
| Result          | ✓ Passed         |

| МОТ #6                  |   | 2020-10-28 12:07 |
|-------------------------|---|------------------|
| MOT test number         |   | 331172055241     |
| Result                  |   | 🗙 Failed         |
| Pass with rectification | Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii)) |                  |

| MOT #5          | 2019-11-08 15:24 |
|-----------------|------------------|
| MOT test number | 485615178272     |
| Result          | ✓ Passed         |
|                 |                  |

| MOT #4          | 2018-10-29 14:46 |
|-----------------|------------------|
| MOT test number | 585285742046     |
| Result          | ✓ Passed         |





| MOT #3  | 2018-10-29 12:44 |
|---|------------------|
| MOT test number   | 515426349070     |
| Result  | 🗙 Failed         |
| Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))  |                  |
| Fail Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))              |                  |
| Fail         Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) |                  |
|   |                  |
| MOT #2  | 2017-11-17 09:07 |

| MOT test number | 775316206889 |
|-----------------|--------------|
| Result          | ✓ Passed     |
|                 |              |

| MOT #1          | 2017-08-23 13:08 |
|-----------------|------------------|
| MOT test number | 586538746383     |
| Result          | ✓ Passed         |



Tax & MOT check

| <b>Tax due:</b><br>1 January 2025 | ✓<br>Taxed | <b>Expires:</b><br>19 October 2024 | √<br>мот               |
|-----------------------------------|------------|------------------------------------|------------------------|
| Tax status                        |            |                                    | Valid until 1 January  |
| Days left                         |            |                                    | 247                    |
| MOT expiry date                   |            |                                    | 19 October 2024        |
| Full MOT history                  |            |                                    | <u>See MOT history</u> |
| Tax calculation                   |            |                                    |                        |

| Vehicle class                           | 48         |
|---|------------|
| Band                                    | E          |
| Single payment (12 months)              | £ 180,00,- |
| Single six month payment                | £ 99,00,-  |
| Total payable by 12 monthly instalments | £ 189,00,- |





### Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 |         |
|----------|---------|
| Date     |         |
| Category | Lamp    |
| Туре     |         |
| Damage 2 | AMPL    |
|          | E Store |
| Date     | 1. E    |
| Category | amt     |
| Туре     |         |

#### Extra CITROEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





### Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value          | 4 10.000 |
|-----------------------------|----------|
| Auction value               | 4 10.000 |
| Average private trade value | 4 10.200 |





## Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| ******   |             |
|--|-------------|
| **********   |             |
| *******  |             |
| ******   |             |
| **********   |             |
| ********   |             |
|  | More info > |
| Plate changes  |             |
| See in this check if this CITROEN had different number plates. |             |
| Number of plates   | ,           |
| Carrent registration   |             |
| Plate since  |             |
| Carrent registration   |             |
| Plate since  |             |
|  |             |





### Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Contact info      |  |





# Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 16         |
| First mileage registration | 2014-08-18 |
| Last registration          | 2023-10-13 |
| Complete history           | See info   |



| Registration #1   | 2014-08-18 | 12 mi      |
|---|------------|------------|
| Registration #2   | 2017-08-23 | 21.835 mi  |
| Registration #3   | 2017-11-17 | 22.297 mi  |
| Registration #4   | 2018-10-29 | 28.145 mi  |
| Registration #5   | 2018-10-29 | 28.145 mi  |
| Registration #6   | 2019-11-08 | 34.474 mi  |
| Registration #7   | 2020-10-28 | 37.742 mi  |
| Devictuation #9   | 2020-10-28 | 37.742 mi  |
| Registration #8   | 2020-10-20 | 57.742 111 |
| Registration #9   | 2020-10-28 | 57.742 mi  |
| -   | 2020-10-28 | 57.742 mi  |
| Registration #9   | 2020-10-28 | 57.742 mi  |
| Registration #9<br>Registration #10   |            |            |
| Registration #9<br>Registration #10<br>Registration #11   |            |            |
| Registration #9<br>Registration #10<br>Registration #11<br>Registration #12                     |            |            |
| Registration #9<br>Registration #10<br>Registration #11<br>Registration #12<br>Registration #13 |            |            |

More info >





# Safety ratings

| NCAP rating    | ****            |
|----------------|-----------------|
| Adult          | 87%             |
| Children       | 71%             |
| Pedestrian     | 35%             |
| Safety systems | 83%             |
| Overall rating | 73%             |
| Video          | see crash video |



| Dimensions & weight                                    |                               |
|--|-------------------------------|
| Width  | 1715 mm                       |
| Height   | 1483 mm                       |
| Length   | 3948 mm                       |
| Wheel base   | 2464 mm                       |
| Kerb weight  | 1090 kg                       |
| Max. allowed weight                                    | 1590 kg                       |
|  |                               |
| Additional information                                 |                               |
| Additional information Fuel tank capacity              | 48                            |
|  | 48 l<br>Multi-Point Injection |
| Fuel tank capacity                                     |                               |
| Fuel tank capacity<br>Fuel delivery                    | Multi-Point Injection         |
| Fuel tank capacity<br>Fuel delivery<br>Number of doors | Multi-Point Injection<br>3    |