





report date: 2024-03-29

General information

Make	PEUGEOT
Model	206 SE
Colour	Blue
Year of manufacture	-
Top speed	123 mph
0 - 60 mph	9.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque 147 Nm at 4.000 rpm	
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	55.4 mpg
Consumption combined	44.1 mpg



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 2

Date	2021-06-29

Pictures 9

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date	2021-06-28
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

MOT history

MOT test number 394669961214

Result ✓ Passed

Next expiry date 2023-06-24

MOT #19 2022-06-17 14:05

MOT test number 921904007176

Result X Failed

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #18 2021-06-25 13:51

MOT test number 651675773074

Result ✓ Passed

MOT #17 2020-12-09 15:45

MOT test number 654700745013

Result ✓ Passed

Advice Fuel tank strap very corroded

MOT #16 2020-12-04 09:15

MOT test number 229706615419

Result ★ Failed

Fail Central Exhaust system insecure (6.1.2 (a))

Advice Exhaust has a minor leak of exhaust gases centre and rear very corroded (6.1.2 (a))

Fail Horn not working (7.7 (a) (ii))

Fail Rear Exhaust system insecure (6.1.2 (a))

Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

Advice Fuel tank strap very corroded

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #15

MOT test number

Result

Advice Fuel tank strap corroded/weak

Exhaust system corroded

MOT #14 2019-11-19 09:57 **MOT** test number 658628962891 Result × Failed Fail Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i)) Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) **Advice Advice** Fuel tank strap corroded/weak Fail Offside Side repeater not working (4.4.1 (a) (ii)) Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i)) Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) **Advice Advice** Exhaust system corroded Fail Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii)) **Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

MOT #13

2018-11-28 09:52

MOT test number

285567161922

Result

Advice
Fuel tank strap corroded

Minor
Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice
Front Brake disc worn, pitted or scored, but not seriously weakened corroded (1.1.14 (a) (ii))

Minor
Windscreen wiper blade defective both front (3.4 (b) (i))

CarCheck.co.uk page 4/12



MOT #6

Result

MOT test number

SA54XAK

report date: 2024-03-29

2011-11-28 09:17

228472031384

✓ Passed

MOT #12	2017-11-24 09:50
MOT test number	615462684549
Result	✓ Passed
Advice Front Exhaust has a minor leak of exhaust gases join (7.1.2)	
MOT #11	2016-11-23 09:13
MOT test number	677500059320
Result	✓ Passed
MOT #10	2015-11-24 09:30
MOT test number	270108861106
Result	✓ Passed
MOT #9	2014-11-26 09:23
MOT test number	408950334338
Result	✓ Passed
MOT #8	2013-11-25 10:03
MOT test number	945899323361
Result	✓ Passed
MOT #7	2012-11-06 14:57
MOT test number	988291112326
Result	✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-29

MOT #5	2010-11-22 09:19
MOT test number	734216320358
Result	✓ Passed
MOT #4	2009-11-27 16:10
MOT test number	871921539357
Result	✓ Passed
MOT #3	2009-11-21 09:20
MOT test number	323495729389
Result	× Failed
Fail Offside Registration plate lamp shows direct white light to the rear (1.1.C.1f)	
Fail Nearside Registration plate lamp shows direct white light to the rear (1.1.C.1f)	

Teal Side Registration plate lamp shows affect white light to the real (1.1.6.1)	
MOT #2	2008-11-15 08:28
MOT test number	423010028415
Result	✓ Passed
MOT #1	2007-11-17 09:28
MOT test number	472841327402
Result	✓ Passed
Notice Front discs corroded on inner edges	

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

· ·		
For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.		GEOT

	More info	>
Plate changes		
See in this check if this PEUGEOT had different number plates.		
Number of plates		,
Current registration	UK NEW YEAR	
Plate since		
Current registration	OK SIES	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courte et info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2004-11-30
Last registration	2022-06-20
Complete history	See info



Registration #1	2004-11-30	8 mi
Registration #2	2007-11-17	21.936 mi
Registration #3	2008-11-15	27.772 mi
Registration #4	2009-11-21	33.610 mi
Registration #5	2009-11-27	33.731 mi
Registration #6	2010-11-22	39.237 mi
Registration #7	2011-11-28	43.953 mi
Registration #8	2012-11-06	46.246 mi
Registration #9	2013-11-25	49.622 mi
Registration #10	2014-11-26	52.406 mi
Registration #11	2015-11-24	55.575 mi
Registration #12	2016-11-23	60.660 mi
Registration #13		11.777 es
Registration #14		11.117 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11.777 es
D		
Registration #22		71.777 es

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditionin
50295	
50482	
50501	
60566	
60567	
60569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1652 mm
Height	1426 mm
Length	3835 mm
Wheel base	2445 mm
Kerb weight	1088 kg

Additional information

Fuel tank capacity	50
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number Carcheck.co.uk	FX5N2270657 page 12/12