





report date: 2024-03-29

General information

Make	PEUGEOT
Model	307 SW SE
Colour	Silver
Year of manufacture	2007
Top speed	112 mph
0 - 60 mph	13.8 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	107 BHP
Max. torque	147 Nm at 4.000 rpm
Engine capacity	1.587 cc
Cylinders	4
Fuel type	Petrol
Consumption city	24.8 mpg
Consumption extra urban	44.8 mpg
Consumption combined	34.0 mpg
CO2 emission	194 g/km
CO2 label	J



CarCheck.co.uk page 1/13



report date: 2024-03-29

Internet history

Entry 1

Date 2021-06-30

Pictures 11

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

	~-				
10/1/	TC	h		-	r\ /
1011		ш	51	LUI	l V
	•			-	. ,

MOT expiry date	2024-07-10
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	19
Total items failed	1

MOT #17	2023-06-17 12:17
MOT test number	366449918060
Result	✓ Passed
Next expiry date	2024-07-10

MOT #16		2022-07-11 15:59
MOT test	number	399034541895
Result		✓ Passed
Advice	Rear Sub-frame pin or bush worn but not resulting in excessive movemen	at (5.3.4 (a) (i))

MOI #12	2022-07-08 12:00
MOT test number	443960870128
Result	★ Failed

DANGEROUS Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

MAJOR Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

MAJOR Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt NSF + OSF (5.3.4 (b) (ii))

Advice Rear Sub-frame pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

DANGEROUS Nearside Front Outer Tyre has a bulge, caused by separation or partial failure of its structure 205/55R16 (5.2.3 (d) (ii))

MAJOR Nearside Rear Shock absorbers has an excessively worn bush (5.3.2 (c))

Advice Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT #14 2021-06-09 07:36

MOT test number 142621315579

Result
✓ Passed

MOT #13 2020-04-16 08:30

MOT test number 382150049127

Result Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge inside edge (5.2.3 (e))

Advice Both rear tyres are slightly perished

MOT #12 2019-04-23 12:37

MOT test number 350257476409

Advice The nearside front tyre has slight wear to the inner edge

MOT #11 2019-04-23 09:07

MOT test number 351438157791

Result X Failed

Advice The nearside front tyre has slight wear to the inner edge

MAJOR Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #10 2018-04-25 09:55

MOT test number 625892996370

MOT #9 2017-04-26 11:37

MOT test number 207046578816

Result \rightarrow Passed

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT #8	2017-04-26 08:52
MOT test number	478043097631
Result	≍ Failed
Advice Rear Brake pad(s) wearing thin (3.5.1g)	
Fail Offside Rear rear brake binding (3.7.B.1)	

MOT #7	2016-03-23 11:12
MOT test number	211006524333
Result	✓ Passed
Advice Offside rear brake grabbing	

MOT #6	2015-04-01 09:18
MOT test number	549351395093
Result	✓ Passed
MOT #5	2014-04-07 09:32
MOT test number	398027794083
Result	✓ Passed

		·
MOT #4		2013-04-10 08:57
MOT test	number	399500603120
Result		✓ Passed
Notice	Offside rear brake binding slightly	
Notice	Play in steering rack inner joint(s)	

MOT #3	2012-03-29 09:16
MOT test number	878299282047
Result	✓ Passed

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #2		2011-04-04 09:34
MOT test	number	835694791042
Result		✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Notice	Nail in nearside rear tyre	

MOT #1	2010-04-19 09:05
MOT test number	480199900192
Result	✓ Passed

CarCheck.co.uk page 6/13



RF07CKP report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 September
Days left	126
MOT expiry date	10 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-

CarCheck.co.uk page 7/13



RF07CKP report date: 2024-03-29

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



RF07CKP report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

More info >

Owner history For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this PEUGEOT had different number plates. deer of plates factor scincore

CarCheck.co.uk page 10/13



RF07CKP report date: 2024-03-29

Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
011.1.6.	

Contact info

More info >


CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-05-08
Last registration	2023-06-17
Complete history	See info



Registration #1	2007-05-08	25 mi
Registration #2	2010-04-19	12.144 mi
Registration #3	2011-04-04	14.736 mi
Registration #4	2012-03-29	18.982 mi
Registration #5	2013-04-10	22.996 mi
Registration #6	2014-04-07	27.365 mi
Registration #7	2015-04-01	31.525 mi
Registration #8	2016-03-23	34.377 mi
Registration #9	2017-04-26	38.313 mi
Registration #10	2017-04-26	38.313 mi
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		91,777 esi
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		

More info >

CarCheck.co.uk page 12/13



RF07CKP report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1762 mm
Height	1580 mm
Length	4428 mm
Wheel base	2708 mm
Kerb weight	1469 kg
Max. allowed weight	1980 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 13/1:

Number of axles 2

Engine number FX6Q3186534