



HYUNDAI




report date: 2024-03-29

General information

Make	HYUNDAI
Model	IX20 SE
Colour	Blue
Year of manufacture	2015
Top speed	112 mph
0 - 60 mph	11.5 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	123 BHP
Max. torque	156 Nm at 4.200 rpm
Engine capacity	1.591 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	54.3 mpg
Consumption combined	43.5 mpg
CO2 emission	150 g/km
CO2 label	F





Internet history

Entry 1	
Date	2022-06-01
Pictures	34
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-06-28
MOT pass rate	64 %
MOT passed	7
Failed MOT tests	4
Total advice items	14
Total items failed	10

MOT #11	2023-06-22 12:40
MOT test number	319453830082
Result	✓ Passed
Next expiry date	2024-06-28
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #10	2023-06-22 10:01
MOT test number	686174123800
Result	✗ Failed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
Fail	Front Brake disc in such a condition that it is seriously weakened worn thin (1.1.14 (a) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #9	2022-06-29 11:08
MOT test number	656724482084
Result	✓ Passed

**MOT #8** 2021-10-29 13:50**MOT test number** 104978815276**Result** ✓ Passed**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #7** 2020-11-06 15:39**MOT test number** 106680220618**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #6** 2020-11-06 09:43**MOT test number** 913813286614**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Nearside Headlamp not working on main beam (4.1.1 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #5** 2020-01-28 12:57**MOT test number** 669142513982**Result** ✓ Passed**Advice** Central Items removed from driver's view prior to test

**MOT #4** 2020-01-28 10:38**MOT test number** 261085570303**Result** ✗ Failed**Advice** Central Items removed from driver's view prior to test**Fail** Central Rear Seat belt retracting mechanism defective (7.1.2 (e))**MOT #3** 2019-01-31 12:09**MOT test number** 903272301517**Result** ✓ Passed**MOT #2** 2019-01-31 12:09**MOT test number** 954344058006**Result** ✗ Failed**Pass with rectification** Offside Windscreen washer not working (3.5 (a))**Pass with rectification** Nearside Windscreen washer not working (3.5 (a))**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #1** 2018-08-02 13:04**MOT test number** 610767800520**Result** ✓ Passed**Advice** Offside Front Mobility aid fitted on steering wheel/does remove.



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
28 June 2024

Tax status	Valid until 1 June
Days left	33
MOT expiry date	28 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2015-09-29
Last registration	2023-06-22
Complete history	See info



Registration #1	2015-09-29	16 mi
Registration #2	2018-08-02	33.467 mi
Registration #3	2019-01-31	36.775 mi
Registration #4	2019-01-31	36.775 mi
Registration #5	2020-01-28	50.197 mi
Registration #6	2020-01-28	50.197 mi
Registration #7	2020-11-06	58.292 mi
Registration #8	2020-01-28	50.197 mi
Registration #9	2020-01-28	50.197 mi
Registration #10	2020-01-28	50.197 mi
Registration #11	2020-01-28	50.197 mi
Registration #12	2020-01-28	50.197 mi
Registration #13	2020-01-28	50.197 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	89%
Children	85%
Pedestrian	64%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1765 mm
Height	1600 mm
Length	4120 mm
Wheel base	2615 mm
Kerb weight	1335 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	G4FCFZ619006