



report date: 2024-03-29

General information

Make	NISSAN
Model	ALMERA SX
Colour	Grey
Year of manufacture	-
Top speed	110 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	97 BHP
Max. torque	136 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	51.4 mpg
Consumption combined	42.2 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2022-04-30
Pictures	50
Listing price	View report



source: cargurus.co.uk

**MOT history**

MOT #19	2022-01-28 16:11
MOT test number	820913188664
Result	✓ Passed
Next expiry date	2023-01-31
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #18	2022-01-28 15:05
MOT test number	642615667515
Result	✗ Failed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Fail	Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

MOT #17	2021-02-01 12:51
MOT test number	808550979098
Result	✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #16	2020-01-17 17:10
MOT test number	661535479769
Result	✓ Passed
Advice	Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #15	2019-01-14 10:30
MOT test number	906187314313
Result	✓ Passed

**MOT #14** 2018-01-12 12:25**MOT test number** 500141878347**Result** ✓ Passed**MOT #13** 2018-01-12 12:25**MOT test number** 424895943901**Result** ✗ Failed

- Pass with rectification** Nearside Registration plate lamp not illuminating the registration plate (1.1.C.1e)
- Pass with rectification** Front registration plate deteriorated (6.3.1d)
- Pass with rectification** Offside Registration plate lamp not illuminating the registration plate (1.1.C.1e)

MOT #12 2017-01-12 16:50**MOT test number** 786766615857**Result** ✓ Passed**MOT #11** 2017-01-12 16:50**MOT test number** 587214199907**Result** ✗ Failed

- Pass with rectification** Brake disc in such a condition that it is seriously weakened front both (3.5.1i)

MOT #10 2016-01-29 11:53**MOT test number** 365824382399**Result** ✓ Passed

- Advice** Slight corrosion on both front discs (inner surface)

**MOT #9** 2016-01-29 11:53**MOT test number** 920344527765**Result** ✗ Failed**Advice** Slight corrosion on both front discs (inner surface)**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**MOT #8** 2015-01-28 15:16**MOT test number** 805638725068**Result** ✓ Passed**MOT #7** 2014-01-29 17:16**MOT test number** 566249324018**Result** ✓ Passed**MOT #6** 2013-01-28 11:49**MOT test number** 937518823055**Result** ✓ Passed**MOT #5** 2012-01-27 12:36**MOT test number** 955807722074**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2011-01-19 15:10**MOT test number** 148709211087**Result** ✓ Passed

**MOT #3** 2010-02-18 10:06**MOT test number** 390359340064**Result** ✓ Passed**Notice** Front tyres wearing close to markers**Notice** NOTE sill covers prevent full inspection**MOT #2** 2010-02-18 10:06**MOT test number** 823519040088**Result** ✗ Failed**Notice** Front tyres wearing close to markers**Pass with rectification** Nearside Headlamp aim too high (1.8)**Notice** NOTE sill covers prevent full inspection**MOT #1** 2009-02-18 10:03**MOT test number** 751599449063**Result** ✓ Passed**Notice** NOTE plastic covers fitted preventing full inspection**Notice** Front tyres wearing close to wear markers



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2006-03-01
Last registration	2022-01-28
Complete history	See info



Registration #1	2006-03-01	16 mi
Registration #2	2009-02-18	10.579 mi
Registration #3	2010-02-18	13.794 mi
Registration #4	2011-01-19	16.119 mi
Registration #5	2012-01-27	28.766 mi
Registration #6	2013-01-28	38.226 mi
Registration #7	2014-01-29	45.495 mi
Registration #8	2015-01-28	52.282 mi
Registration #9	2016-01-29	60.236 mi
Registration #10	2016-01-29	60.236 mi
Registration #11	2016-01-29	60.236 mi
Registration #12	2016-01-29	60.236 mi
Registration #13	2016-01-29	60.236 mi
Registration #14	2016-01-29	60.236 mi
Registration #15	2016-01-29	60.236 mi
Registration #16	2016-01-29	60.236 mi
Registration #17	2016-01-29	60.236 mi
Registration #18	2016-01-29	60.236 mi
Registration #19	2016-01-29	60.236 mi
Registration #20	2016-01-29	60.236 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1706 mm
Height	1448 mm
Length	4197 mm
Wheel base	2535 mm
Kerb weight	1179 kg
Max. allowed weight	1710 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	343963