



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	COUPE SIII
Colour	Black
Year of manufacture	2007
Top speed	115 mph
0 - 60 mph	11.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	104 BHP
Max. torque	143 Nm at 4.500 rpm
Engine capacity	1.599 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.8 mpg
Consumption extra urban	44.8 mpg
Consumption combined	37.2 mpg
CO2 emission	182 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-05-22
Pictures	15
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-05-22
MOT pass rate	83 %
MOT passed	15
Failed MOT tests	3
Total advice items	21
Total items failed	7

MOT #18	2023-05-15 12:09
MOT test number	634563435337
Result	✓ Passed
Next expiry date	2024-05-22
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

MOT #17	2023-05-13 08:31
MOT test number	134584949030
Result	✗ Failed
Fail	Nearside Front Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))
Pass with rectification	Nearside Front Headlamp aim too low (4.1.2 (a))
Fail	Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

MOT #16	2022-05-07 11:10
MOT test number	579028319763
Result	✓ Passed
Minor	Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #15** 2021-05-23 15:59**MOT test number** 538779878903**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #14** 2020-11-23 09:22**MOT test number** 197709196430**Result** ✓ Passed**Advice** Inner Brake disc worn, pitted or scored, but not seriously weakened front and rear (1.1.14 (a) (ii))**Advice** Offside Rear Brake pad(s) wearing thin inner and outer pads (1.1.13 (a) (ii))**Advice** Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 205/55/16 91V 3MM (5.2.3 (e))**MOT #13** 2019-11-21 12:00**MOT test number** 904112921278**Result** ✓ Passed**Advice** Inner Brake disc worn, pitted or scored, but not seriously weakened front and rear (1.1.14 (a) (ii))**Advice** Inner Brake pad(s) wearing thin front and rear (1.1.13 (a) (ii))**MOT #12** 2018-11-20 09:07**MOT test number** 313942425081**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #11** 2017-12-04 15:50**MOT test number** 672018837785**Result** ✓ Passed**Advice** Rear Tyre worn close to the legal limit n/s and o/s (4.1.E.1)**Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**MOT #10** 2016-12-07 08:47**MOT test number** 736098326307**Result** ✓ Passed**MOT #9** 2015-12-07 17:39**MOT test number** 484244984797**Result** ✓ Passed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)**Advice** Front exhaust flexi deteriorating**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #8** 2014-12-15 16:57**MOT test number** 429059544309**Result** ✓ Passed**MOT #7** 2014-12-15 16:57**MOT test number** 198159944303**Result** ✗ Failed**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

**MOT #6** 2014-03-06 09:29**MOT test number** 178665764031**Result** ✓ Passed**MOT #5** 2013-03-08 12:39**MOT test number** 265947063013**Result** ✓ Passed**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2012-07-19 16:43**MOT test number** 317811802245**Result** ✓ Passed**MOT #3** 2012-07-19 11:14**MOT test number** 625831402290**Result** ✗ Failed**Fail** Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #2** 2011-07-06 12:23**MOT test number** 388397681115**Result** ✓ Passed**Notice** Pads getting low**MOT #1** 2010-07-02 16:23**MOT test number** 220523680110**Result** ✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
28 December 2023

✓

MOT

Expires:
22 May 2024

Tax status	Expired at 28 December 2023
Days left	123 days too late
MOT expiry date	22 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-06-29
Last registration	2023-05-15
Complete history	See info



Registration #1	2007-06-29	10 mi
Registration #2	2010-07-02	27.391 mi
Registration #3	2011-07-06	36.362 mi
Registration #4	2012-07-19	43.578 mi
Registration #5	2012-07-19	43.578 mi
Registration #6	2013-03-08	45.172 mi
Registration #7	2014-03-06	52.125 mi
Registration #8	2014-12-15	56.994 mi
Registration #9	2015-12-07	65.244 mi
Registration #10	2016-12-07	73.785 mi
Registration #11	2019-05-29	95.377 mi
Registration #12	2019-05-29	95.377 mi
Registration #13	2019-05-29	95.377 mi
Registration #14	2019-05-29	95.377 mi
Registration #15	2019-05-29	95.377 mi
Registration #16	2019-05-29	95.377 mi
Registration #17	2019-05-29	95.377 mi
Registration #18	2019-05-29	95.377 mi
Registration #19	2019-05-29	95.377 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1760 mm
Height	1330 mm
Length	4395 mm
Wheel base	2530 mm
Kerb weight	1256 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	G4ED7676195