



report date: 2024-03-29

General information

Make	VOLVO
Model	XC60 D4 R-DESIGN AWD
Colour	Red
Year of manufacture	2018
Top speed	127 mph
0 - 60 mph	8.3 seconds
Gearbox	8 speed automatic

Engine & fuel consumption

Power	188 BHP
Max. torque	400 Nm at 1.750 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Diesel
Consumption combined	2.8 mpg
CO2 emission	148 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-02-06
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2025-02-09
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	9
Total items failed	2

MOT #5	2024-01-30 12:46
MOT test number	709420713302
Result	✓ Passed
Next expiry date	2025-02-09
Advice	Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
Advice	Offside Track rod end ball joint has slight play steering (2.1.3 (b) (i))

MOT #4	2024-01-26 10:30
MOT test number	716128317512
Result	✗ Failed
Fail	Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Fail	Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
Advice	Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
Advice	Offside Track rod end ball joint has slight play steering (2.1.3 (b) (i))

MOT #3	2023-02-06 09:24
MOT test number	246287476831
Result	✓ Passed



MOT #2	2022-01-21 12:44
MOT test number	631992570897
Result	✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing and feathering/ worn slightly more on edge (5.2.3 (d) (ii))

MOT #1	2021-02-10 13:16
MOT test number	369690962648
Result	✓ Passed
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened Corroded (1.1.14 (a) (ii))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened Corroded (1.1.14 (a) (ii))
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened Corroded (1.1.14 (a) (ii))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened Corroded (1.1.14 (a) (ii))



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
9 February 2025

Tax status	Valid until 1 February
Days left	278
MOT expiry date	9 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
First licence fee (12 months)	£ 255,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 645,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2018-03-29
Last registration	2024-01-30
Complete history	See info



Registration #1	2018-03-29	8 mi
Registration #2	2019-05-29	25,377 mi
Registration #3	2021-02-10	17,786 mi
Registration #4	2022-01-21	38,067 mi
Registration #5	2023-05-29	25,377 mi
Registration #6	2023-05-29	25,377 mi
Registration #7	2024-01-30	25,377 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	98%
Children	87%
Pedestrian	76%
Safety systems	95%
Overall rating	90%
Video	see crash video



Dimensions & weight

Width	1999 mm
Height	1658 mm
Length	4688 mm
Wheel base	2865 mm
Kerb weight	1837 kg
Max. allowed weight	2450 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	2630153