



report date: 2024-03-29

General information

| | |
|---------------------|-------------------|
| Make | VOLVO |
| Model | S40 D SE (115BHP) |
| Colour | Green |
| Year of manufacture | - |
| Top speed | 121 mph |
| 0 - 60 mph | 10.5 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 114 BHP |
| Max. torque | 265 Nm at 1.750 rpm |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 38.2 mpg |
| Consumption extra urban | 65.7 mpg |
| Consumption combined | 52.3 mpg |



LABEL UNKNOWN



Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-07-30 |
| Pictures | 9 |
| Listing price | View report |



source: cargurus.co.uk

**MOT history**

| | |
|-------------------------|---|
| MOT #24 | 2021-09-08 10:42 |
| MOT test number | 338824646422 |
| Result | ✓ Passed |
| Next expiry date | 2022-09-16 |
| Advice | Oil leak, but not excessive (8.4.1 (a) (i)) |
| Advice | Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |
| Advice | Front Service brake fluctuating, but not excessively (1.2.1 (e)) |
| Advice | Front Brake disc worn, but not excessively (1.1.14 (a) (i)) |
| Advice | Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) |
| Advice | Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive Floor small corrosion outside structural area (5.3.6 (a) (i)) |

| | |
|------------------------|------------------|
| MOT #23 | 2020-09-17 10:02 |
| MOT test number | 940664879423 |
| Result | ✓ Passed |

| | |
|------------------------|------------------|
| MOT #22 | 2019-09-05 09:55 |
| MOT test number | 195320766621 |
| Result | ✓ Passed |

| | |
|------------------------|------------------|
| MOT #21 | 2018-09-04 12:57 |
| MOT test number | 837087111642 |
| Result | ✓ Passed |

- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))
- Advice** Rear Integral body structure is corroded but structural rigidity is not significantly reduced Chassis floorpan (6.1.1 (c) (i))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Nearside Front Lower Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #20**

2018-08-29 10:51

MOT test number

386879863325

Result**✗ Failed**

- Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
- Fail** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))
- Fail** Nearside Headlamp aim too high (4.1.2 (a))
- Advice** Nearside Front Lower Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Fail** Windscreen wiper not working (3.4 (a))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))
- Advice** Rear Integral body structure is corroded but structural rigidity is not significantly reduced Chassis floorpan (6.1.1 (c) (i))

MOT #19

2017-08-25 10:39

MOT test number

441097235162

Result**✓ Passed**

- Advice** Both rear brake discs corroded and pitted

MOT #18

2017-08-22 14:33

MOT test number

438472142962

Result**✗ Failed**

- Fail** Offside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)
- Fail** Nearside Rear Registration plate lamp not working (1.1.C.1d)
- Fail** Nearside Rear Inner Brake pipe excessively corroded (3.6.B.2c)
- Fail** Offside Front Front position lamp(s) not working (1.1.A.3b)
- Advice** Both rear brake discs corroded and pitted
- Fail** Nearside Front Brake hose excessively deteriorated (3.6.B.4d)

**MOT #17** 2016-11-03 14:24**MOT test number** 181657389567**Result** ✓ Passed**Advice** Offside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)**Advice** Oil leak**Advice** Offside Front Track rod end ball joint has slight play (2.2.B.1f)**MOT #16** 2015-10-27 17:14**MOT test number** 693759615559**Result** ✓ Passed**Advice** Oil leak on engine**Advice** Nearside Rear Brake pipe slightly corroded to flexi (3.6.B.2c)**MOT #15** 2015-10-27 14:44**MOT test number** 170681817555**Result** ✗ Failed**Advice** Nearside Rear Brake pipe slightly corroded to flexi (3.6.B.2c)**Advice** Oil leak on engine**Fail** Offside Side repeater not working (1.4.A.2c)**MOT #14** 2014-11-03 11:12**MOT test number** 848907604374**Result** ✓ Passed**Notice** Oil leak

**MOT #13**

2013-11-07 14:51

MOT test number

566711813363

Result

✓ Passed

Notice O/s rear tyre lumpy tread**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Notice** N/s rear tyre out of shape-close too failure**Advice** Nearside Rear Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #12**

2012-11-08 08:45

MOT test number

759733012300

Result

✓ Passed

Notice Oil leak**Advice** Rear Vehicle structure has slight corrosion (6.1.A.1)**Notice** Rear tyres lumping on tread**Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)**MOT #11**

2012-11-02 11:42

MOT test number

228277902306

Result

✗ Failed

Fail Offside Rear Mechanical brake component has restricted free movement (3.5.1k)**Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)**Notice** Oil leak**Fail** Offside Rear Brake pipe excessively corroded (3.6.B.2c)**Advice** Rear Vehicle structure has slight corrosion (6.1.A.1)**Notice** Rear tyres lumping on tread

**MOT #10** 2011-11-08 14:24**MOT test number** 975112011348**Result** ✓ Passed**Notice** Oil leak**MOT #9** 2011-11-03 14:48**MOT test number** 149217101356**Result** ✗ Failed**Notice** O/s wiper spit on edge of rubber**Fail** Offside Front Track rod end ball joint has excessive play (2.2.B.1f)**Notice** Oil leak**Fail** Offside Brake hose excessively deteriorated (3.6.B.4d)**MOT #8** 2010-10-21 08:41**MOT test number** 624484590220**Result** ✓ Passed**MOT #7** 2010-10-19 09:48**MOT test number** 884622790259**Result** ✗ Failed**Fail** Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)**Notice** Oil leak on engine**Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #6** 2009-11-06 09:04**MOT test number** 124210719319**Result** ✓ Passed

**MOT #5** 2009-11-04 16:04**MOT test number** 630648209394**Result** ✗ Failed**Fail** Brakes imbalanced across an axle (3.7.B.5b)**Notice** O/s/r tyre slightly out of shape**Fail** Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)**MOT #4** 2009-05-21 10:00**MOT test number** 240671849117**Result** ✓ Passed**MOT #3** 2008-05-21 15:26**MOT test number** 714162648157**Result** ✓ Passed**MOT #2** 2007-05-18 16:07**MOT test number** 231938537199**Result** ✓ Passed**MOT #1** 2006-05-02 12:49**MOT test number** 650902126195**Result** ✓ Passed



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |

More info >

Plate changes

See in this check if this VOLVO had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | ***** |
| Plate since | 2024-03-29 |
| Current registration | ***** |
| Plate since | 2024-03-29 |

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 26 |
| First mileage registration | 2003-05-30 |
| Last registration | 2021-09-08 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2003-05-30 | 21 mi |
| Registration #2 | 2006-05-02 | 25.095 mi |
| Registration #3 | 2007-05-18 | 35.676 mi |
| Registration #4 | 2008-05-21 | 46.537 mi |
| Registration #5 | 2009-05-21 | 60.302 mi |
| Registration #6 | 2009-11-04 | 62.987 mi |
| Registration #7 | 2009-11-06 | 62.987 mi |
| Registration #8 | 2010-10-19 | 72.788 mi |
| Registration #9 | 2010-10-21 | 72.846 mi |
| Registration #10 | 2011-11-03 | 84.833 mi |
| Registration #11 | 2011-11-08 | 84.833 mi |
| Registration #12 | 2012-11-02 | 96.399 mi |
| Registration #13 | 2012-11-08 | 96.399 mi |
| Registration #14 | 2013-05-20 | 96.399 mi |
| Registration #15 | 2013-05-20 | 96.399 mi |
| Registration #16 | 2013-05-20 | 96.399 mi |
| Registration #17 | 2013-05-20 | 96.399 mi |
| Registration #18 | 2013-05-20 | 96.399 mi |
| Registration #19 | 2013-05-20 | 96.399 mi |
| Registration #20 | 2013-05-20 | 96.399 mi |
| Registration #21 | 2013-05-20 | 96.399 mi |
| Registration #22 | 2013-05-20 | 96.399 mi |
| Registration #23 | 2013-05-20 | 96.399 mi |
| Registration #24 | 2013-05-20 | 96.399 mi |
| Registration #25 | 2013-05-20 | 96.399 mi |
| Registration #26 | 2013-05-20 | 96.399 mi |

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

| | |
|-------------|---------|
| Width | 1716 mm |
| Height | 1422 mm |
| Length | 4516 mm |
| Wheel base | 2562 mm |
| Kerb weight | 1255 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 60 l |
| Fuel delivery | Direct Injection |
| Number of doors | 4 |
| Number of axles | 2 |
| Engine number | F9QTC081849 |