



report date: 2024-03-28

General information

Make	CITROEN
Model	NEMO HDI 8V
Colour	Grey
Year of manufacture	2009
Top speed	94 mph
0 - 60 mph	18.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	160 Nm at 1.750 rpm
Engine capacity	1.399 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	C







Internet history

Entry 1

Date	2022-02-16
Pictures	14
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-30
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	24
Total items failed	1

MOT #14	2023-08-31 11:43
MOT test number	640018296815
Result	✓ Passed
Next expiry date	2024-08-30

MOT #13	2022-08-26 15:24
MOT test number	255261054961
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Oil leak, but not excessive drive shaft oil seal (8.4.1 (a) (i))

MOT #12	2021-08-25 09:19
MOT test number	419563747312
Result	✓ Passed
Advice	Offside Rear O/S/R brake noisy

MOT #11	2020-08-24 14:13
MOT test number	975487562065
Result	✓ Passed
Advice	Signs of fuel leak from filler or breather pipe area to fuel tank. Not leaking at time of test

**MOT #10** 2020-08-24 09:31**MOT test number** 615648080945**Result** ✗ Failed**MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Signs of fuel leak from filler or breather pipe area to fuel tank. Not leaking at time of test**MOT #9** 2019-08-20 11:42**MOT test number** 692534208160**Result** ✓ Passed**Advice** Engine covers and under trays fitted**MOT #8** 2018-08-28 15:55**MOT test number** 492926970521**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Strut top bearing rough when rotated**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Bonnet release handle broken**MOT #7** 2017-11-24 11:55**MOT test number** 593590141739**Result** ✓ Passed

**MOT #6** 2016-11-25 11:28**MOT test number** 921315390810**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2015-11-27 11:37**MOT test number** 107934395036**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Parking brake lever has little reserve travel (3.1.6b)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2014-12-30 11:29**MOT test number** 306154464346**Result** ✓ Passed**MOT #3** 2013-12-13 11:30**MOT test number** 275977043349**Result** ✓ Passed**Notice** Rear wiper blade torn**MOT #2** 2012-12-07 15:59**MOT test number** 497132942476**Result** ✓ Passed**Advice** Nearside Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)**Advice** Offside Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)



MOT #12012-12-05 10:03

MOT test number908320542340

Result

Failed

- Advice

Offside Rear Shock absorber has a slightly worn bush (2.7.4)
- Advice

Offside Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)
- Fail

Nearside Rear Shock absorber has an excessively worn bush (2.7.4)
- Advice

Nearside Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
30 August 2024

Tax status	Valid until 1 July
Days left	63
MOT expiry date	30 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history


Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-12-30
Last registration	2023-08-31
Complete history	See info



Registration #1	2009-12-30	14 mi
Registration #2	2012-12-05	29.497 mi
Registration #3	2012-12-07	29.498 mi
Registration #4	2013-12-13	39.017 mi
Registration #5	2014-12-30	47.966 mi
Registration #6	2015-11-27	54.686 mi
Registration #7	2016-11-25	63.597 mi
Registration #8	2017-11-24	73.004 mi
Registration #9	2018-05-29	85.377 mi
Registration #10	2019-05-29	95.377 mi
Registration #11	2020-05-29	105.377 mi
Registration #12	2021-05-29	115.377 mi
Registration #13	2022-05-29	125.377 mi
Registration #14	2023-05-29	135.377 mi
Registration #15	2023-08-31	140.000 mi
Registration #16	2023-08-31	140.000 mi

More info >



Dimensions & weight

Width	1816 mm
Height	1721 mm
Length	3959 mm
Wheel base	2513 mm
Kerb weight	1185 kg
Max. allowed weight	1710 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	FD982532186