






### General information

Make	CITROEN
Model	DS3 DSPORT PLUS
Colour	White
Year of manufacture	2014
Top speed	132 mph
0 - 60 mph	8.2 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	155 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.3 mpg
Consumption extra urban	58.9 mpg
Consumption combined	47.9 mpg
CO2 emission	137 g/km
CO2 label	E





Internet history	
Entry 1	
Date	2021-06-19
Pictures	1
Listing price	View report



source: autotrader.co.uk



# MOT history

MOT expiry date	2024-08-25
MOT pass rate	64 %
MOT passed	7
Failed MOT tests	4
Total advice items	31
Total items failed	8

MOT #11		2023-08-26 08:05
MOT test	number	541426338796
Result		✓ Passed
Next expiry date 2024-08		2024-08-25
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened Both (1.1.14 (a) (ii))		(1.1.14 (a) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #10		2022-07-29 10:53
MOT test	number	288362765553
Result		✓ Passed
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened both side	s (1.1.14 (a) (ii))
Advice	Rear Service brake fluctuating, but not excessively both sides (1.2.1 (e))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	



МОТ #9	2022-07-20 10:37
MOT test number	733917382623
Result	🗙 Failed
Advice Front Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))	
Advice Rear Service brake fluctuating, but not excessively both sides (1.2.1 (e))	
<b>Fail</b> Front Registration plate does not conform to the specified requirements (0.1 (d)	)
<b>Fail</b> Offside Front Drive shaft joint constant velocity boot split or insecure, no longer of dirt (6.1.7 (g) (ii))	prevents the ingress
Advice Nearside Rear Nail in tyre	
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened both side	es (1.1.14 (a) (ii))
Minor Nearside Rear Tyre obviously under inflated (5.2.3 (I))	
<b>Fail</b> Rear Registration plate does not conform to the specified requirements (0.1 (d))	

МОТ #8	2021-06-28 15:29
MOT test number	994795330481
Result	✓ Passed

MOT #7	2020-10-16 09:10
MOT test number	267631772777
Result	✓ Passed
Advice Lens missing from off side number plate light unit	

МОТ #6	2020-10-15 15:11	
MOT test number	515719055684	
Result	🗙 Failed	
<b>Fail</b> Registration plate lamp inoperative in the case of a single lamp or all lamps Both lamps not working (4.7.1 (b) (ii))		
<b>Fail</b> Offside Registration plate lamp missing in the case of a single lamp or all missing (4.7.1 (b) (ii))	lamps Offside lamp, lens is	





MOT #5		2019-10-02 08:19
MOT test	number	108836041294
Result		✓ Passed
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened corroded	(1.1.14 (a) (ii))
Advice	Exhaust corroded	
MOT #4		2019-10-02 08:19
MOT test	number	840705700351

Mortest number	0+070570055	Ŧ
Result	× Faile	d
Advice Rear Brake pad(	s) wearing thin (1.1.13 (a) (ii))	
Advice Exhaust corrode	d	
Pass with rectification	Offside Front Position lamp not working (4.2.1 (a) (ii))	
Advice Rear Brake disc	worn, pitted or scored, but not seriously weakened corroded (1.1.14 (a) (ii))	

MOT #3		2018-10-08 13:44
MOT test	number	990500987485
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge on 2mm (5.2.3 (e))	
Advice	Rear Brake disc worn, but not excessively corroded (1.1.14 (a) (i))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge on 2mm (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge on 2mm (5.2.3 (e))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge on 2mm (5.2.3 (e))	





MOT #2	2018-10-08 08:12
MOT test number	785621719837
Result	🗙 Failed
<b>Fail</b> Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light (i))	t sources (4.7.1 (b)
Advice Nearside Front Tyre worn close to legal limit/worn on edge on 2mm (5.2.3 (e))	
Advice Nearside Rear Tyre worn close to legal limit/worn on edge on 2mm (5.2.3 (e))	
Fail         Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	
Advice Central Rear Exhaust mounting defective (6.1.2 (a))	
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a)	(ii))
Advice Offside Front Tyre worn close to legal limit/worn on edge on 2mm (5.2.3 (e))	
Advice Offside wiper blade worn	
Advice Offside Rear Tyre worn close to legal limit/worn on edge on 2mm (5.2.3 (e))	
Advice Rear Brake disc worn, but not excessively corroded (1.1.14 (a) (i))	

MOT #1	2017-09-25 12:39
MOT test number	623789060050
Result	✓ Passed



Tax & MOT check

<b>Tax due:</b> 1 March 2025	✓ Taxed	✓ MOT Expires: 25 August 2024
Tax status		Valid until 1 March
Days left		306
MOT expiry date		25 August 2024
Full MOT history		See MOT history
Tax calculation		

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-





#### Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date		
Category		Lamp
Туре		
Damage 2		AMPL
Date		· · ·
Category	1000000	AMPL
Туре		

#### Extra CITROEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





### Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	6.00.000
Auction value	4 11.111
Average private trade value	4 10 200

More info  $\rightarrow$ 





### Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

******	
**********	
*******	
******	
*********	
*******	
	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	,
Current registration	
Rinks sizes	
Plane since	
Current registration	

More info >



#### Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info  $\rightarrow$ 



L8BMV report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-05-29
Last registration	2023-08-26
Complete history	See info



Registration #1	2014-05-29	28 mi
Registration #2	2017-09-25	37.431 mi
Registration #3	2018-10-08	47.308 mi
Registration #4	2018-10-08	47.308 mi
Registration #5	2019-10-02	57.059 mi
Registration #6	2019-10-02	57.059 mi
Registration #7	2020-10-15	64.492 mi
Registration #8		10.000 est
Registration #8 Registration #9		11.777 es
-		11.577 es
Registration #9		11.777 46 11.777 46 11.777 46 11.777 46
Registration #9 Registration #10		01,000 est 01,000 est 01,000 est 01,000 est 01,000 est

More info  $\rightarrow$ 



# Safety ratings

NCAP rating	****
Adult	87%
Children	71%
Pedestrian	35%
Safety systems	83%
Overall rating	73%
Video	see crash video



Dimensions & weight	
Width	1715 mm
Height	1483 mm
Length	3948 mm
Wheel base	2464 mm
Kerb weight	1090 kg
Max. allowed weight	1619 kg
Additional information	
Additional information Fuel tank capacity	48
	48 l Multi-Point Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Multi-Point Injection
Fuel tank capacity Fuel delivery Number of doors	Multi-Point Injection 3