





report date: 2024-03-29

General information

Make	HYUNDAI	
Model	SANTA FE CRDI PREMIUM SE	
Colour	Silver	
Year of manufacture	2013	
Top speed	118 mph	
Gearbox	6 speed Manual	

Engine & fuel consumption

Power	194 BHP
Max. torque	422 Nm at 2.500 rpm
Engine capacity	2.199 сс
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	54.3 mpg
Consumption combined	46.3 mpg
CO2 emission	159 g/km
CO2 label	G



CarCheck.co.uk page 1/13



report date: 2024-03-29

Internet history

Entry 1

Date 2021-10-04

Pictures 16

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

MOT history

MOT expiry date	2024-10-14
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	20
Total items failed	9

MOT #13		2023-09-26 07:45
MOT test	number	549859486053
Result		✓ Passed
Next expi	ry date	2024-10-14
Advice Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))		
Advice Front Brake disc worn, pitted or scored, but not seriously weakened Both corroded (1.1.14 (a) (ii))		
Advice	Nearside DLR inoperative	

MOT #12		2023-09-25 13:05
MOT test	number	698448084489
Result		🗙 Failed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened Both of	corroded (1.1.14 (a) (ii))
Fail O	ffside Stop lamp(s) not working (4.3.1 (a) (ii))	
Advice	Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside DLR inoperative	
Fail O	ffside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))	

CarCheck.co.uk page 3/13



report date: 2024-03-29

× Failed

MOT #11 2022-10-05 15:08 446986941656

Result ✓ Passed

Advice

Result

Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #10 2022-09-30 08:10

MOT test number 796025940594

Advice Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

The state of the s

Fail Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

Fail Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #9 2021-10-15 14:36

MOT test number 360090794851

Result \rightarrow Passed

MOT #8 2021-10-15 08:32

MOT test number 821515335173

Result X Failed

Fail Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

Advice Oil leak, but not excessive Rear diff (8.4.1 (a) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened Both inner edges (1.1.14 (a)

(ii))

Fail Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT test number

926293182543

Result

Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #6

MOT test number

Result

Advice

Tyre worn close to legal limit/worn on edge all 4 tyres (5.2.3 (e))

MOT #5

MOT test number

Result

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #4

MOT test number

Result

Advice Both number plates have large gaps

2018-01-24 12:46

219333306291

✓ Passed

MOT test number
975455325812

Result

Advice Both number plates have large gaps

Fail Offside Front Track rod end ball joint has excessive play (2.2.B.1f)

Fail Nearside Front Headlamp aim too high (1.8)

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #2	2017-01-18 13:10
MOT test number	740717326340
Result	✓ Passed
MOT #1	2016-01-20 11:06
MOT test number	376586368198
Result	✓ Passed
Advice Rear Brake pad(s) wearing thin (3.5.1g)	
Advice Front Brake pad(s) wearing thin (3.5.1g)	

CarCheck.co.uk page 6/13



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 October
Days left	156
MOT expiry date	14 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 7/13



CA62KOD report date: 2024-03-29

Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	
THE PARTY OF THE P	

	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	,
Current registration	AK UK
Plate since	
Current registration	NIV.
Plate since	
	More info >

CarCheck.co.uk page 10/13



CA62KOD report date: 2024-03-29

Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2013-02-01
Last registration	2023-09-26
Complete history	See info



Registration #1	2013-02-01	18 mi
Registration #2	2016-01-20	54.272 mi
Registration #3	2017-01-18	71.271 mi
Registration #4	2018-01-22	82.319 mi
Registration #5	2018-01-24	82.353 mi
Registration #6	2019-01-30	90.979 mi
Registration #7	2020-01-27	96.577 mi
Registration #8	2021-01-23	100.213 mi
Registration #9		11.777 es
Registration #10		71.777 es
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		11.177 es

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	96%
Children	89%
Pedestrian	71%
Safety systems	86%
Overall rating	89%
Video	see crash video



Dimensions & weight

Width	1880 mm
Height	1690 mm
Length	4690 mm
Wheel base	2700 mm
Kerb weight	1963 kg
Max. allowed weight	2600 kg

Additional information

Fuel tank capacity	64 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 13/1

Number of axles 2

Engine number D4HBCU725649