





report date: 2024-03-28

General information

Make	PEUGEOT
Model	107 ACTIVE
Colour	White
Year of manufacture	2013
Top speed	100 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	93 Nm at 3.600 rpm
Engine capacity	998 сс
Cylinders	3
Fuel type	Petrol
Consumption city	55.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	99 g/km
CO2 label	А



CarCheck.co.uk page 1/12



Internet history

Entry 2

Date 2021-11-26

10 **Pictures**

Listing price View report









source: autoonline.co.uk

Entry 1

Date	2021-11-26
Pictures	41

Listing price View report









source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-11-22
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	15
Total items failed	4

MOT #12		2023-11-09 09:24
MOT test	number	566038574385
Result		✓ Passed
Next expi	ry date	2024-11-22
Advice Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))		
Advice	Nearside Rear Nail in tyre	

MOT #11	2022-11-14 11:19
MOT test number	485640428133
Result	✓ Passed
MOT #10	2021-11-23 13:45
MOT test number	963533026243
Result	✓ Passed

MOT #9	2021-11-22 14:23
MOT test number	678665623027
Result	X Failed
Advice Front Tyre worn close to legal limit/worn on edge BOTH (5.2.3 (e))	
Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))	

CarCheck.co.uk page 3/12



YF62ZKT

report date: 2024-03-28

MOT #8 2021-02-13 10:42

MOT test number 177723482878

Result ✓ Passed

Advice Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #7 2021-02-12 14:10

MOT test number 621169225031

Result X Failed

Fail Offside Rear fog lamp not working (4.5.1 (a) (ii))

Advice Offside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Fail Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

MOT #6 2020-02-14 16:11

MOT test number 346538886195

Result \rightarrow Passed

MOT #5 2020-02-14 10:48

MOT test number 160355391216

Result × Failed

Advice Engine oil on min level

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Fail Offside Rear fog lamp not working (4.5.1 (a) (ii))

Advice Coolant on min level

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 4/12



MOT #4 2019-02-18 10:27

MOT test number 569723935483

Result ✓ Passed

Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #3 2018-02-16 16:12

MOT test number 860234404036

Result Passed

Advice

Offside Front Front suspension has slight movement at a wishbone pin or bush rear bush

(2.5.A.1c)

MOT #2 2017-02-17 11:30

MOT test number 273944976470

Result ✓ Passed

Advice Nearside Front Tyre worn close to the legal limit 155/65/14 advise front wheel tracking tyres worn on inside (4.1.E.1)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1 2016-02-13 14:47

MOT test number 576215835406

Result ✓ Passed

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 December
Days left	217
MOT expiry date	22 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.		GEOT

	More info	>
Plate changes		
See in this check if this PEUGEOT had different number plates.		
Number of plates		,
Current registration	UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2013-01-18
Last registration	2023-11-09
Complete history	See info



Registration #1	2013-01-18	28 mi
Registration #2	2016-02-13	44.014 mi
Registration #3	2017-02-17	53.579 mi
Registration #4	2018-02-16	63.863 mi
Registration #5	2019-02-18	73.299 mi
Registration #6	2020-02-14	82.926 mi
Registration #7	2020-02-14	82.926 mi
Registration #8	2021-02-12	91.750 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91.777 es
Registration #12		11.777 es
Registration #13		91.777 es
Registration #14		11.777 es
Registration #15		D.777 es

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
50569	

Safety ratings

NCAP rating	***
Adult	68%
Children	73%
Pedestrian	53%
Safety systems	71%
Overall rating	66%
Video	see crash video



Dimensions & weight

Width	1855 mm
Height	1470 mm
Length	3430 mm
Wheel base	2340 mm
Kerb weight	900 kg
Max. allowed weight	1180 kg

Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 12/12