




report date: 2024-03-29

General information

Make	NISSAN
Model	PIXO N-TEC
Colour	Red
Year of manufacture	2009
Top speed	96 mph
0 - 60 mph	14.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	90 Nm at 3.400 rpm
Engine capacity	996 cc
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	64.2 mpg
CO2 emission	103 g/km
CO2 label	B





MOT history

MOT expiry date	2024-10-31
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	44
Total items failed	11

<b>MOT #16</b>	2023-11-01 11:36
MOT test number	469502587824
Result	✓ Passed
Next expiry date	2024-10-31

<b>MOT #15</b>	2022-11-01 09:18
MOT test number	600229019434
Result	✓ Passed

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing perishing (5.2.3 (d) (ii))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear of arm (5.3.4 (a) (i))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear of arm (5.3.4 (a) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing perishing (5.2.3 (d) (ii))

<b>MOT #14</b>	2021-10-15 09:01
MOT test number	432631008362

Result	✓ Passed
--------	----------

- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Offside Front Brake pad(s) wearing thin inner pad (1.1.13 (a) (ii))
- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Nearside Rear Tyre slightly damaged 155/ 65/ r14 (5.2.3 (d) (ii))



MOT #13 2021-10-14 14:10

MOT test number 458429371399

Result ✗ Failed

**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Offside Front Brake pad(s) wearing thin inner pad (1.1.13 (a) (ii))

**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

**Fail** Nearside Front Wheel bearing rough when rotated (5.1.3 (b) (i))

**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**Advice** Nearside Rear Tyre slightly damaged 155/ 65/ r14 (5.2.3 (d) (ii))

**Fail** Exhaust carbon monoxide content at idle exceeds default limits (8.2.1.2 (b))

**Fail** Nearside Front Brake pipe excessively corroded (1.1.11 (c))

MOT #12 2020-09-22 09:42

MOT test number 899340035430

Result ✓ Passed

MOT #11 2019-09-23 15:31

MOT test number 230576594474

Result ✓ Passed

**Advice** Nearside Front tyre wearing edges

**Advice** Rear tyres cracking in treads slightly

**Advice** Offside Front tyre tread low & wearing edges

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened slightly worn (1.1.14 (a) (ii))

**Advice** Front suspension arm rear bushes cracking



MOT #10 2019-09-20 12:50

MOT test number 851411067113

Result ✗ Failed

**Advice** Offside Front tyre tread low & wearing edges

**Fail** Offside Front Brake pipe excessively corroded (1.1.11 (c))

**Advice** Front suspension arm rear bushes cracking

**Fail** Horn not working (7.7 (a) (ii))

**Advice** Nearside Front tyre wearing edges

**Fail** Brake pipe excessively corroded BOTH front to rears at rear flexible hoses (1.1.11 (c))

**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Rear tyres cracking in treads slightly

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened slightly worn (1.1.14 (a) (ii))

MOT #9 2018-09-22 09:14

MOT test number 368968264077

Result ✓ Passed

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Nearside Front Wheel bearing slightly noisy (5.1.3 (b) (i))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))



MOT #8 2018-02-06 14:38

MOT test number 391088714658

Result ✔ Passed

- Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement REAR (2.4.G.2)
- Advice** Nearside Front wheel bearing slightly rough
- Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement REAR (2.4.G.2)
- Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)

MOT #7 2017-02-22 12:56

MOT test number 705225880841

Result ✔ Passed

- Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement REAR (2.4.G.2)
- Advice** Nearside Front Wheel bearing slightly rough when rotated
- Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)
- Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement REAR (2.4.G.2)

MOT #6 2017-02-22 11:37

MOT test number 651400836519

Result ✘ Failed

- Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement REAR (2.4.G.2)
- Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Advice** Nearside Front Wheel bearing slightly rough when rotated
- Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement REAR (2.4.G.2)
- Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)



<b>MOT #5</b>	2016-02-25 11:59
<b>MOT test number</b>	706672831767
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement REAR (2.4.G.2)
<b>Advice</b>	Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement REAR (2.4.G.2)
<b>Advice</b>	Offside rear tyre outer wall cracks appearing

<b>MOT #4</b>	2015-02-26 16:53
<b>MOT test number</b>	116267355051
<b>Result</b>	✓ Passed

<b>MOT #3</b>	2014-08-11 15:18
<b>MOT test number</b>	135073424236
<b>Result</b>	✓ Passed
<b>Notice</b>	OSR Tyre sidewall starting to perish

<b>MOT #2</b>	2013-08-13 11:38
<b>MOT test number</b>	176065923258
<b>Result</b>	✓ Passed

<b>MOT #1</b>	2012-08-17 14:27
<b>MOT test number</b>	527160232244
<b>Result</b>	✓ Passed



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 May 2025

✓  
**MOT**

**Expires:**  
31 October 2024

<b>Tax status</b>	Valid until 1 May
<b>Days left</b>	366
<b>MOT expiry date</b>	31 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	B
<b>Single payment (12 months)</b>	£ 20,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 21,00,-




Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



## Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

<b>Trade retail value</b>	£ 19,999
<b>Auction value</b>	£ 19,999
<b>Average private trade value</b>	£ 19,999

[More info >](#)



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	<b>RV59WPM</b>
Plate since	2024-03-29
Current registration	<b>RV59WPM</b>
Plate since	2024-03-29

More info >



**Finance check**

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled. If not, and you buy this NISSAN then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this NISSAN is financed.


<b>Finance company</b>	REDACTED
<b>Date of agreement</b>	REDACTED
<b>Agreement type</b>	REDACTED
<b>Agreement term</b>	REDACTED
<b>Agreement number</b>	REDACTED
<b>Contact info</b>	REDACTED

**More info** >



Mileage check

<b>Odometer</b>	In miles
<b>Mileage registrations</b>	17
<b>First mileage registration</b>	2009-09-08
<b>Last registration</b>	2023-11-01
<b>Complete history</b>	<a href="#">See info</a>



<b>Registration #1</b>	2009-09-08	7 mi
<b>Registration #2</b>	2012-08-17	17.064 mi
<b>Registration #3</b>	2013-08-13	20.678 mi
<b>Registration #4</b>	2014-08-11	24.321 mi
<b>Registration #5</b>	2015-02-26	26.979 mi
<b>Registration #6</b>	2016-02-25	29.711 mi
<b>Registration #7</b>	2017-02-22	35.822 mi
<b>Registration #8</b>	2017-02-22	35.822 mi
<b>Registration #9</b>	2018-02-06	39.335 mi
<b>Registration #10</b>	2019-05-29	45.277 mi
<b>Registration #11</b>	2020-05-29	51.219 mi
<b>Registration #12</b>	2021-05-29	57.161 mi
<b>Registration #13</b>	2022-05-29	63.103 mi
<b>Registration #14</b>	2023-05-29	69.045 mi
<b>Registration #15</b>	2023-05-29	69.045 mi
<b>Registration #16</b>	2023-05-29	69.045 mi
<b>Registration #17</b>	2023-11-01	75.000 mi

[More info >](#)



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1630 mm
Height	1470 mm
Length	3565 mm
Wheel base	2360 mm
Kerb weight	855 kg
Max. allowed weight	1250 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2
Engine number	107462