





report date: 2024-03-29

### General information

Make	FORD
Model	GALAXY
Colour	Silver
Year of manufacture	2014
Top speed	121 mph
0 - 100 km/h	10.2 seconds
Gearbox	6 speed manual

## Engine & fuel consumption

Power	103 kW / 140 HP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.997 сс
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	50.0 mpg
Consumption combined	44.4 mpg
CO2 emission	139 g/km
CO2 label	E



CarCheck.co.uk page 1/12



report date: 2024-03-29

## Internet history

### Entry 1

Date 2021-08-28

Pictures 21

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



EK64ENU report date: 2024-03-29

MOT history

MOT expiry date	2024-09-28
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	16
Total items failed	4

MOT #8		2023-09-22 09:21
MOT test	number	619804690793
Result		✓ Passed
Next exp	iry date	2024-09-28
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously we	eakened (1.1.14 (a) (ii))
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult be	lt
Advice	Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt	
Minor (i))	Offside Registration plate lamp inoperative in the case of multiple lamp	ps or light sources (4.7.1 (b)

MOT #7	2022-09-20 12:40	
MOT test number	382186072182	
Result	✓ Passed	
Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))		
Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt		
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult b	elt	

MOT #6	2021-09-08 16:16
MOT test number	985064515470
Result	✓ Passed

CarCheck.co.uk page 3/12



report date: 2024-03-29

**MOT #5** 2020-09-22 09:41

MOT test number 209494349367

**Result** ✓ Passed

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #4 2019-09-26 13:41

**MOT test number** 633002248392

Result \( \sqrt{Passed} \)

MOT #3 2019-09-23 10:27

MOT test number 496648844588

Result X Failed

**Fail** Nearside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

**Fail** Offside Front Inner Tyre has ply or cords exposed (5.2.3 (d) (ii))

**Fail** Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Advice Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #2 2018-09-04 09:34

MOT test number 917244448267

Result \( \sqrt{Passed} \)

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #1		2017-09-25 08:44
MOT test	number	954959256037
Result		✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Front and rear pads low	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	

CarCheck.co.uk page 5/12



report date: 2024-03-29

### Tax & MOT check





Expires: 28 September 2024

Tax status	Valid until 1 September
Days left	126
MOT expiry date	28 September 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	49
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

## Owner history

For how long did the current and previous owner(s) have this FORD? How many owners defined the premium report and see all owner registrations. Download the full report is	
THE STATE OF THE S	
***************************************	
***************************************	
***************************************	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	NK SIN
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2014-09-29
Last registration	2023-09-22
Complete history	See info



Registration #1	2014-09-29	14 mi
Registration #2	2017-09-25	33.237 mi
Registration #3	2018-09-04	38.389 mi
Registration #4	2019-09-23	46.906 mi
Registration #5	2019-09-26	46.983 mi
Registration #6		m.m-
Registration #6 Registration #7		11,777 ea
•		11,777 ea 11,777 ea
Registration #7		11,777 ea 11,777 ea 11,777 ea

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

### Car features

S0225	Air conditioning
S0295	
60482	
50501	
60566	
60567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1884 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Kerb weight	1590 kg

# Additional information

Fuel tank capacity	70 I
Number of axles	2
Engine number	EA09685

CarCheck.co.uk page 12/12