



report date: 2024-03-28

General information

Make	FORD
Model	FOCUS C-MAX GHIA TDCI
Colour	Blue
Year of manufacture	-
Top speed	124 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	136 BHP
Max. torque	320 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	48.7 mpg





LABEL UNKNOWN



Internet history

Entry 1

Date	2021-10-27
Pictures	60
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

<b>MOT #23</b>	2023-03-25 12:31
<b>MOT test number</b>	802611508373
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2024-03-24
<b>Advice</b>	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
<b>Advice</b>	Oil leak, but not excessive (8.4.1 (a) (i))
<b>Advice</b>	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

<b>MOT #22</b>	2023-03-18 11:33
<b>MOT test number</b>	117232213158
<b>Result</b>	✗ Failed
<b>DANGEROUS</b>	Central Rear Passenger's seat insecure (6.2.6 (a) (ii))
<b>Advice</b>	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
<b>MAJOR</b>	Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
<b>DANGEROUS</b>	Offside Rear Passenger's seat insecure (6.2.6 (a) (ii))
<b>Advice</b>	Oil leak, but not excessive (8.4.1 (a) (i))
<b>Advice</b>	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
<b>MAJOR</b>	Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

<b>MOT #21</b>	2022-03-24 15:42
<b>MOT test number</b>	354604541765
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Advice</b>	Exhaust mounting defective Exhaust tail pipe hanger (6.1.2 (a))
<b>Advice</b>	Front brake discs in slight poor condition on inner face
<b>Advice</b>	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #20**

2022-03-14 14:44

**MOT test number**

879888193717

**Result****✗ Failed**

- Advice** Front brake discs in slight poor condition on inner face
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Bonnet release in slight poor condition
- MAJOR** Nearside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Exhaust mounting defective Exhaust tail pipe hanger (6.1.2 (a))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Oil filler cap missing

**MOT #19**

2021-03-22 12:56

**MOT test number**

569390060646

**Result****✓ Passed**

- Advice** Offside Rear Coil spring corroded and both sides front (5.3.1 (b) (i))
- Advice** Both headlamp glasses going dull.
- Advice** Both rear shock absorber upper dust covers adrift from top mounts.
- Advice** Offside Rear Lower Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Both front suspension lower arm rear inner mount bushes perishing slightly.

**MOT #18**

2020-03-11 16:09

**MOT test number**

584923990038

**Result****✓ Passed**

**MOT #17** 2019-03-23 09:23**MOT test number** 233082925550**Result** ✓ Passed**Advice** Front Coil spring corroded both sides of vehicle (5.3.1 (b) (i))**Advice** Exhaust tail pipe nount hook fractured away from pipe.**MOT #16** 2019-03-18 16:43**MOT test number** 926692292016**Result** ✗ Failed**Advice** Front Coil spring corroded both sides of vehicle (5.3.1 (b) (i))**Advice** Exhaust tail pipe nount hook fractured away from pipe.**MAJOR** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Both headlamp glasses going dull and beams slightly out of focus.**MOT #15** 2018-03-12 11:24**MOT test number** 143824170961**Result** ✓ Passed**MOT #14** 2018-03-12 11:24**MOT test number** 640427928129**Result** ✗ Failed**Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)**MOT #13** 2017-03-21 17:24**MOT test number** 881999520102**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit on limits (4.1.E.1)

**MOT #12** 2016-03-07 12:45**MOT test number** 360141794168**Result** ✓ Passed**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)**Advice** Nearside Front Tyre worn close to the legal limit on legal limits (4.1.E.1)**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)**Advice** Offside Tyre worn close to the legal limit inside edge worn (4.1.E.1)**MOT #11** 2015-02-23 14:08**MOT test number** 167854355040**Result** ✓ Passed**MOT #10** 2015-02-23 14:08**MOT test number** 668144455041**Result** ✗ Failed**Pass with rectification** Offside Steering rack gaiter split (2.2.D.2d)**Pass with rectification** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Pass with rectification** Nearside Steering rack gaiter split (2.2.D.2d)**Pass with rectification** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #9** 2014-03-15 12:11**MOT test number** 585204674038**Result** ✓ Passed**MOT #8** 2013-03-22 14:47**MOT test number** 547241483006**Result** ✓ Passed

**MOT #7** 2013-03-22 14:47**MOT test number** 807451483015**Result** ✗ Failed**Pass with rectification** Registration plate lamp not working (1.1.C.1d)**MOT #6** 2012-03-09 14:38**MOT test number** 938719362099**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #5** 2011-03-01 17:05**MOT test number** 785620361006**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #4** 2010-03-02 10:32**MOT test number** 794101860057**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Rear seat belts not checked due to child seats fitted**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #3 2009-02-13 12:57

MOT test number 831454849097

Result ✓ Passed

**Notice** Offside and nearside rear tyres showing signs of wear and cracking around walls and tread.  
205/55/16

MOT #2 2008-02-25 12:01

MOT test number 134566758496

Result ✓ Passed

MOT #1 2007-02-28 11:59

MOT test number 983569757087

Result ✓ Passed

**Notice** Nearside front tyre on legal limit of 1.6mm

**Notice** Offside front tyre on legal limit of 1.6mm

**Notice** Rear tyres showing signs of cracking around tread and walls. 205/55/16





Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	EX04UHK
Plate since	2019-03-28
Current registration	EX04UHK
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2004-03-01
Last registration	2023-03-25
Complete history	<a href="#">See info</a>



Registration #1	2004-03-01	26 mi
Registration #2	2007-02-28	18.614 mi
Registration #3	2008-02-25	24.385 mi
Registration #4	2009-02-13	28.481 mi
Registration #5	2010-03-02	33.801 mi
Registration #6	2011-03-01	40.002 mi
Registration #7	2012-03-09	45.063 mi
Registration #8	2013-03-22	50.448 mi
Registration #9	2014-03-15	58.255 mi
Registration #10	2015-02-23	63.277 mi
Registration #11	2016-03-07	79.523 mi
Registration #12	2017-03-21	94.501 mi
Registration #13	2018-03-20	94.501 mi
Registration #14	2019-03-20	94.501 mi
Registration #15	2020-03-20	94.501 mi
Registration #16	2021-03-20	94.501 mi
Registration #17	2022-03-20	94.501 mi
Registration #18	2023-03-20	94.501 mi
Registration #19	2024-03-20	94.501 mi
Registration #20	2025-03-20	94.501 mi
Registration #21	2026-03-20	94.501 mi
Registration #22	2027-03-20	94.501 mi
Registration #23	2028-03-20	94.501 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1783 mm
Height	1558 mm
Length	4333 mm
Wheel base	2640 mm
Kerb weight	1523 kg

Additional information

Fuel tank capacity	53 l
Fuel delivery	Direct Injection
Number of doors	5
Number of axles	2
Engine number	4A71795