



TOYOTA



report date: 2024-03-28

General information

Make	TOYOTA
Model	COROLLA VERSO D-4D T3
Colour	Silver
Year of manufacture	2007
Top speed	122 mph
0 - 60 mph	9.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	310 Nm at 2.800 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.3 mpg
Consumption extra urban	53.3 mpg
Consumption combined	44.8 mpg
CO2 emission	167 g/km
CO2 label	H





Internet history

Entry 2


Date	2021-07-23
Pictures	25
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-07-22
Pictures	25
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2023-07-07
MOT pass rate	62 %
MOT passed	13
Failed MOT tests	8
Total advice items	29
Total items failed	11

MOT #21 2022-07-08 10:22

MOT test number 631322689929

Result ✓ Passed

Next expiry date 2023-07-07

Advice Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))

Advice Underbody has general corrosion

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))

MOT #20 2021-07-01 11:50

MOT test number 840912311115

Result ✓ Passed

Advice Brake pipe clips or supports missing, pipe adequately supported Front to Rear (1.1.11 (d) (i))

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Compression ignition. Manufacturer's plate obscured / illegible. Carried out test to pre 2008 turbo limit (3.0m-1) . Result = 1.15m-1

**MOT #19**

2021-06-24 16:54

MOT test number

910342840333

Result**✗ Failed****Fail** Nearside Side repeater not working (4.4.1 (a) (ii))**Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Compression ignition. Manufacturer's plate obscured / illegible. Carried out test to pre 2008 turbo limit . Result = 1.15m-1**Advice** Brake pipe clips or supports missing, pipe adequately supported Front to Rear (1.1.11 (d) (i))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #18**

2020-07-01 14:43

MOT test number

625052356381

Result**✓ Passed****MOT #17**

2020-07-01 14:43

MOT test number

543618605224

Result**✗ Failed****Pass with rectification** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #16**

2019-06-25 09:38

MOT test number

940004807925

Result**✓ Passed**

**MOT #15** 2019-06-25 09:38**MOT test number** 704873028894**Result** ✗ Failed**Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))**MOT #14** 2018-06-25 10:27**MOT test number** 177212874245**Result** ✓ Passed**MOT #13** 2017-06-27 08:09**MOT test number** 349464970686**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #12** 2016-06-20 13:53**MOT test number** 227595334536**Result** ✓ Passed**MOT #11** 2016-06-20 13:53**MOT test number** 448290008496**Result** ✗ Failed**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**MOT #10** 2015-06-18 12:59**MOT test number** 648869765120**Result** ✓ Passed

**MOT #9** 2015-06-18 10:11**MOT test number** 796369865164**Result** ✗ Failed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**MOT #8** 2014-06-12 09:53**MOT test number** 265383864155**Result** ✓ Passed**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**MOT #7** 2013-06-25 09:15**MOT test number** 158656173172**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Notice** Front to rear brake pipe clip fixing damaged / missing but brake pipe remains adequately supported.**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #6** 2013-06-25 09:15**MOT test number** 945876873168**Result** ✗ Failed**Notice** Front to rear brake pipe clip fixing damaged / missing but brake pipe remains adequately supported.**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Pass with rectification** Nearside Headlamp aim too high (1.8)**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)

**MOT #5** 2012-06-25 15:45**MOT test number** 496357372118**Result** ✓ Passed**Notice** One front to rear brake pipe clip missing; pipes still adequately supported.**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2011-06-24 16:14**MOT test number** 416655871133**Result** ✓ Passed**MOT #3** 2011-06-14 10:10**MOT test number** 325035261135**Result** ✗ Failed**Fail** Offside Inner Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)**Notice** Nail in nearside front tyre**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2010-06-24 13:31**MOT test number** 310145970183**Result** ✓ Passed**MOT #1** 2010-06-24 13:31**MOT test number** 153575570154**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too low (1.8)**Pass with rectification** Nearside Headlamp aim too low (1.8)



Tax & MOT check

✕
Untaxed

Tax expired:
15 March 2023

✕
MOT

Expired:
7 July 2023

Tax status	Expired at 15 March 2023
Days left	411 days too late
MOT expiry date	7 July 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2007-06-30
Last registration	2022-07-08
Complete history	See info



Registration #1	2007-06-30	27 mi
Registration #2	2010-06-24	29.260 mi
Registration #3	2011-06-14	38.754 mi
Registration #4	2011-06-24	39.039 mi
Registration #5	2012-06-25	48.626 mi
Registration #6	2013-06-25	57.326 mi
Registration #7	2014-06-12	65.899 mi
Registration #8	2015-06-18	74.843 mi
Registration #9	2015-06-18	74.843 mi
Registration #10	2016-06-20	82.323 mi
Registration #11	2016-06-20	82.323 mi
Registration #12	2016-06-20	82.323 mi
Registration #13	2016-06-20	82.323 mi
Registration #14	2016-06-20	82.323 mi
Registration #15	2016-06-20	82.323 mi
Registration #16	2016-06-20	82.323 mi
Registration #17	2016-06-20	82.323 mi
Registration #18	2016-06-20	82.323 mi
Registration #19	2016-06-20	82.323 mi
Registration #20	2016-06-20	82.323 mi
Registration #21	2016-06-20	82.323 mi
Registration #22	2016-06-20	82.323 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1660 mm
Length	4360 mm
Wheel base	2750 mm
Kerb weight	1495 kg
Max. allowed weight	2160 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	2AD521824