



L009NJK


report date: 2024-03-29

General information

Make	MAZDA
Model	6 D SPORT
Colour	Blue
Year of manufacture	2009
Top speed	135 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	185 BHP
Max. torque	400 Nm at 1.800 rpm
Engine capacity	2.184 cc
Cylinders	4
Fuel type	Diesel
Consumption city	39.8 mpg
Consumption extra urban	60.1 mpg
Consumption combined	50.4 mpg
CO2 emission	149 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-06-04
Pictures	1
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-11-24
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	37
Total items failed	19

MOT #17	2023-11-23 11:05
MOT test number	351696575515
Result	✓ Passed
Next expiry date	2024-11-24
Advice	Offside Front Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Rear Suspension arm corroded but not seriously weakened both side (5.3.3 (b) (i))
Advice	Rear Anti-roll bar linkage corroded but not seriously weakened both side (5.3.3 (b) (i))
Advice	Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
Advice	Rear Coil spring corroded both side (5.3.1 (b) (i))
Advice	Rear Suspension arm pin or bush worn but not resulting in excessive movement both side (5.3.4 (a) (i))

**MOT #16**

2022-11-25 15:41

MOT test number

759652098852

Result

✓ Passed

Advice Front Lower Suspension arm pin or bush worn but not resulting in excessive movement both side (5.3.4 (a) (i))

Advice Rear Upper Brake pipe corroded, covered in grease or other material both side (1.1.11 (c))

Advice Under the car corroded by black seal

Advice Offside Front Upper Oil leak, but not excessive (8.4.1 (a) (i))

Advice Front Upper Brake pipe corroded, covered in grease or other material both side (1.1.11 (c))

Advice Front Inner Tyre worn close to legal limit/worn on edge both side (5.2.3 (e))

MOT #15

2021-06-16 13:48

MOT test number

460815902753

Result

✓ Passed

Advice Underbody has surface corrosion all over

Advice Exhaust joints corroded

MOT #14

2020-07-07 14:03

MOT test number

842391625569

Result

✓ Passed

Advice Brake pipe corroded, covered in grease or other material front to rears (1.1.11 (c))

Advice All exhaust corroded

**MOT #13** 2020-07-07 09:46**MOT test number** 554558297127**Result** ✗ Failed**Advice** All exhaust corroded**Fail** Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Fail** Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Brake pipe corroded, covered in grease or other material front to rears (1.1.11 (c))**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**MOT #12** 2019-07-17 08:48**MOT test number** 749940518924**Result** ✓ Passed**MOT #11** 2019-07-17 08:48**MOT test number** 600550540605**Result** ✗ Failed**Pass with rectification** Offside Front Brake hose excessively deteriorated (1.1.12 (b) (ii))**MOT #10** 2018-07-05 12:44**MOT test number** 278122952280**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #9** 2018-07-05 10:02**MOT test number** 127452412206**Result** ✗ Failed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))**Minor** Tyre pressure monitoring system warning lamp indicates a fault (5.2.3 (h) (i))**Fail** Engine MIL inoperative or indicates a malfunction dpf lamp (8.2.2.2 (g))**Fail** Offside Front Wheel bearing rough when rotated (5.1.3 (b) (i))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Pass with rectification** Nearside Headlamp aim too high (4.1.2 (a))**MOT #8** 2017-06-29 10:56**MOT test number** 429525066609**Result** ✓ Passed**Advice** Front Brake pipe slightly corroded both at ends (3.6.B.2c)

**MOT #7**

2017-06-23 10:16

MOT test number

520956527405

Result**✗ Failed****Advice**

Front Brake pipe slightly corroded both at ends (3.6.B.2c)

Fail

Nearside Front position lamp(s) not working (1.1.A.3b)

Fail

Windscreen wiper does not clear the windscreen effectively both split (8.2.2)

Fail

Offside Front wheel bearing has excessive play (2.5.A.3c)

Fail

Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Fail

Nearside Registration plate lamp not working (1.1.C.1d)

Fail

Offside Front Anti-roll bar linkage missing (2.4.G.1)

Fail

Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #6

2016-06-30 11:27

MOT test number

165106490293

Result**✓ Passed****Advice**

DPF faulty light

MOT #5

2015-07-03 12:11

MOT test number

218704085188

Result**✓ Passed****Advice**

Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

**MOT #4**

2015-07-03 09:32

MOT test number

399324485115

Result**✗ Failed**

- Fail** Offside Inner Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Front brake application uneven (3.7.B.2)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #3

2014-07-18 10:27

MOT test number

889949294189

Result**✓ Passed**

- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Notice** Both rear tyres bald on inner edges and out of shape
- Advice** Inner Front Brake pad(s) wearing thin (3.5.1g)
- Notice** Front wipers smearing
- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)

MOT #2

2013-07-22 15:03

MOT test number

828133603279

Result**✓ Passed**

- Notice** DPF light on



MOT #1	2012-07-06 13:12
MOT test number	406868382184
Result	✓ Passed



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-07-22
Last registration	2023-11-23
Complete history	See info



Registration #1	2009-07-22	15 mi
Registration #2	2012-07-06	57.091 mi
Registration #3	2013-07-22	72.258 mi
Registration #4	2014-07-18	84.532 mi
Registration #5	2015-07-03	96.179 mi
Registration #6	2015-07-03	96.179 mi
Registration #7	2016-06-30	108.395 mi
Registration #8	2017-06-23	119.836 mi
Registration #9	2017-06-29	119.840 mi
Registration #10	2018-07-05	132.447 mi
Registration #11	2019-06-20	151.277 mi
Registration #12	2019-06-20	151.277 mi
Registration #13	2019-06-20	151.277 mi
Registration #14	2019-06-20	151.277 mi
Registration #15	2019-06-20	151.277 mi
Registration #16	2019-06-20	151.277 mi
Registration #17	2019-06-20	151.277 mi
Registration #18	2019-06-20	151.277 mi
Registration #19	2019-06-20	151.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	77%
Children	81%
Pedestrian	49%
Safety systems	71%
Overall rating	72%
Video	see crash video



Dimensions & weight

Width	1795 mm
Height	1440 mm
Length	4755 mm
Wheel base	2725 mm
Kerb weight	1560 kg
Max. allowed weight	2110 kg

Additional information

Fuel tank capacity	64 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	R2 10203473