





report date: 2024-03-28

General information

Make	MAZDA
Model	3 D TS2
Colour	Silver
Year of manufacture	2012
Top speed	115 mph
0 - 60 mph	11.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	72.4 mpg
Consumption combined	64.2 mpg
CO2 emission	117 g/km
CO2 label	С



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-02-01

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-01-14
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	11
Total items failed	11

MOT #11	2024-01-12 17:15
MOT test number	602514817857
Result	✓ Passed
Next expiry date	2025-01-14

MOT #10	2023-01-05 12:52
MOT test	number 534049314658
Result	✓ Passed
Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	

CarCheck.co.uk page 3/12



MOT #9 2023-01-04 11:19

MOT test number 862620266831

Result X Failed

Fail Nearside Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Brake fluid contaminated (1.8 (a))

Fail Parking brake lever defective so that it cannot be satisfactorily operated (1.1.6 (d))

Fail Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Fail Offside Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Offside Front Brakes imbalanced across an axle (1.2.1 (b) (i))

MOT #8 2022-01-13 11:34

MOT test number 343377464630

Result ✓ Passed

MOT #7 2021-01-15 17:12

MOT test number 436036820907

Result

✓ Passed

MOT #6 2021-01-14 16:08

MOT test number 587050923191

Result ★ Failed

Fail Windscreen washer provides insufficient washer liquid (3.5 (a))

Fail Nearside Parking brake inoperative on one side (1.4.1 (a))

Fail Reversing lamp inoperative (4.6.1 (a))

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

CarCheck.co.uk page 4/12



OY12ZCK

report date: 2024-03-28

MOT #5 2019-05-20 15:59

MOT test number 142435296075

Result
✓ Passed

MOT #4 2019-04-03 11:11

MOT test number 410258650928

Result × Failed

Advice Nearside Front Tyre slightly damaged/cracking or perishing slight damage to outer wall (5.2.3 (d)

(ii))

Minor Windscreen damaged but not adversely affecting driver's view zone b (3.2 (a) (i))

Fail Offside Rear Road wheel fixing missing 1 wheel nut missing (5.2.1 (a) (i))

MOT #3 2017-10-10 12:54

MOT test number 757997552729

Result ✓ Passed

MOT #2 2016-04-06 11:30

MOT test number 892178634660

Result

Passed

MOT #1 2015-05-01 13:38

MOT test number 999111525187

Result

Passed

Notice Wiper blades split but still clears screen

Notice Both front tyres wearing on inner edges

Notice Nearside mirror missing

Notice Offside rear tyre inner and outer edges worn

Notice Nearside front tyre has slight damage to sidewall

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 April
Days left	337
MOT expiry date	14 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



OY12ZCK

report date: 2024-03-28

Owner	history
OWNER	1113601 9

For how long did the current and previous owner(s) have this MAZDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full re	
THE STATE OF THE S	

THE PARTY OF THE P	

	More info >
Plate changes	
See in this check if this MAZDA had different number plates.	
Number of plates	
Correct registration	UK LINE
Plate since	
Current registration	NK NAME OF THE PARTY OF THE PAR
Plate since	
	More info >
·	

CarCheck.co.uk page 9/12



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2012-03-31
Last registration	2024-01-12
Complete history	See info



Registration #1	2012-03-31	23 mi
Registration #2	2015-05-01	28.279 mi
Registration #3	2016-04-06	39.460 mi
Registration #4	2017-10-10	53.965 mi
Registration #5	2019-04-03	69.147 mi
Registration #6	2019-05-20	70.757 mi
Registration #7	2021-01-14	79.243 mi
Registration #8		11.777 es
Registration #9		11.777 mi
Registration #10		11.777 es
Registration #11		11.177 mi
Registration #12		11.777 es
Registration #13		11.777 no

More info >

CarCheck.co.uk page 11/12



Safety ratings

NCAP rating	****
Adult	86%
Children	84%
Pedestrian	51%
Safety systems	71%
Overall rating	77%
Video	see crash video



Dimensions & weight

Width	2002 mm
Height	1470 mm
Length	4480 mm
Wheel base	2640 mm
Kerb weight	1323 kg
Max. allowed weight	1830 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	Y6 335588

CarCheck.co.uk page 12/12