



report date: 2024-03-28

## General information

Make	VOLVO
Model	V70 D3 R-DESIGN
Colour	Black
Year of manufacture	2011
Top speed	130 mph
0 - 60 mph	9.4 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	161 BHP
Max. torque	400 Nm at 1.400 rpm
Engine capacity	1.984 cc
Cylinders	5
Fuel type	Diesel
Consumption city	39.2 mpg
Consumption extra urban	61.4 mpg
Consumption combined	51.4 mpg
CO2 emission	144 g/km
CO2 label	F





Internet history

Entry 1

Date	2022-02-23
Pictures	0
Listing price	<a href="#">View report</a>

source: [autotrader.co.uk](#)



## MOT history

MOT expiry date	2025-04-05
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	14
Total items failed	11

MOT #16	2024-04-02 14:02
MOT test number	930206129435
Result	✓ Passed
Next expiry date	2025-04-05

MOT #15	2024-04-02 10:05
MOT test number	841564091985
Result	✗ Failed
Fail	Central Rear Exhaust system insecure (6.1.2 (a))
Fail	Nearside Front Headlamp aim projected beam image is obviously incorrect dip beam bulb (4.1.2 (c))

MOT #14	2023-04-04 08:49
MOT test number	125208731265
Result	✓ Passed

MOT #13	2022-04-06 14:41
MOT test number	137064816648
Result	✓ Passed

**MOT #12**

2021-03-23 17:52

**MOT test number**

690139188188

**Result**

✓ Passed

**Advice** Nearside Rear Other passenger door hinge deteriorated but the door can still be readily opened and closed Screws missing from door lock (6.2.3 (c) (i))

**Advice** Brake pipe corroded, covered in grease or other material All (1.1.11 (c))

**MOT #11**

2021-03-18 15:34

**MOT test number**

548590455779

**Result**

✗ Failed

**Fail** Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

**Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**Advice** Nearside Rear Other passenger door hinge deteriorated but the door can still be readily opened and closed Screws missing from door lock (6.2.3 (c) (i))

**Fail** Rear Registration plate insecure (0.1 (a))

**Advice** Brake pipe corroded, covered in grease or other material All (1.1.11 (c))

**MOT #10**

2020-03-13 15:00

**MOT test number**

544906805432

**Result**

✓ Passed

**MOT #9**

2020-03-06 11:59

**MOT test number**

728046619575

**Result**

✗ Failed

**Advice** Power steering close to minimum mark (2.1.5 (b) (i))

**Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

**MOT #8** 2019-03-13 11:58**MOT test number** 995666754744**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge ON LIMIT (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge ON LIMIT (5.2.3 (e))**MOT #7** 2018-03-27 16:47**MOT test number** 779725410334**Result** ✓ Passed**MOT #6** 2017-03-01 11:53**MOT test number** 319436411277**Result** ✓ Passed**MOT #5** 2017-02-21 15:56**MOT test number** 698011302134**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Front registration plate character(s) incorrectly spaced (6.3.4a)**Fail** Nearside Front Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Rear registration plate character(s) incorrectly spaced (6.3.4a)**MOT #4** 2016-03-07 15:57**MOT test number** 986853775792**Result** ✓ Passed

**MOT #3** 2016-03-07 14:41**MOT test number** 538551298284**Result** ✗ Failed**Fail** Rear registration plate character(s) incorrectly spaced (6.3.4a)**Fail** Front registration plate character(s) incorrectly spaced (6.3.4a)**MOT #2** 2015-03-25 14:59**MOT test number** 427464385072**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Under-trays fitted obscuring some underside components**Notice** Vehicle's internal headlight adjuster altered to recheck lights**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**MOT #1** 2014-03-20 13:17**MOT test number** 279579074059**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
5 April 2025

<b>Tax status</b>	Valid until 1 April
<b>Days left</b>	338
<b>MOT expiry date</b>	5 April 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	<b>MR55TAH</b>
Plate since	2019-03-28
Current registration	<b>MR55TAH</b>
Plate since	2019-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2011-03-31
Last registration	2024-04-02
Complete history	<a href="#">See info</a>



Registration #1	2011-03-31	19 mi
Registration #2	2014-03-20	21.390 mi
Registration #3	2015-03-25	29.326 mi
Registration #4	2016-03-07	33.942 mi
Registration #5	2016-03-07	33.949 mi
Registration #6	2017-02-21	38.345 mi
Registration #7	2017-03-01	38.469 mi
Registration #8	2018-03-27	42.761 mi
Registration #9	2019-03-13	47.383 mi
Registration #10	2019-03-20	51.377 mi
Registration #11	2019-03-20	51.377 mi
Registration #12	2019-03-20	51.377 mi
Registration #13	2019-03-20	51.377 mi
Registration #14	2019-03-20	51.377 mi
Registration #15	2019-03-20	51.377 mi
Registration #16	2019-03-20	51.377 mi
Registration #17	2019-03-20	51.377 mi
Registration #18	2019-03-20	51.377 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	88%
Children	84%
Pedestrian	43%
Safety systems	71%
Overall rating	77%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1861 mm
Height	1547 mm
Length	4823 mm
Wheel base	2816 mm
Kerb weight	1752 kg
Max. allowed weight	2300 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	846923