





General information

| Make | KIA |
|---------------------|----------------|
| Model | RIO 1 ISG |
| Colour | White |
| Year of manufacture | 2018 |
| Top speed | 107 mph |
| 0 - 60 mph | 12.5 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 83 BHP |
|-------------------------|---------------------|
| Max. torque | 122 Nm at 4.000 rpm |
| Engine capacity | 1.248 сс |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 43.5 mpg |
| Consumption extra urban | 57.6 mpg |
| Consumption combined | 46.3 mpg |
| CO2 emission | 125 g/km |
| CO2 label | D |








Internet history

| Entry 1 | |
|---------------|-------------|
| Date | 2021-09-21 |
| Pictures | 13 |
| Listing price | View report |









source: autotrader.co.uk



MOT history

| MOT expiry date | 2025-03-29 |
|--------------------|------------|
| MOT pass rate | 75 % |
| MOT passed | 3 |
| Failed MOT tests | 1 |
| Total advice items | 10 |
| Total items failed | 2 |

| MOT #4 | 2024-03-22 15:30 |
|--|------------------|
| MOT test number | 326090003395 |
| Result | ✓ Passed |
| Next expiry date | 2025-03-29 |
| Advice Nearside Play in steering rack inner joint(s) slight play | |

| MOT #3 | 2024-03-22 09:25 |
|---|------------------|
| MOT test number | 219674256293 |
| Result | 🗙 Failed |
| Fail Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) | |
| Advice Items removed from driver's view prior to test | |
| Advice TPMS warning lamp illuminated | |
| Advice Front Brake pad(s) wearing thin required soon (1.1.13 (a) (ii)) | |
| Advice Nearside Play in steering rack inner joint(s) slight play | |
| Fail Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) | |
| Advice Rear wiper blade torn | |





| MOT #2 | | 2023-03-30 15:10 |
|----------------------------|--|-----------------------------|
| MOT test | number | 402707843593 |
| Result | | ✓ Passed |
| Advice (d) (ii)) | Offside Front Tyre slightly damaged/cracking or perishing cracking in sh | oulder (18 dot code) (5.2.3 |
| Advice (d) (ii)) | Offside Rear Tyre slightly damaged/cracking or perishing cracking in sho | oulder (18 dot code) (5.2.3 |
| Advice (5.2.3 (d) (| Nearside Rear Tyre slightly damaged/cracking or perishing cracking in s | houlder (18 dot code) |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e) |)) |

| MOT #1 | 2021-09-11 08:44 |
|-----------------|------------------|
| MOT test number | 797946372219 |
| Result | ✓ Passed |



Tax & MOT check

| ✓ Taxed | ✓ MOT |
|--------------------------|---------------------------|
| Tax due: 1 April 2025 | Expires: 29 March 2025 |
| Tax status | Valid until 1 April |
| Days left | 336 |
| MOT expiry date | 29 March 2025 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|-------------------------------|------------|
| Band | G |
| First licence fee (12 months) | £ 210,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |





Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|-------------|
| Date | FE D |
| Category | L CENPE |
| Туре | K K |
| Damage 2 | AMPL |
| Date | |
| Category | AMPL |
| Туре | |

Extra KIA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10.200 |





Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| xxxxxxxx | |
|--|-------------|
| *********** | |
| ******** | |
| ****** | |
| *********** | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this KIA had different number plates. | |
| Number of plates | , |
| Current registration | |
| Plate since | |
| Current registration | |
| Plate since | |
| | |





Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.


| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |





Mileage check

| In miles |
|------------|
| 6 |
| 2018-09-17 |
| 2024-03-22 |
| See info |
| |



| Registration #1 | 2018-09-17 | 14 mi |
|-----------------|------------|------------|
| Registration #2 | 2021-09-11 | 8.937 mi |
| Registration #3 | | 11.117 esi |
| Registration #4 | | 11.117 esi |
| Registration #5 | | 11.777 esi |
| Registration #6 | | 11.777 esi |





Car features

| S0225 | Air conditioning |
|--------|------------------|
| S0295 | |
| S0482 | |
| \$0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 93% |
| Children | 84% |
| Pedestrian | 71% |
| Safety systems | 59% |
| Overall rating | 80% |
| Video | see crash video |



| Dimensions & weight | |
|-----------------------------------|-----------------------|
| Width | 1725 mm |
| Height | 1450 mm |
| Length | 4065 mm |
| Wheel base | 2580 mm |
| Kerb weight | 1110 kg |
| Max. allowed weight | 1560 kg |
| Additional information | |
| Fuel tank capacity | 45 |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 5 page 11/11 |

| Number of axles | 2 |
|-----------------|--------------|
| Engine number | G4LAJP087169 |