




report date: 2024-03-28

General information

Make	KIA
Model	SEDONA TS
Colour	Silver
Year of manufacture	2008
Top speed	122 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	182 BHP
Max. torque	343 Nm at 3.500 rpm
Engine capacity	2.902 cc
Cylinders	4
Fuel type	Diesel
Consumption city	27.7 mpg
Consumption extra urban	44.1 mpg
Consumption combined	36.2 mpg
CO2 emission	206 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-02-21
Pictures	48
Listing price	View report



source: yesauto.com

**MOT history**

MOT expiry date	2025-01-31
MOT pass rate	88 %
MOT passed	14
Failed MOT tests	2
Total advice items	25
Total items failed	3

MOT #16 2024-02-01 12:24**MOT test number** 948854730026**Result** Passed**Next expiry date** 2025-01-31**Advice** Offside Front Steering linkage ball joint has slight play rack end (2.1.3 (b) (i))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**MOT #15** 2023-02-10 11:19**MOT test number** 956768738407**Result** Passed**Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))**MOT #14** 2022-02-22 10:47**MOT test number** 258054005568**Result** Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #13** 2021-03-02 13:13**MOT test number** 420255407007**Result** Passed

**MOT #12** 2020-10-13 08:49**MOT test number** 870697983544**Result** ✓ Passed**Advice** Sill, engine and under covers fitted, partial examination only**MOT #11** 2020-10-13 05:53**MOT test number** 443043873400**Result** ✗ Failed**Advice** Sill, engine and under covers fitted, partial examination only**Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #10** 2019-04-16 11:26**MOT test number** 669929862272**Result** ✓ Passed**Advice** Sill, engine and under covers fitted, partial examination only**MOT #9** 2018-04-17 13:53**MOT test number** 925660659282**Result** ✓ Passed**MOT #8** 2017-09-21 09:56**MOT test number** 763843840896**Result** ✓ Passed**Advice** Passenger seat(s) missing at time of test

**MOT #7** 2016-09-22 14:50**MOT test number** 465081823966**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit bald on inner edge (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Parking brake lever has little reserve travel (3.1.6b)**MOT #6** 2015-09-25 13:09**MOT test number** 927419968355**Result** ✓ Passed**Advice** Nearside Front Anti-roll bar linkage ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)**Advice** Brake hydraulic reservoir fluid close to minimum level (3.6.G.1b)**MOT #5** 2014-09-29 10:03**MOT test number** 965792374288**Result** ✓ Passed**Notice** Both rear seats removed**MOT #4** 2013-09-17 10:16**MOT test number** 129880363237**Result** ✓ Passed**Notice** Passenger seat(s) missing at time of test**Advice** Nearside Front Anti-roll bar has slight play in a ball joint (2.4.G.2)

**MOT #3** 2012-09-24 10:40**MOT test number** 759858762292**Result** ✓ Passed**Notice** Both rear seats removed from vehicle**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #2** 2011-10-17 13:52**MOT test number** 885990991271**Result** ✓ Passed**Advice** Front registration plate delaminated but not likely to be misread (6.3.1d)**Notice** Both rear seats not fitted to rear of vehicle**Advice** Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #1** 2011-10-11 12:38**MOT test number** 367634781283**Result** ✗ Failed**Fail** Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**Advice** Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Notice** Both rear seats not fitted to rear of vehicle**Fail** Nearside Front Sub-frame rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Advice** Front registration plate delaminated but not likely to be misread (6.3.1d)



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
31 January 2025

Tax status	Valid until 1 March
Days left	307
MOT expiry date	31 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-




Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-12-30
Last registration	2024-02-01
Complete history	See info



Registration #1	2008-12-30	29 mi
Registration #2	2011-10-11	17.624 mi
Registration #3	2011-10-17	17.624 mi
Registration #4	2012-09-24	25.363 mi
Registration #5	2013-09-17	33.144 mi
Registration #6	2014-09-29	41.821 mi
Registration #7	2015-09-25	48.950 mi
Registration #8	2016-09-22	56.953 mi
Registration #9	2017-09-21	65.054 mi
Registration #10	2018-09-20	73.155 mi
Registration #11	2019-09-19	81.256 mi
Registration #12	2020-09-18	89.357 mi
Registration #13	2021-09-17	97.458 mi
Registration #14	2022-09-16	105.559 mi
Registration #15	2023-09-15	113.660 mi
Registration #16	2024-02-01	121.761 mi
Registration #17	2024-02-01	121.761 mi
Registration #18	2024-02-01	121.761 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1985 mm
Height	1815 mm
Length	4810 mm
Wheel base	2890 mm
Kerb weight	2168 kg
Max. allowed weight	2900 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	J3776349