





report date: 2024-03-28

General information

Make	CITROEN
Model	XSARA 16V EXCLUSIVE
Colour	Silver
Year of manufacture	2009
Top speed	115 mph
0 - 60 mph	11.5 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	107 BHP
Max. torque	147 Nm at 4.000 rpm
Engine capacity	1.587 сс
Cylinders	4
Fuel type	Petrol
Consumption city	28.0 mpg
Consumption extra urban	51.4 mpg
Consumption combined	39.2 mpg
CO2 emission	172 g/km
CO2 label	Н



CarCheck.co.uk page 1/13



EFO9NXP report date: 2024-03-28

Internet history


Entry 1

Date 2021-08-26

Pictures 8

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

Μ	OT	his	tory

MOT expiry date	2024-06-14
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	25
Total items failed	3

MOT #13	2023-06-06 12:52
MOT test number	273882805034
Result	✓ Passed
Next expiry date	2024-06-14

MOT #12		2022-05-28 11:12
MOT test	number	210351218155
Result		✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice (b))	Nearside Front Headlamp has a product on the lens but not seriously reduc	ing light output (4.1.4
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #11	2022-05-28 09:45
MOT test number	941775322567
Result	X Failed
Fail Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the (5.3.4 (b) (ii))	ne ingress of dirt
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Fail Nearside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents (5.3.4 (b) (ii))	the ingress of dirt
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #10		2021-05-17 13:10
MOT test	number	946855242229
Result		✓ Passed
Advice	N/s/f lower suspension arm rear bush splitting	
Advice	Front brake pads appear low	
Advice	N/s headlight lens tarnished output reduced	
Minor	Nearside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Both rear and o/s/f tyre starting to perish on treads	

MOT #9		2020-06-15 14:45
MOT test	number	537162551317
Result		✓ Passed
Advice	Antifreeze residue across the top of radiator.	
Advice	Unable to clearly view the front brake pads with wheels in place.	
Advice	Nearside headlamp lens deteriorated.	
Advice	Bonnet support rod, retaining clip broken.	

MOT #8	2019-06-13 11:21
MOT test number	627297181559
Result	✓ Passed
Advice Nearside headlamp lens weathered/ deteriorated	
Advice Windscreen washers weak in operation	

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT #7		2018-06-13 11:03
MOT test	number	483254237617
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside headlamp aim close to lower limit	

MOT #6		2018-06-13 11:03
MOT test	number	800748169304
Result		X Failed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))	
Advice	Offside headlamp aim close to lower limit	
Pass wit	h rectification Offside Stop lamp(s) not working (4.3.1 (a) (ii))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #5	2017-06-12 09:45
MOT test number	156515994779
Result	✓ Passed
MOT #4	2016-05-27 15:03
MOT test number	314992372008
Result	✓ Passed
MOT #3	2015-06-08 14:46
MOT test number	558069355158
Result	✓ Passed

CarCheck.co.uk page 5/13



EFO9NXP report date: 2024-03-28

MOT #2

MOT test number

657859764173

Result

Notice Child seat fitted not allowing full inspection of adult belt

 MOT #1
 2013-06-11 08:40

 MOT test number
 889872163174

 Result
 ✓ Passed

CarCheck.co.uk page 6/13



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 August
Days left	95
MOT expiry date	14 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

EF09NXP

report date: 2024-03-28

For how long did the current and previous owner(s) have this CITROEN? How many owners did have? Check it in the premium report and see all owner registrations. Download the full report		OEN

MARKET STATE OF THE STATE OF TH		

M	ore info	>

Plate changes

See in this check if this CITROEN had different number plates.

More info >

CarCheck.co.uk page 10/13



report date: 2024-03-28

Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2009-07-27
Last registration	2023-06-06
Complete history	See info



Registration #1	2009-07-27	19 mi
Registration #2	2013-06-11	7.382 mi
Registration #3	2014-06-18	13.520 mi
Registration #4	2015-06-08	19.250 mi
Registration #5	2016-05-27	26.811 mi
Registration #6	2017-06-12	32.868 mi
Registration #7	2018-06-13	43.297 mi
Registration #8	2018-06-13	43.297 mi
Registration #9		9.777 es
Registration #10		11.777 es
Registration #11		91.777 esi
Registration #12		11.777 es
Registration #13		91.777 esi
Registration #14		11.777 es

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-28

Safety ratings

NCAP rating	***
Adult	83%
Children	74%
Pedestrian	33%
Safety systems	40%
Overall rating	67%
Video	see crash video



Dimensions & weight

Width	1667 mm
Height	1612 mm
Length	3860 mm
Wheel base	2460 mm
Kerb weight	1133 kg
Max. allowed weight	1597 kg

Additional information

Fuel tank capacity	47 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	FX7S3417498

CarCheck.co.uk page 13/13