



TOYOTA

J7JDT

report date: 2024-03-29

General information

Make	TOYOTA
Model	MR2 T-BAR
Colour	White
Year of manufacture	1992
Top speed	136 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	158 BHP
Max. torque	191 Nm at 4.800 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Petrol



LABEL UNKNOWN



Internet history

Entry 2

Date	2022-09-18
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 1

Date	2022-07-08
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2023-08-14
MOT pass rate	64 %
MOT passed	7
Failed MOT tests	4
Total advice items	29
Total items failed	15

MOT #11	2022-08-15 10:31
MOT test number	539528070191
Result	✓ Passed
Next expiry date	2023-08-14

MOT #10	2011-10-07 13:26
MOT test number	979570481219
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Notice	Front and rear suspension corroded

**MOT #9** 2011-09-26 10:16**MOT test number** 579549561283**Result** ✗ Failed**Fail** Seat belt anchorage prescribed area is excessively corroded (5.2.6)**Notice** Front and rear suspension corroded**Fail** Offside Front An item not tested (Manual)**Fail** Headlamp aim too low (1.8)**Fail** Offside front brake binding (3.7.B.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**MOT #8** 2010-10-25 12:13**MOT test number** 302598790287**Result** ✓ Passed**Notice** Steering tie rods corroded**Advice** Front coil spring corroded (2.4.C.1b)**MOT #7** 2009-09-30 10:50**MOT test number** 734673279222**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear Sub-frame corroded but not seriously weakened (2.4.G.1)**Advice** Suspension arm corroded but not seriously weakened (2.4.G.1)

**MOT #6** 2009-09-28 12:25**MOT test number** 942671379206**Result** ✗ Failed**Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear Sub-frame corroded but not seriously weakened (2.4.G.1)**Fail** Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)**Fail** Offside Seat belt anchorage prescribed area is excessively corroded (5.2.6)**Fail** Nearside Rear wheel bearing rough when rotated (2.6.1)**Advice** Suspension arm corroded but not seriously weakened (2.4.G.1)**Fail** Exhaust emissions carbon monoxide content at idle excessive (7.3.D.4)**MOT #5** 2008-10-23 11:03**MOT test number** 672457698206**Result** ✓ Passed**Advice** Trailing arm corroded but not seriously weakened (2.4.G.1)**Notice** Both sides front stabilisers corroded**Advice** Coil spring corroded (2.4.C.1b)**Advice** Rear Sub-frame corroded but not seriously weakened (2.4.G.1)**Notice** Off side rear support bar broken**Advice** Offside Front Macpherson strut corroded but not seriously weakened (2.4.G.1)

**MOT #4** 2008-10-21 11:57**MOT test number** 112805698288**Result** ✗ Failed**Advice** Rear Sub-frame corroded but not seriously weakened (2.4.G.1)**Notice** Steering rack drum sticks corroded**Fail** Offside Headlamp aim not tested (1.8.A.1c)**Advice** Offside Front Macpherson strut corroded but not seriously weakened (2.4.G.1)**Advice** Trailing arm corroded but not seriously weakened (2.4.G.1)**Notice** Off side rear support bar broken**Notice** Both sides front stabilisers corroded**Fail** Exhaust emissions carbon monoxide content excessive (7.3.B.1a)**Advice** Coil spring corroded (2.4.C.1b)**MOT #3** 2007-10-11 15:04**MOT test number** 384094587284**Result** ✓ Passed**MOT #2** 2006-09-20 12:52**MOT test number** 774183966267**Result** ✓ Passed**Notice** Both front tyres worn on inner edge**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)



MOT #1 2006-09-20 12:52

MOT test number 724463966238

Result ✗ Failed

- Pass with rectification

Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Advice

Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Notice

Both front tyres worn on inner edge
- Pass with rectification

Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)



Tax & MOT check

✕  
Untaxed

Tax expired:  
1 November 2022

✕  
MOT

Expired:  
14 August 2023

Tax status	Expired at 1 November 2022
Days left	544 days too late
MOT expiry date	14 August 2023
Full MOT history	<a href="#">See MOT history</a>






Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	1992-01-24
Last registration	2022-08-15
Complete history	<a href="#">See info</a>



Registration #1	1992-01-24	6 mi
Registration #2	2006-09-20	82.026 mi
Registration #3	2007-10-11	82.751 mi
Registration #4	2008-10-21	83.616 mi
Registration #5	2008-10-23	83.621 mi
Registration #6	2009-09-28	84.447 mi
Registration #7	2009-09-30	84.447 mi
Registration #8	2010-09-28	85.277 mi
Registration #9	2010-09-28	85.277 mi
Registration #10	2010-09-28	85.277 mi
Registration #11	2010-09-28	85.277 mi
Registration #12	2010-09-28	85.277 mi
Registration #13	2010-09-28	85.277 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1700 mm
Height	1240 mm
Length	4180 mm

Additional information

Engine number	3S9157547
---------------	-----------