





report date: 2024-03-29

General information

| Make | MERCEDES |
|---------------------|--------------------------|
| Model | VITO 120 CDI COMPACT P/V |
| Colour | Black |
| Year of manufacture | 2008 |
| Top speed | 122 mph |
| 0 - 60 mph | 8.0 seconds |
| Gearbox | 5 speed automatic |

Engine & fuel consumption

| Power | 204 BHP |
|-----------------|---------------------|
| Max. torque | 440 Nm at 1.800 rpm |
| Engine capacity | 2.987 cc |
| Cylinders | 6 |
| Fuel type | Diesel |



CarCheck.co.uk page 1/14



Internet history

Entry 1

Date 2021-09-21

Pictures 14

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-29

| B 4 | \sim $-$ | | |
|-------|-------------|------|-------|
| 10.71 | $^{\prime}$ | hic | torv. |
| 101 | C I | 1115 | IUI V |
| | • | | tory |

| MOT expiry date | 2024-08-24 |
|--------------------|------------|
| MOT pass rate | 85 % |
| MOT passed | 11 |
| Failed MOT tests | 2 |
| Total advice items | 43 |
| Total items failed | 3 |

| MOT #13 | 2023-08-25 09:45 |
|------------------|------------------|
| MOT test number | 236543769193 |
| Result | ✓ Passed |
| Next expiry date | 2024-08-24 |

| MOT #12 | 2022-08-09 07:3 | 9 |
|----------|-------------------------------------------------------------------------------------------|------|
| MOT test | number 15991272735 | 1 |
| Result | ✓ Passe | ed : |
| Advice | Brake disc worn, pitted or scored, but not seriously weakened all discs (1.1.14 (a) (ii)) | |
| Advice | Rear Exhaust mounting defective silencer (6.1.2 (a)) | |

| MOT #11 | 2021-08-13 12:44 |
|-----------------|------------------|
| MOT test number | 450949846283 |
| Result | ✓ Passed |

| MOT #10 | 2020-03-05 10:27 |
|-----------------|------------------|
| MOT test number | 163373614844 |
| Result | ✓ Passed |

CarCheck.co.uk page 3/14



report date: 2024-03-29

MOT test number

Result

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #8 2018-02-01 10:48 **MOT** test number 331067461434 Result ✓ Passed **Advice** Pitting inner face offside front disc **Advice** Offside front tyre low inner edge Pitting inner face rear discs Advice Advice Front brake fluctuating, but not excessively both (3.7.B.3) Advice Wear front discs **Advice** Front brake application uneven, but not excessively Advice Offside reflector damaged

 MOT #7
 2016-11-16 14:25

 MOT test number
 537808300903

 Result
 ✓ Passed

MOT test number

Result

Fail Tyre tread depth below requirements of 1.6mm both rear (4.1.E.1)

Fail Exhaust system not adequately supported front bracket brocken (7.1.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 4/14



report date: 2024-03-29

MOT #5 2015-11-13 15:18 **MOT test number** 679609443547 Result ✓ Passed Advice Child seat fitted offside rear Pitting inner face offside front disc Advice Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1) Advice Nearside mirror glass damaged Advice Offside rear reflector damaged Advice Rear Tyre worn close to the legal limit both (4.1.E.1) Advice Pitting inner face rear discs

| MOT #4 | | 2015-1 | 1-13 15:18 |
|----------|---------------------|------------------------------------------------------------------------|-----------------|
| MOT test | number | | 776691887 |
| Result | | | x Failed |
| Advice | Rear Tyre worn c | lose to the legal limit both (4.1.E.1) | |
| Pass wit | h rectification | Windscreen wiper does not clear the windscreen effectively both (8.2.2 | .) |
| Advice | Child seat fitted o | offside rear | |
| Advice | Pitting inner face | offside front disc | |
| Advice | Nearside Front Ty | re worn close to the legal limit (4.1.E.1) | |
| Advice | Nearside mirror g | lass damaged | |
| Advice | Offside rear refle | ctor damaged | |
| Advice | Pitting inner face | rear discs | |

CarCheck.co.uk page 5/14



report date: 2024-03-29

| MOT #3 | | 2014-12-02 10:40 |
|----------|--------------------------------------------------------------|------------------|
| MOT test | number | 108936134375 |
| Result | | ✓ Passed |
| Notice | Offside reflector incomplete | |
| Notice | Emissions to low to register | |
| Advice | Rear front brake fluctuating, but not excessively (3.7.B.3) | |
| Notice | All discs worn and pitted | |
| Notice | Uneven wear nearside front tyre | |
| Advice | Front front brake fluctuating, but not excessively (3.7.B.3) | |
| Notice | Both rear tyres nearing limit | |

| MOT #2 | | 2013-11-14 17:06 |
|----------|-------------------------------------------------------------------------------|------------------|
| MOT test | number | 416818613358 |
| Result | | ✓ Passed |
| Advice | Offside Front brake disc worn, pitted or scored, but not seriously weakened (| (3.5.1i) |
| Notice | Vehicle's internal headlight adjuster altered to recheck lights | |
| Advice | Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3 | 3.5.1i) |
| Advice | Nearside Front brake disc worn, pitted or scored, but not seriously weakened | d (3.5.1i) |
| Advice | Nearside Rear brake disc worn, pitted or scored, but not seriously weakened | (3.5.1i) |
| Advice | Windscreen has damage to an area less than a 40mm circle outside zone 'A' | (8.3.1d) |

CarCheck.co.uk page 6/14



report date: 2024-03-29

MOT #1 2011-12-07 11:10

MOT test number 976131741313

Result ✓ Passed

Advice Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

Advice Exhaust has part of the system slightly deteriorated (7.1.1a)


Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Parking brake lever has little reserve travel (3.1.6b)

CarCheck.co.uk page 7/14



Tax & MOT check



Days left 186
MOT expiry date 24 August 2024

Full MOT history See MOT history

CarCheck.co.uk page 8/14



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date
Category


Type

Damage 2

Date

Category

Type



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-29

More info >

Owner history

| e met mistery | |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------|
| For how long did the current and previous owner(s) have this MERCEDES? How many ow MERCEDES have? Check it in the premium report and see all owner registrations. Downloaner. | |
| | |
| | |
| *************************************** | |
| | |
| | |
| | |
| | More info > |
| Plate changes | |
| See in this check if this MERCEDES had different number plates. | |
| Number of plates | , |
| Current registration | NK UK |
| Plate since | |
| Current registration | NK SIK |
| Plate since | |

CarCheck.co.uk page 11/14



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Courts at info | |

Contact info

More info >

CarCheck.co.uk page 12/14



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 15 |
| First mileage registration | 2008-10-27 |
| Last registration | 2023-08-25 |
| Complete history | See info |



| Registration #1 | 2008-10-27 | 22 mi |
|------------------|------------|-----------|
| Registration #2 | 2011-12-07 | 33.090 mi |
| Registration #3 | 2013-11-14 | 43.125 mi |
| Registration #4 | 2014-12-02 | 44.866 mi |
| Registration #5 | 2015-11-13 | 48.678 mi |
| Registration #6 | 2015-11-13 | 48.678 mi |
| Registration #7 | 2016-11-15 | 52.114 mi |
| Registration #8 | 2016-11-16 | 52.114 mi |
| Registration #9 | | 11.777 es |
| Registration #10 | | 11.777 es |
| Registration #11 | | 9.70 es |
| Registration #12 | | 11.777 es |
| Registration #13 | | 9.70 es |
| Registration #14 | | 11.777 es |
| Registration #15 | | 70.777 au |

More info >

CarCheck.co.uk page 13/14



Safety ratings

| NCAP rating | *** |
|-------------|-----------------|
| Video | see crash video |



Additional information

| - | |
|--------------------|------------------|
| Fuel tank capacity | 75 I |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 6 |
| Engine number | 64299040672309 |

CarCheck.co.uk page 14/14