



report date: 2024-03-28

General information

| | |
|---------------------|----------------------|
| Make | VOLVO |
| Model | XC60 D4 MOMENTUM AWD |
| Colour | Grey |
| Year of manufacture | 2018 |
| Top speed | 127 mph |
| 0 - 60 mph | 8.3 seconds |
| Gearbox | 8 speed automatic |

Engine & fuel consumption

| | |
|----------------------|---------------------|
| Power | 188 BHP |
| Max. torque | 400 Nm at 1.750 rpm |
| Engine capacity | 1.969 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption combined | 2.8 mpg |
| CO2 emission | 144 g/km |
| CO2 label | F |





Internet history

Entry 2


| | |
|---------------|-----------------------------|
| Date | 2022-04-22 |
| Pictures | 10 |
| Listing price | View report |



source: [autoonline.co.uk](#)

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2022-04-16 |
| Pictures | 12 |
| Listing price | View report |



source: [cargurus.co.uk](#)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2025-04-05 |
| MOT pass rate | 100 % |
| MOT passed | 4 |
| Failed MOT tests | 0 |
| Total advice items | 4 |
| Total items failed | 0 |

| | |
|------------------|---|
| MOT #4 | 2024-03-14 16:23 |
| MOT test number | 956447852406 |
| Result | ✓ Passed |
| Next expiry date | 2025-04-05 |
| Advice | Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) |
| Minor | Windscreen damaged but not adversely affecting driver's view causing wiper to slightly not clear screen (3.2 (a) (i)) |
| Advice | Front tyres worn on inner edges |

| | |
|-----------------|------------------|
| MOT #3 | 2023-03-31 07:50 |
| MOT test number | 223202993572 |
| Result | ✓ Passed |

| | |
|-----------------|------------------|
| MOT #2 | 2022-04-06 08:41 |
| MOT test number | 272788216681 |
| Result | ✓ Passed |

| | |
|-----------------|------------------------------------|
| MOT #1 | 2021-11-22 14:36 |
| MOT test number | 604289626179 |
| Result | ✓ Passed |
| Advice | Engine covers and undertray fitted |



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
5 April 2025

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 April |
| Days left | 336 |
| MOT expiry date | 5 April 2025 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|---|------------|
| Vehicle class | 49 |
| Band | H |
| First licence fee (12 months) | £ 255,00,- |
| First licence fee diesel non RDE2 tested (12 months) | £ 645,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,299 |
| Auction value | £ 19,299 |
| Average private trade value | £ 19,299 |

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |

More info >

Plate changes

See in this check if this VOLVO had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | ***** |
| Plate since | 2019-09-29 |
| Current registration | ***** |
| Plate since | 2019-09-29 |

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 7 |
| First mileage registration | 2018-12-15 |
| Last registration | 2024-03-14 |
| Complete history | See info |



| | | |
|-----------------|------------|-----------|
| Registration #1 | 2018-12-15 | 18 mi |
| Registration #2 | 2021-11-22 | 26.775 mi |
| Registration #3 | 2022-04-06 | 28.703 mi |
| Registration #4 | 2022-05-20 | 28.777 mi |
| Registration #5 | 2022-06-20 | 28.777 mi |
| Registration #6 | 2022-07-20 | 28.777 mi |
| Registration #7 | 2022-08-20 | 28.777 mi |

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 98% |
| Children | 87% |
| Pedestrian | 76% |
| Safety systems | 95% |
| Overall rating | 90% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1999 mm |
| Height | 1658 mm |
| Length | 4688 mm |
| Wheel base | 2865 mm |
| Kerb weight | 1837 kg |
| Max. allowed weight | 2450 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 60 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |

| | |
|------------------------|---------|
| Number of axles | 2 |
| Engine number | 2839783 |