



report date: 2024-03-29

General information

Make	VOLVO
Model	C30 D DRIVE SE LUX
Colour	Black
Year of manufacture	2011
Top speed	118 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	57.7 mpg
Consumption extra urban	83.1 mpg
Consumption combined	72.4 mpg
CO2 emission	99 g/km
CO2 label	A







Internet history

Entry 1

Date	2021-06-16
Pictures	9
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-12
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	57
Total items failed	12

MOT #15 2023-07-03 13:28

MOT test number 305360657320

Result ✓ Passed

Next expiry date 2024-07-12

Minor Windscreen wiper blade defective both smeary / advise replacement (3.4 (b) (i))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush / past service standards / advise repair (5.3.4 (a) (i))

Advice Various covers/trims/shields loose / damaged

Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords wearing inner edge (5.2.3 (d) (i))

Advice Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))

Advice Offside Rear tyre heavily worn on inner edge / devoid of tread / advise replacement

Advice Various covers fitted obscuring components



MOT #14

2022-07-04 16:00

MOT test number

191344674838

Result

✓ Passed

- Advice

Nearside steering rack /steering rack inner joint has play.
- Advice

Nearside side repeater damaged.
- Advice

Various covers/trim/shields loose.
- Advice

Various covers fitted obscuring components.
- Advice

Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush. (5.3.4 (a) (i))



MOT #13	2022-06-21 12:45
MOT test number	650924138383
Result	✗ Failed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge Worn close to legal limit. (5.2.3 (e))
- Fail** Nearside Rear Seat belt not functioning as intended (7.1.2 (c))
- Advice** Nearside side repeater damaged.
- Advice** Screw in offside rear tyre.
- Fail** Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Fail** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing Perished. (5.2.3 (d) (ii))
- Advice** Various covers/trimms/shields loose.
- Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Minor** Offside Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))
- Fail** Offside Front Wheel bearing rough when rotated (5.1.3 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge Inner and outer edges devoid of tread. (5.2.3 (e))
- Minor** Nearside Rear Tyre obviously under inflated (5.2.3 (l))
- Advice** Various covers fitted obscuring components.
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge Inner edge devoid of tread (5.2.3 (e))
- Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** Offside Rear brake disc corroded.
- Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge inner edge devoid of tread (5.2.3 (e))
- Minor** Nearside Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))
- Advice** Nearside steering rack /steering rack inner joint has play.
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush. (5.3.4 (a) (i))
- Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #12**

2021-07-13 09:34

MOT test number

990987561044

Result

✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Road wheel slightly distorted outer rim (5.2.2 (c) (i))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Seat belt slightly damaged (7.1.2 (b) (i))**MOT #11**

2021-07-12 11:49

MOT test number

679218426098

Result

✗ Failed

Fail Nearside Front Lower Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Front Road wheel slightly distorted outer rim (5.2.2 (c) (i))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Offside Rear Seat belt slightly damaged (7.1.2 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #10**

2020-08-05 14:55

MOT test number

584266093050

Result

✓ Passed

MOT #9

2020-08-05 08:58

MOT test number

611973473290

Result

✗ Failed

Fail Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #8**

2019-08-15 10:37

MOT test number

702825188933

Result

✓ Passed

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
Rear bush (5.3.4 (a) (i))

Advice Nearside Front Wheel rim slightly damaged

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
Rear bush (5.3.4 (a) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge Inner edge (5.2.3 (e))

Advice Offside Front Wheel has a welding repair on inner rim

MOT #7

2018-08-17 13:30

MOT test number

899002893787

Result

✓ Passed

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #6

2018-08-17 09:48

MOT test number

752507689625

Result

✗ Failed

Fail Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Fail Offside Front Position lamp not working (4.2.1 (a))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #5

2017-08-21 14:29

MOT test number

685060263804

Result

✓ Passed

**MOT #4** 2017-03-28 12:28**MOT test number** 411333186462**Result** ✓ Passed

- Advice** Nearside Rear Tyre worn close to the legal limit At the shoulders (4.1.E.1)
- Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Offside Front Tyre worn close to the legal limit At the shoulders (4.1.E.1)
- Advice** Offside Rear Tyre worn close to the legal limit At the shoulders (4.1.E.1)
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)
- Advice** Nearside Front Tyre worn close to the legal limit At the shoulders (4.1.E.1)

MOT #3 2016-03-16 14:56**MOT test number** 335282164312**Result** ✓ Passed

- Advice** Engine cover fitted
- Advice** Offside Rear Seat belt damaged but webbing not significantly weakened very slight damage (5.2.2a)
- Advice** Under tray fitted

MOT #2 2015-03-23 11:21**MOT test number** 155242285493**Result** ✓ Passed**MOT #1** 2014-04-08 15:26**MOT test number** 778608194093**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
12 July 2024

Tax status	Valid until 1 July
Days left	64
MOT expiry date	12 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	 
Plate since	2024-03-29
Current registration	 
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-04-13
Last registration	2023-07-03
Complete history	See info



Registration #1	2011-04-13	13 mi
Registration #2	2014-04-08	29.480 mi
Registration #3	2015-03-23	39.015 mi
Registration #4	2016-03-16	46.440 mi
Registration #5	2017-03-28	53.062 mi
Registration #6	2017-08-21	55.958 mi
Registration #7	2018-08-17	77.739 mi
Registration #8	2018-08-17	77.739 mi
Registration #9	2019-08-15	101.061 mi
Registration #10	2020-08-15	125.377 mi
Registration #11	2021-08-15	150.377 mi
Registration #12	2022-08-15	175.377 mi
Registration #13	2023-08-15	200.377 mi
Registration #14	2024-08-15	225.377 mi
Registration #15	2025-08-15	250.377 mi
Registration #16	2026-08-15	275.377 mi
Registration #17	2027-08-15	300.377 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1437 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1760212