



RENAULT

DG67MGY

report date: 2024-03-29

General information

Make	RENAULT
Model	ZOE DYNAMIQUE NAV
Colour	Grey
Year of manufacture	2017
Top speed	84 mph
0 - 60 mph	13.5 seconds
Gearbox	1 speed automatic

Engine & fuel consumption

Power	92 BHP
Max. torque	221 Nm at 2.500 rpm
Fuel type	Electricity



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-02-04
Pictures	10
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2025-04-19
MOT pass rate	63 %
MOT passed	5
Failed MOT tests	3
Total advice items	12
Total items failed	11

MOT #8	2024-03-27 16:58
MOT test number	310572366564
Result	✓ Passed
Next expiry date	2025-04-19
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #7	2024-03-26 14:28
MOT test number	170343580382
Result	✗ Failed
Fail	Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
Fail	Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
Fail	Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
Fail	Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**MOT #6**

2023-04-20 07:14

MOT test number

579137664873

Result

✓ Passed

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**MOT #5**

2023-04-05 08:46

MOT test number

758198695578

Result

✗ Failed

Fail Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**Fail** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**MOT #4**

2022-04-11 10:58

MOT test number

398463737075

Result

✓ Passed

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #3**

2022-04-09 10:24

MOT test number

396100927739

Result**✗ Failed****Fail**

Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice

Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice

Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Fail

Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #2

2021-04-14 13:26

MOT test number

474493527896

Result**✓ Passed****MOT #1**

2020-11-30 17:21

MOT test number

491947078878

Result**✓ Passed**



Tax & MOT check

✗
Untaxed

Tax expired:
27 April 2024

✓
MOT

Expires:
19 April 2025

Tax status

Expired at 27 April 2024

Days left

3 days too late

MOT expiry date

19 April 2025

Full MOT history

[See MOT history](#)



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2017-12-18
Last registration	2024-03-27
Complete history	See info



Registration #1	2017-12-18	18 mi
Registration #2	2020-11-30	11.785 mi
Registration #3		
Registration #4	2021-04-14	11.729 mi
Registration #5	2022-04-09	20.142 mi
Registration #6		
Registration #7		
Registration #8		
Registration #9		
Registration #10		

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	89%
Children	80%
Pedestrian	66%
Safety systems	85%
Overall rating	82%
Video	see crash video



Dimensions & weight

Width	1730 mm
Height	1562 mm
Length	4084 mm
Wheel base	2588 mm
Kerb weight	1480 kg
Max. allowed weight	1966 kg

Additional information

Fuel delivery	Not Applicable
Number of doors	5
Number of seats	5

Engine number C051420