





report date: 2024-03-29

#### General information

Make	RENAULT	
Model	GRAND SCENIC GR DYNAMIQUE TT BOSE PLUS ENERGY DCI S/S	
Colour	Black	
Year of manufacture	2014	
Top speed	112 mph	
0 - 100 km/h	12.8 seconds	
0 - 60 mph	13.5 seconds	
Gearbox	6 speed Manual	

### Engine & fuel consumption

Power	81 kW / 110 HP / 110 BHP
Max. torque	260 Nm at 1.750 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	62.8 mpg
Consumption extra urban	72.4 mpg
Consumption combined	68.9 mpg
CO2 emission	105 g/km
CO2 label	В



CarCheck.co.uk page 1/12



### Internet history

#### Entry 2

Date 2021-07-02

Pictures 24

Listing price <u>View report</u>









source: cargurus.co.uk

#### Entry 1

Date	2021-07-01
Pictures	20

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-07-11
MOT pass rate	64 %
MOT passed	7
Failed MOT tests	4
Total advice items	10
Total items failed	10

MOT #11		2023-06-13 15:22
MOT test	number	314394518385
Result		<b>✓</b> Passed
Next expi	ry date	2024-07-11
Advice Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))  Advice Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))		

MOT #10	2023-06-09 10:40	
MOT test number	519706888004	
Result	🗙 Failed	
Fail Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))		
Fail Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))		
Fail Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))		
Advice Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))		
Fail Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))		
Fail Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))		
Advice Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))		

CarCheck.co.uk page 3/12



DT14AUU

report date: 2024-03-29

MOT #9 2022-06-20 10:34

**MOT test number** 992564081927

**Result** ✓ Passed

Advice Offside Front Outer Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #8 2022-06-18 12:01

**MOT test number** 837799919938

**Result** X Failed

**Fail** Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Minor Front Windscreen wiper blade defective smearing screen slightly (3.4 (b) (i))

Fail Offside Rear Tyre not fitted in accordance with side wall instructions (5.2.3 (i))

**Advice** Offside Front Outer Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

MOT #7 2021-07-12 14:09

**MOT test number** 948738978636

Result 

Passed

MOT #6 2020-01-21 16:59

**MOT test number** 133777179939

**Result** ✓ Passed

MOT #5 2020-01-21 16:59

**MOT test number** 562403215743

**Result** X Failed

Pass with rectification Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

CarCheck.co.uk page 4/12



MOT #4

MOT test number

694859886210

Result

Advice Nearside Rear parking brake efficiency low

MOT #3

MOT test number

697971162374

Result

MOT #2

MOT test number

2018-01-24 09:42

MOT test number

210392224432

Result

Pass with rectification

Offside Rear Stop lamp not working (1.2.1b)

MOT #1

MOT test number

292894541662

Result

Advice Rear Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 5/12



### Tax & MOT check



Tax status	Valid until 1 July
Days left	62
MOT expiry date	11 July 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



### Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	
manage of the same	
***************************************	
**********	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 9/12



#### Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 10/12



### Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2014-07-31
Last registration	2023-06-13
Complete history	See info



Registration #1	2014-07-31	16 mi
Registration #2	2017-06-08	21.521 mi
Registration #3	2018-01-24	23.620 mi
Registration #4	2018-01-24	23.620 mi
Registration #5	2019-01-22	37.582 mi
Registration #6	2020-01-21	52.174 mi
Registration #7	2020-01-21	52.174 mi
Registration #8		71.777 es
Registration #9		71.777 es
Registration #10		77,777 44
Registration #11		11.117 es
Registration #12		11.177 es
Registration #13		11.777 es

mn.n.n

More info >

77.777 au

CarCheck.co.uk page 11/12



### Car features

S0225	Air conditionin
S0295	
50482	
60501	
60566	
60567	
50569	

### Safety ratings

NCAP rating	****
Adult	91%
Children	76%
Pedestrian	42%
Safety systems	99%
Overall rating	79%
Video	see crash video



## Dimensions & weight

Width	1845 mm
Height	1672 mm
Length	4573 mm
Wheel base	2770 mm
Kerb weight	1516 kg
Max. allowed weight	2200 kg

# Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 12/1

Number of axles 2

Engine number D228382