





report date: 2024-03-28

General information

Make	FIAT
Model	PANDA EASY
Colour	Grey
Year of manufacture	2017
Top speed	99 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	42.2 mpg
Consumption extra urban	65.7 mpg
Consumption combined	54.3 mpg
CO2 emission	119 g/km
CO2 label	С



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history

Entry 3

Date	2024-02-12
Pictures	0
Listing price	<u>View report</u>

source: carcraft.co.uk

Entry 2

y _	
Date	2023-12-06
Pictures	0
Listing price	View report

source: carcraft.co.uk

Entry 1

Date	2022-07-31	
Pictures	12	
Listing price	View report	









source: cargurus.co.uk

CarCheck.co.uk page 2/11



DP17FMZ report date: 2024-03-28

MOT history

MOT expiry date	2025-02-13
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	10
Total items failed	1

MOT #6		2024-02-14 09:37
MOT test	number	458473863282
Result		✓ Passed
Next expi	ry date	2025-02-13
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))	

MOT #5	2023-07-05 07:07
MOT test number	912863607765
Result	✓ Passed
MOT #4	2022-06-14 10:35
MOT test number	886617763497
Result	✓ Passed
Advice Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))	
Advice Offside Rear Brake cable damaged but not to excess (1.1.15 (a))	
Advice Nearside Rear Brake cable damaged but not to excess (1.1.15 (a))	

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT test number
983602048008

Result

Advice
Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))

Advice
Nearside Rear Brake cable damaged but not to excess (1.1.15 (a))

Fail
Offside Rear Shock absorbers has an excessively worn bush (5.3.2 (c))

Advice
Offside Rear Brake cable damaged but not to excess (1.1.15 (a))

MOT #2 2021-06-21 11:41 **MOT test number** 878724821166 Result ✓ Passed **MOT #1** 2020-06-22 11:15 110569328904 **MOT** test number Result ✓ Passed **Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 4/11



report date: 2024-03-28

Tax & MOT check





Expires: 13 February 2025

Tax status	Valid until 1 February
Days left	279
MOT expiry date	13 February 2025
Full MOT history	See MOT history

Tax calculation

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

Owner	history
-------	---------

For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report		•

manage of the same		

	More info	>
Plate changes		
See in this check if this FIAT had different number plates.		
Number of plates		
Current registration	UK UK	
Plate since		
Current registration	UK C	
Plate since		
	More info	>

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0111.5	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2017-06-30
Last registration	2024-02-14
Complete history	See info



Registration #1	2017-06-30	13 mi
Registration #2	2020-06-22	24.017 mi
Registration #3	2021-06-21	32.787 mi
Registration #4	2022-06-13	38.956 mi
Registration #5	2022-06-14	38.956 mi
Registration #6		71.777 es
Registration #6 Registration #7		11.777 es
		11.77 es 11.77 es
Registration #7		11.777 es 11.777 es 11.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	82%
Children	63%
Pedestrian	49%
Safety systems	43%
Overall rating	68%
Video	see crash video



Dimensions & weight

Width	1643 mm
Height	1551 mm
Length	3653 mm
Wheel base	2300 mm
Kerb weight	1015 kg
Max. allowed weight	1420 kg

Additional information

Fuel tank capacity	37 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	4 page 11/1:

Number of axles 2

Engine number 1874562