





report date: 2024-03-28

General information

Make	CITROEN
Model	DS3 DSTYLE PLUS
Colour	Red
Year of manufacture	2011
Top speed	118 mph
0 - 60 mph	9.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	160 Nm at 4.200 rpm
Engine capacity	1.598 сс
Cylinders	4
Fuel type	Petrol
Consumption city	29.1 mpg
Consumption extra urban	52.3 mpg
Consumption combined	40.4 mpg
CO2 emission	136 g/km
CO2 label	E



CarCheck.co.uk page 1/13



Internet history

Entry 1

Date 2021-01-21

Pictures 10

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/13



B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-11-10
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	15
Total items failed	10

MOT #14		2023-11-06 15:22
MOT test	number	907198890106
Result		✓ Passed
Next expi	ry date	2024-11-10
Advice	Nearside Front Coil spring corroded (5.3.1 (b) (i))	
Advice	Front Exhaust has a minor leak of exhaust gases back box (6.1.2 (a))	
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (i	ii))

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #13 2023-10-30 14:09 380424317794 **MOT** test number Result × Failed **Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i)) Fail Front Exhaust system insecure (6.1.2 (a)) Fail Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i)) Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Offside Front Direction indicator incorrect colour (4.4.3 (a)) Fail **Advice** Front Exhaust has a minor leak of exhaust gases back box (6.1.2 (a)) Fail Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii)) Fail Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i)) Nearside Front Direction indicator incorrect colour (4.4.3 (a)) Fail

MOT #12	2022-10-31 13:35
MOT test number	763254961588
Result	✓ Passed
MOT #11	2021-10-12 09:04
MOT test number	975277264001
Result	./ Passed

MOT #10	2020-11-11 12:22
MOT test number	920080927210
Result	✓ Passed
Advice Tyre slightly damaged/cracking or perishing o/s rear (5.2.3 (d) (ii) Advice Tyre slightly damaged/cracking or perishing n/s rear (5.2.3 (d) (ii)	

CarCheck.co.uk page 4/13



MOT #9 2019-11-07 12:22

MOT test number 484271742753

MOT #8 2019-09-07 09:35

MOT test number 312645816583

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #7 2018-09-17 15:35

MOT test number 499477629506

Result Passed

Advice Rear both tyres perished

MOT #6 2018-09-17 09:08

MOT test number 692744436760

Result X Failed

Advice Rear Service brake binding but not excessively both (1.2.1 (f))

Fail Rear Exhaust silencer insecure (8.1.1 (b) (i))

Advice Rear both tyres perished

MOT #5 2017-09-28 08:56

MOT test number 682680532130

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #4	2017-09-27 08:41
MOT test number	379830967781
Result	× Failed
Fail Exhaust system not adequately supported 3 hangers broken (7.1.1)	
Fail Windscreen wiper does not clear the windscreen effectively both (8.2.2)	
Fail Nearside Rear coil spring broken (2.4.C.1a)	

Neurside Neur Spring Broken (2.4.6.14)	
MOT #3	2016-09-26 15:54
MOT test number	956310539526
Result	✓ Passed
MOT #2	2015-09-30 16:13
MOT test number	641825151591
Result	✓ Passed
MOT #1	2014-09-03 15:52
MOT test number	566996344264
Result	✓ Passed

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 March
Days left	306
MOT expiry date	10 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history	
For how long did the current and previous owner(s) have this CITROEN? How many owner have? Check it in the premium report and see all owner registrations. Download the full	

	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	NK SIZ
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-28

Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >


CarCheck.co.uk page 11/13



Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-09-23
Last registration	2023-11-06
Complete history	See info



Registration #1	2011-09-23	27 mi
Registration #2	2014-09-03	16.755 mi
Registration #3	2015-09-30	20.202 mi
Registration #4	2016-09-26	24.237 mi
Registration #5	2017-09-27	27.609 mi
Registration #6	2017-09-28	27.609 mi
Registration #7	2018-09-17	31.366 mi
Registration #8	2018-09-17	31.366 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es

PRIN. PR. PR

More info >

71.777 mi

CarCheck.co.uk page 12/13



Safety ratings

NCAP rating	****
Adult	87%
Children	71%
Pedestrian	35%
Safety systems	83%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1715 mm
Height	1483 mm
Length	3948 mm
Wheel base	2464 mm
Kerb weight	1147 kg
Max. allowed weight	1554 kg

Additional information

Fuel tank capacity	48 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	FHCA1351172

CarCheck.co.uk page 13/13