



report date: 2024-03-28

General information

Make	VAUXHALL
Model	COMBO 1700 SE ECOFLEX
Colour	White
Year of manufacture	2011
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	46.3 mpg
Consumption extra urban	62.8 mpg
Consumption combined	55.4 mpg



LABEL UNKNOWN



MOT history

MOT expiry date	2025-01-28
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	26
Total items failed	10

MOT #18 2024-01-15 08:49

MOT test number 741558580498

Result ✓ Passed

Next expiry date 2025-01-28

- Advice** Rear exhaust box poor condition
- Advice** Nearside Play in steering rack inner joint(s)
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))
- Advice** Coolant leak
- Advice** Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge slight wear (5.2.3 (e))

MOT #17 2023-01-04 16:08

MOT test number 810164022699

Result ✓ Passed

- Advice** Front inner tyre wear
- Advice** Rear exhaust poor condition

**MOT #16**

2023-01-04 11:51

MOT test number

116128829219

Result

✗ Failed

Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Front inner tyre wear**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Rear exhaust poor condition**MOT #15**

2022-01-21 13:03

MOT test number

817855236775

Result

✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge inside edge wearing low (5.2.3 (e))**Advice** Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened inside face rusty and pitted (1.1.14 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge inside edge wearing low (5.2.3 (e))**MOT #14**

2022-01-20 10:04

MOT test number

831801005675

Result

✗ Failed

Advice Offside Front Tyre worn close to legal limit/worn on edge inside edge wearing low (5.2.3 (e))**Pass with rectification** Nearside Front Headlamp not working on dipped beam h7 bulb fitted (4.1.1 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge inside edge wearing low (5.2.3 (e))**Advice** Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened inside face rusty and pitted (1.1.14 (a) (ii))**Fail** Reversing lamp switch does not operate automatically when reverse gear is selected (4.6.3 (a))**Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))

**MOT #13** 2021-01-29 15:51**MOT test number** 404746728996**Result** ✓ Passed**Advice** Nearside Front Play in steering rack inner joint(s)**MOT #12** 2020-08-03 12:04**MOT test number** 484466787853**Result** ✓ Passed**MOT #11** 2019-08-20 15:42**MOT test number** 512007645903**Result** ✓ Passed**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Nearside Front Brake pad(s) wearing thin Both (1.1.13 (a) (ii))**MOT #10** 2018-08-30 15:35**MOT test number** 769455982476**Result** ✓ Passed**MOT #9** 2017-09-12 15:18**MOT test number** 190882843768**Result** ✓ Passed**MOT #8** 2017-09-12 12:46**MOT test number** 402219029092**Result** ✗ Failed**Fail** Nearside Rear coil spring broken (2.4.C.1a)**Fail** Offside Front Upper Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)**Fail** Offside Rear coil spring broken (2.4.C.1a)

**MOT #7** 2016-09-09 13:14**MOT test number** 533767674620**Result** ✓ Passed**MOT #6** 2015-09-08 12:57**MOT test number** 288088244099**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #5** 2015-09-08 12:57**MOT test number** 292622244337**Result** ✗ Failed**Pass with rectification** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #4** 2014-09-17 08:52**MOT test number** 307310064486**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #3** 2014-09-15 14:12**MOT test number** 676968854249**Result** ✗ Failed**Fail** Nearside Direction indicators not working (1.4.A.2c)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Nearside Hazard warning lamps inoperative (1.4.B.1b)



MOT #2	2014-04-07 10:01
MOT test number	485237994043
Result	✓ Passed
<div>Notice Front brake disc`s worn and lippted</div>	

MOT #1	2014-02-20 17:45
MOT test number	705881554009
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
28 January 2025

Tax status	Valid until 1 February
-------------------	------------------------

Days left	279
------------------	-----

MOT expiry date	28 January 2025
------------------------	-----------------

Full MOT history	See MOT history
-------------------------	---------------------------------



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	DU11SVO
Plate since	2019-09-29
Current registration	DU11SVO
Plate since	2019-09-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2011-03-23
Last registration	2024-01-15
Complete history	See info



Registration #1	2011-03-23	6 mi
Registration #2	2014-02-20	95.909 mi
Registration #3	2014-04-07	95.926 mi
Registration #4	2014-09-15	98.853 mi
Registration #5	2014-09-17	98.867 mi
Registration #6	2015-09-08	104.267 mi
Registration #7	2015-09-08	104.267 mi
Registration #8	2016-09-09	111.006 mi
Registration #9	2017-09-12	117.218 mi
Registration #10	2017-09-12	117.218 mi
Registration #11	2018-09-12	123.430 mi
Registration #12	2018-09-12	123.430 mi
Registration #13	2019-09-12	129.642 mi
Registration #14	2019-09-12	129.642 mi
Registration #15	2020-09-12	135.854 mi
Registration #16	2020-09-12	135.854 mi
Registration #17	2021-09-12	142.066 mi
Registration #18	2021-09-12	142.066 mi
Registration #19	2024-01-15	148.278 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Additional information

Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	4297596