



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	CADDY C20 TDI HIGHLINE BLUEMOTION TECHNOLOGY
Colour	Blue
Year of manufacture	2016
Top speed	106 mph
0 - 100 km/h	13.3 seconds
0 - 60 mph	12.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 kW / 102 HP / 101 BHP
Max. torque	250 Nm at 2.500 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.1 mpg
Consumption extra urban	58.9 mpg
Consumption combined	54.3 mpg
CO2 emission	123 g/km
CO2 label	D





## Internet history

### Entry 1

Date	2022-04-28
Pictures	7
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

**MOT history**

<b>MOT expiry date</b>	2023-10-26
<b>MOT pass rate</b>	57 %
<b>MOT passed</b>	4
<b>Failed MOT tests</b>	3
<b>Total advice items</b>	12
<b>Total items failed</b>	6

<b>MOT #7</b>	2022-10-27 11:51
<b>MOT test number</b>	930623750593
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2023-10-26

<b>MOT #6</b>	2022-10-26 10:08
<b>MOT test number</b>	229803081382
<b>Result</b>	✗ Failed
<b>Fail</b>	Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
<b>Fail</b>	Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

<b>MOT #5</b>	2021-07-07 12:08
<b>MOT test number</b>	383564516456
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))
<b>Advice</b>	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #4** 2020-08-17 16:12**MOT test number** 147663770650**Result** ✓ Passed**Advice** Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))**Advice** Offside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #3** 2020-08-14 10:53**MOT test number** 912745956390**Result** ✗ Failed**Fail** Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))**Advice** Offside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Fail** Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))**MOT #2** 2019-09-11 16:26**MOT test number** 382708361558**Result** ✓ Passed**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))



MOT #12019-09-11 12:41

MOT test number739528037080

Result

Failed

Advice

Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail

Nearside Windscreen washer provides insufficient washer liquid (3.5 (a))

Advice

Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail

Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

Advice

Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))



Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 May 2024

✗  
**MOT**  
  
Expired:  
26 October 2023

Tax status	Valid until 1 May
Days left	1
MOT expiry date	26 October 2023
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2016-10-12
Last registration	2022-10-27
Complete history	<a href="#">See info</a>



Registration #1	2016-10-12	13 mi
Registration #2	2019-09-11	44.683 mi
Registration #3	2019-09-11	44.683 mi
Registration #4	2020-08-14	54.996 mi
Registration #5	2020-08-17	54.997 mi
Registration #6	2022-10-27	55.277 mi
Registration #7	2022-10-27	55.277 mi
Registration #8	2022-10-27	55.277 mi
Registration #9	2022-10-27	55.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	78%
Pedestrian	58%
Safety systems	68%
Overall rating	74%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2062 mm
Height	1836 mm
Length	4876 mm
Wheel base	3 mm
Kerb weight	1594 kg
Max. allowed weight	2299 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	2
Number of axles	2
Engine number	DFSD084278