




report date: 2024-03-29

General information

| | |
|---------------------|-------------------------|
| Make | VAUXHALL |
| Model | GRANDLAND SPORT NAV S/S |
| Colour | Grey |
| Year of manufacture | 2018 |
| Top speed | 121 mph |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 128 BHP |
| Max. torque | 300 Nm at 1.750 rpm |
| Engine capacity | 1.499 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 60.1 mpg |
| Consumption extra urban | 72.4 mpg |
| Consumption combined | 56.5 mpg |
| CO2 emission | 110 g/km |
| CO2 label | B |








Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-10-14 |
| Pictures | 12 |
| Listing price | View report |



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

| | |
|---------------------------|------------|
| MOT expiry date | 2024-09-02 |
| MOT pass rate | 100 % |
| MOT passed | 3 |
| Failed MOT tests | 0 |
| Total advice items | 9 |
| Total items failed | 0 |

MOT #3 2023-08-31 14:51**MOT test number** 404943878685**Result** Passed**Next expiry date** 2024-09-02

Minor Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated leaking grease slightly (6.1.7 (g) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #2 2022-08-19 12:58**MOT test number** 924541291094**Result** Passed

Advice Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))

Advice Offside Front Outer CV boot leaking grease.

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt



| | |
|-----------------|--|
| MOT #1 | 2021-08-31 08:37 |
| MOT test number | 297466489791 |
| Result | ✓ Passed |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Advice | Nearside Front Nail in tyre |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
2 September 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 April |
| Days left | 336 |
| MOT expiry date | 2 September 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|---|------------|
| Vehicle class | 49 |
| Band | F |
| First licence fee (12 months) | £ 185,00,- |
| First licence fee diesel non RDE2 tested (12 months) | £ 210,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | ***** |
| Plate since | 2019-06-29 |
| Current registration | ***** |
| Plate since | 2019-06-29 |

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

| | | |
|-------------------|----------|------|
| Finance company | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type | XXXXXXXX | XXXX |
| Agreement term | XXXXXXXX | XXXX |
| Agreement number | XXXXXXXX | XXXX |
| Contact info | XXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 5 |
| First mileage registration | 2018-09-03 |
| Last registration | 2023-08-31 |
| Complete history | See info |



| | | |
|-----------------|------------|-----------|
| Registration #1 | 2018-09-03 | 21 mi |
| Registration #2 | 2021-08-31 | 67.484 mi |
| Registration #3 | 2023-08-31 | 67.484 mi |
| Registration #4 | 2023-08-31 | 67.484 mi |
| Registration #5 | 2023-08-31 | 67.484 mi |

More info >



Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 84% |
| Children | 87% |
| Pedestrian | 63% |
| Safety systems | 60% |
| Overall rating | 76% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1856 mm |
| Height | 1609 mm |
| Length | 4477 mm |
| Wheel base | 2675 mm |
| Kerb weight | 1392 kg |
| Max. allowed weight | 2000 kg |

Additional information

| | |
|-----------------|-------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | 10Q3BB0184037 LQP |