



report date: 2024-03-29

General information

Make	NISSAN
Model	ALMERA S
Colour	Silver
Year of manufacture	-
Top speed	108 mph
0 - 60 mph	13.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	121 BHP
Max. torque	128 Nm at 2.800 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	51.4 mpg
Consumption combined	42.8 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-10-01
Pictures	0
Listing price	View report

source: autotrader.co.uk

**MOT history****MOT #21** 2022-01-10 11:53**MOT test number** 715219320321**Result** ✗ Failed

- Fail** Offside Headlamp aim too low (4.1.2 (a))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Fail** Power steering pump leaking (2.1.5 (a))
- Advice** Exhaust damaged and knocking against body
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #20 2021-01-05 16:33**MOT test number** 897693489447**Result** ✓ Passed**MOT #19** 2020-01-08 15:36**MOT test number** 302208125010**Result** ✓ Passed**MOT #18** 2020-01-08 12:07**MOT test number** 191284330467**Result** ✗ Failed

- Fail** Emissions oxygen sensor obviously defective (8.2.1.1 (a))
- Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
- Fail** Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Fail** Service brake efficiency below requirements (1.2.2 (a) (i))
- Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

**MOT #17** 2019-01-09 12:48**MOT test number** 547679901499**Result** ✓ Passed**MOT #16** 2018-01-10 12:51**MOT test number** 500394636105**Result** ✓ Passed**MOT #15** 2018-01-10 12:51**MOT test number** 413257136734**Result** ✗ Failed**Pass with rectification** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Pass with rectification** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #14** 2017-01-09 14:17**MOT test number** 581061500914**Result** ✓ Passed**MOT #13** 2017-01-09 14:17**MOT test number** 677297115007**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)**MOT #12** 2016-01-08 13:34**MOT test number** 367693787442**Result** ✓ Passed**MOT #11** 2015-01-06 09:47**MOT test number** 397666705047**Result** ✓ Passed

**MOT #10** 2014-01-04 16:04**MOT test number** 297704904011**Result** ✓ Passed**MOT #9** 2013-01-04 15:54**MOT test number** 946354203079**Result** ✓ Passed**MOT #8** 2012-01-06 17:44**MOT test number** 106716002472**Result** ✓ Passed**MOT #7** 2010-08-04 12:09**MOT test number** 841976010264**Result** ✓ Passed**MOT #6** 2009-07-28 09:47**MOT test number** 201679909290**Result** ✓ Passed**MOT #5** 2008-08-01 10:13**MOT test number** 614594718212**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2008-08-01 10:13**MOT test number** 533154618226**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Offside Rear Stop lamp not working (1.2.1b)



MOT #3	2007-08-02 11:28
MOT test number	941734817208
Result	✓ Passed

MOT #2	2007-08-02 11:28
MOT test number	333464317499
Result	✗ Failed
Pass with rectification	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Pass with rectification	Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
Pass with rectification	Nearside Front Front position lamp(s) not working (1.1.A.3b)

MOT #1	2006-07-15 11:16
MOT test number	110826696184
Result	✓ Passed



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2003-03-29
Last registration	2022-01-10
Complete history	See info



Registration #1	2003-03-29	14 mi
Registration #2	2006-07-15	20.055 mi
Registration #3	2007-08-02	25.726 mi
Registration #4	2008-08-01	31.073 mi
Registration #5	2009-07-28	38.070 mi
Registration #6	2010-08-04	44.783 mi
Registration #7	2012-01-06	52.174 mi
Registration #8	2013-01-04	54.049 mi
Registration #9	2014-01-04	58.896 mi
Registration #10	2015-01-06	63.607 mi
Registration #11	2016-01-08	68.461 mi
Registration #12	2016-01-08	75.000 mi
Registration #13	2016-01-08	75.000 mi
Registration #14	2016-01-08	75.000 mi
Registration #15	2016-01-08	75.000 mi
Registration #16	2016-01-08	75.000 mi
Registration #17	2016-01-08	75.000 mi
Registration #18	2016-01-08	75.000 mi
Registration #19	2016-01-08	75.000 mi
Registration #20	2016-01-08	75.000 mi
Registration #21	2016-01-08	75.000 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1706 mm
Height	1448 mm
Length	4184 mm
Wheel base	2535 mm
Kerb weight	1170 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number	197826