



report date: 2024-03-29

General information

| | |
|---------------------|-------------------|
| Make | BMW |
| Model | X3 XDRIVE20D SE |
| Colour | White |
| Year of manufacture | 2013 |
| Top speed | 130 mph |
| 0 - 60 mph | 8.5 seconds |
| Gearbox | 8 speed automatic |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 181 BHP |
| Max. torque | 380 Nm at 1.750 rpm |
| Engine capacity | 1.995 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 46.3 mpg |
| Consumption extra urban | 53.3 mpg |
| Consumption combined | 50.4 mpg |
| CO2 emission | 147 g/km |
| CO2 label | F |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-06-11 |
| Pictures | 1 |
| Listing price | View report |



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-05-11 |
| MOT pass rate | 75 % |
| MOT passed | 9 |
| Failed MOT tests | 3 |
| Total advice items | 12 |
| Total items failed | 3 |

| | |
|------------------|---|
| MOT #12 | 2023-05-10 09:02 |
| MOT test number | 372798715326 |
| Result | ✓ Passed |
| Next expiry date | 2024-05-11 |
| Advice | Rear Brake pad(s) wearing thin on limit (1.1.13 (a) (ii)) |
| Advice | Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) |

| | |
|-----------------|--|
| MOT #11 | 2022-05-03 12:05 |
| MOT test number | 367207304145 |
| Result | ✓ Passed |
| Minor | Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) |
| Advice | Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Advice | Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |

| | |
|-----------------|------------------|
| MOT #10 | 2021-05-12 13:22 |
| MOT test number | 250428300404 |
| Result | ✓ Passed |

**MOT #9** 2021-03-19 13:22**MOT test number** 795034696841**Result** ✓ Passed**Advice** Movement in offside front inner rack joint**MOT #8** 2020-02-26 14:15**MOT test number** 277144556717**Result** ✓ Passed**Advice** Movement in offside front inner rack joint**MOT #7** 2020-02-26 14:15**MOT test number** 590227374533**Result** ✗ Failed**Pass with rectification** Nearside Front Headlamp light intensity severely reduced (4.1.4 (a))**Advice** Movement in offside front inner rack joint**MOT #6** 2019-03-25 14:39**MOT test number** 324654110653**Result** ✓ Passed**Advice** Plastic shields and covers fitted unable to fully inspect.**MOT #5** 2018-03-22 16:56**MOT test number** 102854726067**Result** ✓ Passed

**MOT #4** 2018-03-22 11:03**MOT test number** 468828788928**Result** ✗ Failed**Advice** Offside Rear Tyre bald on inner edge**Fail** Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)**MOT #3** 2017-03-23 12:16**MOT test number** 746394204580**Result** ✓ Passed**MOT #2** 2017-03-23 12:16**MOT test number** 817960654659**Result** ✗ Failed**Pass with rectification** Nearside Front Headlamp aim beam image obviously incorrect refitted bulb, set aim up (1.8.A.1b)**MOT #1** 2016-03-24 12:46**MOT test number** 149480725091**Result** ✓ Passed**Advice** Nearside front tyre has a cut on outer sidewall and wearing on outer edge**Advice** Offside front wheel has slight play from inner tie rod arm



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
11 May 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 August |
| Days left | 93 |
| MOT expiry date | 11 May 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 49 |
| Band | F |
| Single payment (12 months) | £ 200,00,- |
| Single six month payment | £ 110,00,- |
| Total payable by 12 monthly instalments | £ 210,00,- |



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|------------|
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |

More info >

Plate changes

See in this check if this BMW had different number plates.

| | |
|----------------------|----------------|
| Number of plates | 1 |
| Current registration | LT13KXP |
| Plate since | 2019-09-29 |
| Current registration | LT13KXP |
| Plate since | 2019-09-29 |

More info >



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this BMW is financed.

| | | |
|-------------------|----------|------|
| Finance company | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type | XXXXXXXX | XXXX |
| Agreement term | XXXXXXXX | XXXX |
| Agreement number | XXXXXXXX | XXXX |
| Contact info | XXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 14 |
| First mileage registration | 2013-03-25 |
| Last registration | 2023-05-10 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2013-03-25 | 6 mi |
| Registration #2 | 2016-03-24 | 30.385 mi |
| Registration #3 | 2017-03-23 | 37.332 mi |
| Registration #4 | 2017-03-23 | 37.332 mi |
| Registration #5 | 2018-03-22 | 47.747 mi |
| Registration #6 | 2018-03-22 | 47.767 mi |
| Registration #7 | 2019-03-25 | 56.982 mi |
| Registration #8 | 2019-03-25 | 56.982 mi |
| Registration #9 | 2019-03-25 | 56.982 mi |
| Registration #10 | 2019-03-25 | 56.982 mi |
| Registration #11 | 2019-03-25 | 56.982 mi |
| Registration #12 | 2019-03-25 | 56.982 mi |
| Registration #13 | 2019-03-25 | 56.982 mi |
| Registration #14 | 2019-03-25 | 56.982 mi |

More info >



Car features

The BMW factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete BMW factory list for this vehicle [here](#).

More info >

Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 88% |
| Children | 83% |
| Pedestrian | 53% |
| Safety systems | 71% |
| Overall rating | 78% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1881 mm |
| Height | 1675 mm |
| Length | 4648 mm |
| Wheel base | 2810 mm |
| Kerb weight | 1725 kg |
| Max. allowed weight | 2315 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 67 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |

| | |
|------------------------|----------|
| Number of axles | 2 |
| Engine number | 73778329 |