



Mercedes-Benz

FI9PGA

report date: 2024-03-28

General information

Make	MERCEDES-BENZ
Model	VITO 116 CDI DUALINER
Colour	Grey
Year of manufacture	2011
Gearbox	6 speed Manual

Engine & fuel consumption

Power	163 BHP
Max. torque	360 Nm at 1.600 rpm
Engine capacity	2.143 cc
Cylinders	4
Fuel type	Diesel
Consumption city	30.4 mpg
Consumption extra urban	43.5 mpg
Consumption combined	37.7 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-20
Pictures	18
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-05-02
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	37
Total items failed	0

MOT #13	2024-04-22 15:27
MOT test number	195620365911
Result	✓ Passed
Next expiry date	2025-05-02
Minor	Offside Obligatory mirror slightly loose (3.3 (b) (i))
Advice	Nearside Front Outer Brake pad(s) wearing thin (1.1.13 (a) (ii))
Minor	Nearside Obligatory mirror slightly loose (3.3 (b) (i))

MOT #12	2024-04-15 09:00
MOT test number	647144587091
Result	✗ Failed
Minor	Nearside Obligatory mirror slightly loose (3.3 (b) (i))
MAJOR	Parking brake efficiency below requirements (1.4.2 (a) (i))
Advice	Nearside Front Outer Brake pad(s) wearing thin (1.1.13 (a) (ii))
Minor	Offside Obligatory mirror slightly loose (3.3 (b) (i))
MAJOR	Nearside Rear Parking brake inoperative on one side (1.4.1 (a))

**MOT #11** 2023-05-03 10:20**MOT test number** 483741907726**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #10** 2022-04-11 11:39**MOT test number** 920661327419**Result** ✓ Passed**MOT #9** 2021-02-02 10:35**MOT test number** 225310869239**Result** ✓ Passed**MOT #8** 2020-02-04 15:35**MOT test number** 504893988020**Result** ✓ Passed**Minor** Nearside Obligatory mirror slightly loose (3.3 (b) (i))**Advice** Offside Front Tyre wearing on outer edge**Minor** Offside Obligatory mirror slightly loose (3.3 (b) (i))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Nearside Front Tyre wearing on outer edge

**MOT #7**

2020-02-04 11:26

MOT test number

961152539113

Result**✗ Failed****Minor**

Nearside Obligatory mirror slightly loose (3.3 (b) (i))

Advice

Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice

Offside Front Tyre wearing on outer edge

Minor

Offside Obligatory mirror slightly loose (3.3 (b) (i))

DANGEROUS

Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

Advice

Nearside Front Tyre wearing on outer edge

MOT #6

2019-02-05 11:17

MOT test number

755656280855

Result**✓ Passed****Advice**

Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

AdviceNearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement
Front bush (5.3.4 (a) (i))**Advice**

Rear Suspension component pin or bush slightly worn Differential bushes (5.3.4 (a) (i))

AdviceOffside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement
Front bush (5.3.4 (a) (i))

**MOT #5** 2019-01-29 14:37**MOT test number** 831897041650**Result** ✗ Failed**MAJOR** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Rear Suspension component pin or bush slightly worn Differential bushes (5.3.4 (a) (i))**Advice** Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement
Front bush (5.3.4 (a) (i))**MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))**MAJOR** Offside Rear Parking brake inoperative on one side (1.4.1 (a))**Minor** Offside Obligatory mirror slightly damaged (3.3 (b) (i))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement
Front bush (5.3.4 (a) (i))**MAJOR** Nearside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**MOT #4** 2018-01-19 09:49**MOT test number** 273820306506**Result** ✓ Passed**Advice** Offside Front Sub-frame rubber bush deteriorated but not resulting in excessive movement
differential bush (2.4.G.2)**Advice** E c u engine light on**Advice** Nearside Sub-frame rubber bush deteriorated but not resulting in excessive movement differential
bush (2.4.G.2)**MOT #3** 2017-01-27 16:01**MOT test number** 360347175967**Result** ✓ Passed



MOT #2	2015-10-28 11:42
MOT test number	132792321901
Result	✓ Passed

MOT #1	2014-11-20 11:55
MOT test number	369974124391
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 July 2024

✓
MOT

Expires:
2 May 2025

Tax status		Valid until 1 July
Days left		63
MOT expiry date		2 May 2025
Full MOT history		See MOT history



Damage history


Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How many owners did this MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From
Owner	From
Owner	From
Owner	From
Owner	From
Owner	From

More info >

Plate changes

See in this check if this MERCEDES-BENZ had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2019-01-01
Current registration	 XXXXXX
Plate since	2019-01-01

More info >



Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES-BENZ is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-11-23
Last registration	2024-04-22
Complete history	See info



Registration #1	2011-11-23	12 mi
Registration #2	2014-11-20	101.550 mi
Registration #3	2015-10-28	129.187 mi
Registration #4	2017-01-27	163.805 mi
Registration #5	2018-01-19	193.919 mi
Registration #6	2019-01-29	223.207 mi
Registration #7	2019-02-05	223.212 mi
Registration #8	2020-02-04	251.492 mi
Registration #9	2020-05-20	251.557 mi
Registration #10	2020-05-20	251.557 mi
Registration #11	2020-05-20	251.557 mi
Registration #12	2020-05-20	251.557 mi
Registration #13	2020-05-20	251.557 mi
Registration #14	2020-05-20	251.557 mi
Registration #15	2020-05-20	251.557 mi

More info >



Car features

The MERCEDES-BENZ factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MERCEDES-BENZ factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Additional information

Fuel tank capacity	75 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	6
Engine number	65194030552142