





report date: 2024-03-29

## General information

Make	FIAT
Model	500C POP
Colour	Pink
Year of manufacture	2016
Top speed	99 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 6.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	65.7 mpg
Consumption combined	60.1 mpg
CO2 emission	110 g/km
CO2 label	В



CarCheck.co.uk page 1/11



report date: 2024-03-29

## Internet history

## Entry 3

Date 2024-02-05

Pictures 0

Listing price <u>View report</u>

#### source: carcraft.co.uk

#### Entry 2

Date 2024-01-12

Pictures 12

Listing price <u>View report</u>










### source: cargurus.co.uk


#### Entry 1

Date 2021-12-22

Pictures 37

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/11



report date: 2024-03-29

MOT	history
1.101	iliocol y

MOT expiry date	2025-02-11
MOT pass rate	86 %
MOT passed	6
Failed MOT tests	1
Total advice items	6
Total items failed	2

MOT #7	2024-02-12 15:25
MOT test number	912959092914
Result	<b>✓</b> Passed
Next expiry date	2025-02-11

MOT #6	2023-01-18 09:55
MOT test number	155140736703
Result	✓ Passed
Advice Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))	

MOT #5	2022-03-21 15:18
MOT test number	481912968499
Result	<b>✓</b> Passed
MOT #4	2021-11-29 11:04
MOT test number	432444717776
- ·	4 D d
Result	✓ Passed

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #3 2021-11-29 10:33

**MOT test number** 779554564431

Result X Failed

Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))

Fail Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #2 2020-09-23 16:01

MOT test number 258383884210

Result \( \sqrt{Passed} \)

**Advice** Nearside Rear Nail in tyre

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

MOT #1 2019-05-22 15:58

**MOT test number** 759699112065

CarCheck.co.uk page 4/11



report date: 2024-03-29

## Tax & MOT check





Tax statusValid until 1 FebruaryDays left278

MOT expiry date 11 February 2025

Full MOT history See MOT history

## Tax calculation

Vehicle class	48
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

## Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

## Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

Owner	history
OWITEL	HISLULY

For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report I	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Current registration	NK NK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

## Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2016-06-30
Last registration	2024-02-12
Complete history	See info



Registration #1	2016-06-30	18 mi
Registration #2	2019-05-22	15.582 mi
Registration #3	2020-09-23	28.011 mi
Registration #4	2021-11-29	34.017 mi
Registration #5	2021-11-29	34.017 mi
Registration #6		0.00 44
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		0.00 44
Registration #11		10.777 esc

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

## Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1627 mm
Height	1488 mm
Length	3546 mm
Wheel base	2300 mm
Kerb weight	865 kg
Max. allowed weight	1345 kg

# Additional information

Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles CarCheck.co.uk	2 page 11/11